



# BIG SEWICKLEY CREEK WATERSHED ASSESSMENT, RESTORATION, & PROTECTION PLAN



OCTOBER 2010

***Prepared for:***

Big Sewickley Creek Watershed Association  
2615 Warrendale Bayne Road  
Baden, PA 15005



***Prepared by:***



PITTSBURGH OFFICE  
P.O. Box 763  
Greensburg, PA 15601



***Funded by:***



BIG SEWICKLEY CREEK WATERSHED ASSOCIATION

BIG SEWICKLEY CREEK  
WATERSHED ASSESSMENT, RESTORATION, AND PROTECTION PLAN

**Table Of Contents**

**Narrative**

1.0	Introduction.....	1
2.0	Watershed Background.....	1
	2.1 Watershed Description	
	2.2 Topography	
	2.3 Bedrock	
	2.4 Hydrology	
	2.5 Stream Health	
	2.6 Economic Influence	
	2.7 Important Watershed Features	
3.0	Municipal Information .....	6
4.0	Fish And Macroinvertebrate Surveys .....	11
5.0	Water Quality .....	13
6.0	Watershed Issues.....	14
7.0	Big Sewickley Creek Segment Analyses.....	15
8.0	East Branch Big Sewickley Creek Segment Analyses .....	60
9.0	North Fork Big Sewickley Creek Segment Analyses .....	70
10.0	Cooney Hollow Segment Analyses .....	85
11.0	Rippling Run Segment Analyses .....	87
12.0	Conclusions And Management Recommendations.....	91
13.0	Acknowledgements.....	93

**Attachments**

- A Management Recommendations For The Watershed
- B Field Assessment Waypoint Data
- C Macroinvertebrate And Fish Survey
- D Biological Sampling
- E Visual Assessment Field Sheet
- F GIS Map References Summary
- G Media: News Reports/Articles On BSCWA

## **Figures (GIS Maps)**

- 1 Stream Assessment Scoring
- 2 Areas Of Encroachment & Bank Erosion
- 3 Stormwater Management & Land Use
- 4 Biological Surveys & Sampling
- 5 Oil And Gas Wells
- 6 Natural Areas
- 7 Watershed Management Recommendations

BIG SEWICKLEY CREEK WATERSHED ASSOCIATION  
BIG SEWICKLEY CREEK  
WATERSHED ASSESSMENT, RESTORATION & PROTECTION PLAN

**1.0 INTRODUCTION**

In March of 2006 the Big Sewickley Creek Watershed Association (BSCWA) applied for a Growing Greener grant from the PA Department of Environmental Protection (PaDEP) to conduct a watershed assessment of the Big Sewickley Creek Watershed. In November of 2006, the group was awarded a grant for \$58,537. The BSCWA chose to have the Allegheny County Conservation District (ACCD) serve as the sponsor to administer this grant. In June of 2007 the ACCD contracted with Blazosky Associates, Inc. (BAI) to conduct the assessment and complete the restoration and protection plan.

Over the next 12 months (June 5, 2007 to May 13, 2008), BAI conducted visual assessments of the watershed, walking many streams and their tributaries in the watershed to identify impacts and potential project sites. In addition, macroinvertebrate studies were conducted at nine (9) sites, fish surveys at three (3) sites, and sampling for fecal coliform at twenty-five (25) locations across the watershed (between June 12, 2008 and July 25, 2008) (with additional fecal re-sampling on January 6, 2009 of six (6) sites). Field pH and conductivities were taken at the confluence of most tributaries encountered, as well as other general stream check points. This data is provided within this report and its appendices.

During the visual assessments, BAI scored stream segments using a modified version of the United States Department of Agriculture (USDA) protocol for visual stream assessments (see Attachment E). Stream reaches were scored based on criteria such as: channel condition, stream embeddedness, canopy cover, AMD (if applicable), riparian zone, bank stability, in-stream fish and macroinvertebrate cover, and water appearance. Photos were taken of non-point source pollution impacts as well as areas that had a positive impact on water quality or potential for watershed management options. A global positioning system (GPS) hand-held unit and topographic maps were utilized to field locate areas that had an issue that would be depicted in the final plan report.

Finally, the GPS points were incorporated into an excel spreadsheet which was then used to create data layers for maps that were developed in a Geographic Information System (GIS). The GIS maps included in this report depict many features of the watershed and include the waypoints, scoring, and other information that was taken in the field along with land use information provided from other sources.

**2.0 WATERSHED BACKGROUND**

A watershed is defined by the United States Environmental Protection Agency (EPA) as the area of land where all of the water that is under it or drains off of it goes into the same place.

**2.1 WATERSHED DESCRIPTION**

Encompassing approximately 46 square miles, the watershed extends from the southwestern tip of Cranberry Township, southwest toward the northeastern tips of Leetsdale and Ambridge at the Ohio River. The watershed consists of ten boroughs and townships in three counties, including: Marshall Township, Franklin Park Borough, Bell



Acres Borough, Leet Township, and Leetsdale Borough in Allegheny County; New Sewickley Township, Economy Borough, Harmony Township, and Ambridge Borough in Beaver County; and Cranberry Township in Butler County (- with a very small portion of the watershed in the Borough of Bradford Woods, which is to the east of Marshall Township). Economy Borough and Marshall Township make up the largest land area in the watershed. The watershed is comprised of one main watershed, Big Sewickley Creek, and four smaller subsheds, North Fork Big Sewickley Creek, East Branch Big Sewickley, Cooney Hollow, and Rippling Run.

The main stem of Big Sewickley Creek extends from the headwaters in Marshall to the mouth between Leetsdale and Ambridge. Flowing through 8 municipalities, the Creek creates the border between these municipalities - Economy, Harmony, and Ambridge to the north and Franklin Park, Bell Acres, Leet, and Leetsdale to the south.

The East Branch extends from the headwaters in Marshall, just east of I-79, to the confluence with Big Sewickley Creek in Franklin Park, near the intersection of the 3 municipalities of Franklin Park, Economy, and Marshall. It only flows in these 2 municipalities.

Rippling Run, a tributary to the East Branch, flows solely through Franklin Park. The North Fork extends from headwaters in Economy (tip is in Marshall) to the confluence with Big Sewickley Creek in Economy at the Economy/Bell Acres border. Cooney Hollow flows solely through Economy. The mouth of Cooney Hollow is approximately one half mile east of the North Fork's mouth.

## **2.2 TOPOGRAPHY**

Located within the Pittsburgh Low Plateau Section, topography within the watershed consists of smooth to irregular, undulating, topographic land surfaces with narrow and relatively shallow valleys. Topographic relief is low to moderate ranging from over 1200 feet above mean sea level (msl) in the highlands of the watershed to approximately 720 feet msl at the confluence with the Ohio River. The drainage pattern is dendritic. Forces that have shaped topography within this watershed are largely from fluvial erosion and periglacial mass wasting (Pennsylvania Geological Survey, 2000).

## **2.3 BEDROCK**

The subsurface geology of the watershed is comprised of Pennsylvania age sedimentary rocks predominantly shale and siltstone, but also containing sandstone. Specifically, the Glenshaw (Pcg) Formation underlies much of the valley floor while the Casselman (Pcc) form the uplands.

## **2.4 HYDROLOGY**

A United States Geological Survey (USGS) gauging station exists on the Big Sewickly just east of the borough of Ambridge and records flow draining from the upper 15.6 square miles of the watershed. Based on a 10 year dataset (1968 – 1978) the Big Sewickly had a median discharge of 7.6 cubic feet per second. The  $Q_{7-10}$  (the 7 day, 10 year low flow) was 0.09 cubic feet per second. Base flow (as a percentage of annual recharge) appears to be low with variations over the 10 year period between 4.2 to 13.4

percent. Since there are few withdrawals within the watershed, low base flow conditions may be due to a low groundwater storativity of the fractured bedrock aquifer.

## 2.5 STREAM HEALTH

Big Sewickley Creek and the North Fork of Big Sewickley Creek are designated by PA Code Chapter 93 as Trout Stocked Fisheries (TSF). The streams are designated as "attaining" their designated use for aquatic health. Based on PADEP eFACTS (<http://www.ahs2.dep.state.pa.us/eFactsWeb/default.aspx>, accessed October 15, 2010), there are no "non-attaining" designations for the Big Sewickley.

The PA Fish and Boat Commission (PFBC) classifies streams that are stocked with trout as Approved Trout Waters (ATW). PFBC has guidelines including water quality for ATW waters. For example, (1) for new waters added to the stocked trout program, water temperatures shall not exceed 24C at any time prior to June 1. (2) The pH at the time of stocking shall not be less than 6.0 for brook trout and brown trout, and not less than 6.5 for rainbow trout. (3) No stream section shall be stocked if pollutants are known to be present at concentrations equal to or greater than the PA Department of Health action limits, or, in the case of a bioaccumulative substance, in a concentration which is harmful to humans (G. Smith, PFBC, October 2010).

## 2.6 ECONOMIC INFLUENCE

The BSCW is comprised of diverse industrial and economic areas. Historically, steel towns were located near the Ohio River (concentrated in Ambridge and Leetsdale), and oil production occurred in Economy Borough and parts of Marshall Township. Historically, oil and gas wells have been concentrated in Economy. Most of the active wells left to date are in Economy, Marshall Township, and Franklin Park. Oil and gas well activity in the watershed is depicted on Figure 6.

Current areas of economic activity include industrial facilities near the Ohio River (Leetsdale Industrial Park, Buncher Commerce Park, Port Ambridge Industrial Park), and commercial/retail (Thorn Hill Industrial Park) located near Marshall/Cranberry Township near I-79. Other growth has occurred in the form of suburban housing developments throughout the upper sections of the watershed.

## 2.7 IMPORTANT WATERSHED FEATURES

### ***National Heritage Inventory***

*([http://www.naturalheritage.state.pa.us/CNAI\\_Download.aspx](http://www.naturalheritage.state.pa.us/CNAI_Download.aspx))*

The BSCW is identified as an exceptional area of great importance for biological diversity and ecological integrity through the 1994 Natural Heritage Inventory (NHI) of Allegheny County. The Allegheny County NHI identifies and maps Allegheny County's most significant natural areas. The study investigated plant and animal species and communities that are unique or uncommon in Allegheny County; it also explored areas important for general wildlife habitat, education and scientific study.

Designated as the *Big and Little Sewickley Creek Landscape Conservation Area* (LCA), the area is the largest tract of relatively contiguous, undeveloped "green space" in the county, and an area that contains a large Biological Diversity Area, four managed lands, and encompasses a watershed of a High Quality stream. According to the study,

an LCA is defined as a large contiguous area that is important because of its size, open space and habitats, and although including a variety of land uses, has not been heavily disturbed and thus retains much of its natural character. Sites of exceptional county significance merit quick, strong and complete protection.

In addition, the *Cooney Hollow Biological Diversity Area* (BDA) is identified in the 1993 Beaver County NHI. Although small in size, this site is noted as both a high diversity area and a community/ecosystem conservation area. The area is a quality example of a mature Mesic Central Forest community.

### ***State Game Lands***

The watershed also contains the State Game Lands 203, a 1,247 acre managed land. State Game Lands 203 is a largely forested land with patches of cleared land in the form of food plots, clearcuts, and reverting forest, all of which is managed for wildlife. This property, which is owned and managed by the Pennsylvania Game Commission, is situated in the East Branch Big Sewickley Creek valley and in other tributary valleys to the Big Sewickley Creek. The forest here represents some of the most natural land in the area and an important large green space for Allegheny County. All of the forest has been selectively logged more than once, so it does take on the character of a young, early successional forest with scattered mature trees. Since high quality examples of this forest community are fairly uncommon in the county, the Game Commission is encouraged to allow some of this forest to remain undisturbed and mature on its own so that it can be preserved as an example of old growth forest in the future.

[http://www.naturalheritage.state.pa.us/CNAI\\_PDFs/Allegheny%20County%20NHI%201994%20WEB.pdf](http://www.naturalheritage.state.pa.us/CNAI_PDFs/Allegheny%20County%20NHI%201994%20WEB.pdf)

### ***Blue Heronry***

Located within ¼ mile upstream from the Big Sewickley Creek sewage treatment plant, a heronry was identified (at waypoint BSC-38 on Figure 1). According to ([http://en.wikipedia.org/wiki/Great\\_Blue\\_Heron](http://en.wikipedia.org/wiki/Great_Blue_Heron)) great blue herons:

- Usually breed in monospecific colonies, in trees close to lakes or other wetlands; often with other species of herons;
- Maintain Large colonies, ranging between 5–500 nests per colony, with an average of approximately 160 nests per colony; and,
- Build a bulky stick nest, and the female lays three to six pale blue eggs. One brood is raised each year. If the nest is abandoned or destroyed, the female may lay a replacement clutch. Reproduction is negatively affected by human disturbance, particularly during the beginning of nesting. Repeated human intrusion into nesting areas often results in nest failure, with abandonment of eggs or chicks.

Hérons choose nesting sites where food will be plentiful onsite or in very close proximity, where they can have a penthouse view so they can watch for predators, and where they won't be disturbed by people. Great Blue Herons are indicators of ecosystem health because they return to the same site each year (Vermont Fish and Wildlife Department 1995). They are linked with and dependent upon habitat quality.

According to the draft 2005 North American Breeding Bird Survey, Great Blue Heron have been increasing in population since studies were first conducted in 1966 and continue to show positive trends (Sauer et al. 2005). The National Audubon Society (2006) estimates the continental North American population at 124,500. Virginia Department of Conservation and Recreation (2006) reports that heron populations are secure globally, but vulnerable due to restricted habitat requirements and disturbance factors.

Great blue herons are on the increase in Pennsylvania and, unknown to many residents, the Pittsburgh area is home to several breeding colonies -- called rookeries or, more specifically, heronries. A State Game Commission survey of wading birds in 2007 showed that heron nests increased by 32 percent since 2002.

According to the PA Game Commission, in the Pittsburgh area, the rookery in Franklin Park increased from 21 to 41 nests, and three new colonies were established: 17 nests appeared on Twelvemile Island, another 9 at Boyce Mayview Park and 17 more in Deer Creek. Since the survey, a single nest has been built in Allegheny Cemetery. Indeed, the fact that these birds have expanded in density and number in recent years may be attributable to the lowering of pollution in rivers, streams, ponds and lakes.

BAI observed the heronry on the main stem of Big Sewickley Creek and observed several herons over the course of the field assessments, including during field checks of debris jam areas in the fall of 2010. This would seem to indicate that the heron population is sustainable in the watershed and that the water quality is on a positive trend.



[http://dorisdumrauf.blogspot.com/2008\\_03\\_01\\_archive.html](http://dorisdumrauf.blogspot.com/2008_03_01_archive.html)

<http://www.flickr.com/photos/verikoko/2407013460/>

<http://heronsforever.org/greatblueheron>

[http://www.pittsburghlive.com/x/pittsburghtrib/lifestyles/fitness/s\\_633184.html](http://www.pittsburghlive.com/x/pittsburghtrib/lifestyles/fitness/s_633184.html)

### ***Bell Acres Nature Preserve in Bell Acres***

Located at the corner of Turkeyfoot Road and Sevin Road, the Bell Acres Nature Preserve (Park) is a non-traditional borough park with over 200 acres which can be used for hiking, birdwatching, etc. The park also contains the Bell Acres Trail, which is  $\frac{3}{4}$  mile long and ends at the Merriman House foundation. The Merriman Family is believed to be the first settlers in the area. There are no facilities located at this park. Bell Acres was very fortunate to have all of this land donated by The Western Pennsylvania Conservancy. This land will remain parkland in perpetuity.

### **3.0 MUNICIPAL INFORMATION**

There are parts of twelve different municipalities in three counties in the BSC Watershed. Below is some general information on each of the municipalities that gives some background for the demographics of the watershed community.

#### ***Ambridge Borough***

Website: (<http://www.ambridgeboro.org>)

County: Beaver

Population: 7,769

Population Density: 5,232.8 per square mile

Square Miles: 1.7 (0.2 is water)

Governing Body: Mayor and seven (7) member council

Description: "Ambridge began as a steel town in 1905 and thrived for many years until the steel industry collapsed in the early 1980's. Since then, most of the steel industry has moved away, but industries and small steel fabricating companies still remain. In recent years, the town council and community has initiated a massive brownfields project to replace old dilapidated factories with new residential and commercial use structures. Also, a group of enthusiastic citizens has started the Committee to Clean and Beautify Ambridge. This group of dedicated citizens cleans public areas, plants flowers, and has raised money for a beautiful water feature that was built in a park in the center of town. These are only a small sample of the many projects that have recently been completed, are currently being planned, or are underway".

#### ***Bell Acres Borough***

Website: (<http://www.bellacresborough.org>) *Also info from (<http://en.wikipedia.org>)*

County: Allegheny

Population: 1,382

Population Density: 265.3 per square mile

Square Miles: 5.2

Governing Body: Mayor and seven (7) member council

Description: "Bell Acres was settled around 1808. The area was originally established as Sewickley Township on June 28, 1854. Bell Acres was incorporated as its own borough on March 14, 1960. The Borough has sustained slow moderate growth with a population of 443 people in 1870 to approximately 1350 at present. The Borough contains is mostly comprised of single family homes. Bell Acres also has a municipal park located at the corner of Big Sewickley Creek Road and Hitzel Hill Road, and a nature preserve at the corner of Turkeyfoot Road and Sevin Road. The preserve is a non-traditional borough park with over 200 acres which can be used for hiking, birdwatching, etc".

#### ***Cranberry Township***

Website: (<http://www.twp.cranberry.pa.us> )

*Also info from*

*([http://en.wikipedia.org/wiki/Cranberry\\_Township,\\_Butler\\_County,\\_Pennsylvania](http://en.wikipedia.org/wiki/Cranberry_Township,_Butler_County,_Pennsylvania))*

County: Butler

Population: 28,000

Population Density: 1,036.5 per square mile

Square Miles: 23.7

Governing Body: Five (5) member Board of Supervisors



Description: "Cranberry Township, in the southwestern corner of Butler County, Pennsylvania, was incorporated in 1804. The community's name is derived from the wild cranberries which used to grow in the area. Cranberry Township is a land of rolling hills, which are mostly covered with woodlands. Some of the largest oak trees are between 200 and 250 years old."

"One reason for Cranberry's rapid growth has been its location. Situated at the intersection of I-76 (the Pennsylvania Turnpike) I-79, and Routes 19 and 228, the community is easily accessible from virtually anywhere in the region. In addition, the opening of I-279 in 1989 cut travel time to Pittsburgh to less than half an hour."

"Right now, about 40 percent of Cranberry's land is undeveloped; another 10-15 percent may be ripe for redevelopment. Cranberry Township is one of the fastest-growing areas in the United States in both population and businesses. While many residential communities are being built, even more so are retail stores. One of the busiest business centers is at the Cranberry Mall. Cranberry Township is also home to the Thorn Hill Industrial Park, where many businesses are headquartered."

### ***Economy Borough***

Website: (<http://www.economyborough.org>)

Also info from: ([http://en.wikipedia.org/wiki/Economy,\\_Pennsylvania](http://en.wikipedia.org/wiki/Economy,_Pennsylvania));

(<http://www.economyborough.org/EBHistory.pdf>)

County: Beaver

Population: 9,363

Population Density: 1,036.5 per square mile

Square Miles: 17.8 (0.1 is water)

Governing Body: Mayor and seven (7) member council

Description: "Economy's history as a community began in 1827 when Economy Township was formed from the southern part of New Sewickley Township. Economy village had been founded by the Harmony Society just two years earlier, and the increase in population within the area warranted the change. Since the Harmonists worked together to develop intensive cultivation and various manufacturing activities on their lands, Economy village would soon have its own township of Harmony, erected from Economy Township in 1851. The balance of Economy Township remained as it had been, a sparsely populated rural community. The area was settled in the 1790's. The area where John Ullrich made his home became known as Wall Rose, a crossroads village remaining today. The discovery of the Economy oil field in the 1890's brought major changes to the township. Wallace City, just north of the township line in New Sewickley, became the center of the booming oil industry. More than one hundred wells were drilled in the field, which extended from the Pfaff farm in Economy north to Big Knob in New Sewickley. The twelve square mile oil field produced as much as 45,000 barrels of oil a day during peak production years. The oil was under great pressure, and many of the wells produced without pumping. The boom brought construction of boarding houses, livery stables, shops and stores, in addition to drilling rigs, tanks and all sorts of shacks and buildings. Some evidence of the oil industry remains in Tevebaugh Hollow. By 1910, the oil boom had reached its peak, and then quickly declined. Economy's population began to increase with the post war period. In the late 1950's, construction began on Northern Lights Shopping Center, the first large shopping center in Beaver County, located in Economy between Conway and Baden. In 1957, in order to preserve the boundaries of the township and to prevent further annexation by surrounding communities, the residents of Economy Township petitioned for borough status."

On January 1, 1958, the new form of government was adopted and Economy became officially known as Economy Borough. The township's primary concern was the building and maintenance of roads."

"In recent years, Economy Borough's growth has been remarkable as rural areas are converted to suburban housing developments. However, the borough has preserved its rural integrity and charm. Three local parks and picnic areas are maintained, and the borough also hosts Old Economy County Park, a large popular recreation area with a swimming pool and abundant summer activities."

### ***Franklin Park Borough***

Website: (<http://www.franklinparkborough.us>)

*Also info from ([http://en.wikipedia.org/wiki/Franklin\\_Park,\\_Pennsylvania](http://en.wikipedia.org/wiki/Franklin_Park,_Pennsylvania))*

County: Allegheny

Population: 11,364

Population Density: 836.5 per square mile

Square Miles: 13.6

Governing Body: Mayor and seven (7) member council including a junior council member.

Description: "Franklin Park is a growing community located northwest of Pittsburgh in the North Hills area of Allegheny County. The Borough has a highly educated workforce, good schools and a superb quality of life. With quick access to the interstate highway system Franklin Park Borough is within easy reach of the region's retail centers, universities, hospitals, cultural and recreational facilities. It also includes the highest point in altitude in Allegheny County, at 846 feet. There are also 4 parks and one nature reserve. Blueberry Hill Park is Franklin Park Borough's premier community park. It is a beautiful 87 acre park nestled in the heart of the borough off of Nicholson Road. Linbrook Park is an 80 acre park located in the western part of Franklin Park Borough off of Big Sewickley Creek Road. More of a natural park, it is a great place to visit since most of the park is not developed. Acorn Park is a 25 acre park located off of McGee Road, most of this park is a natural area having been untouched for over 100 years. Old Orchard Park is a 16 acre neighborhood park located in the southeastern part of Franklin Park Borough off of Rochester Road. This park is currently under development with a one mile walking trail. The Mel Lubert Nature Reserve is a natural area consisting of an 8 acre park located in the northeastern section of Franklin Park Borough off of Wexford Run Road. Currently it remains a natural area with Pine Creek running through it and two retention ponds that host a variety of wildlife species. Future plans are to construct a nature trail through the park."

### ***Harmony Township***

Website: (<http://www.harmonytwp.org>)

*Also info from*

*([http://en.wikipedia.org/wiki/Harmony\\_Township,\\_Beaver\\_County,\\_Pennsylvania](http://en.wikipedia.org/wiki/Harmony_Township,_Beaver_County,_Pennsylvania))*

County: Beaver

Population: 3,373

Population Density: 1,176.3 per square mile

Square Miles: 3.0 (0.2 is water)

Governing Body: Five (5) member board of commissioners.

Description: "Harmony Township was formed in 1851 from Economy Township, and is comprised of 3.13 square miles and has a population of 5,022 as of 2004. Economically and

socially, the township is a sub-center of the Pittsburgh metropolitan area. Major manufacturers located within the township provide raw materials and finished products”.

***Leet Township***

Website: (<http://leettownship.org>)

*Also ([http://en.wikipedia.org/wiki/Leet\\_Township,\\_Pennsylvania](http://en.wikipedia.org/wiki/Leet_Township,_Pennsylvania))*

County: Allegheny

Population: 1,568

Population Density: 983.9 per square mile

Square Miles: 1.6

Governing Body: Five (5) Township Commissioners

Description: “There are 569 households out of which 36.0% have children under the age of 18 living with them, 67.7% are married couples living together, 8.1% have a female householder with no husband present, and 20.4% are non-families. 17.8% of all households are made up of individuals and 8.1% have someone living alone who is 65 years of age or older. The average household size is 2.70 and the average family size is 3.08.”

**A historical account of the flood of September 2004 on Big Sewickley Creek provided by Leet Township emergency management officials:**

“The night of September 17th was unlike any other time, in our community of Fair Oaks. It compared to the flood of 1936, for those who were around back then and could compare the two. Those of us with experience in Crisis Management had our limits and knowledge tested to the limit. That evening we received over 6 inches of rainfall and a night most of us will never forget”.

“The water of Big Sewickley Creek came up so quickly and flowed so rapidly that its path left devastation and shock all along the creek route. Backyard items were floating away; water was taking refuge in basements, crashing through windows and flooding garages. Residents were scrambling and emergency sirens were ringing out in neighborhoods bordering the creek”.

“The Fair Oaks Fire Department and Allegheny Emergency Management were receiving never-ending calls for help. Other communities in Beaver County were sending additional help, along with rescue boats and vehicles that could maneuver through the high rising water. The Quaker Valley School District provided safe haven for students who were stranded and supplied buses to transport evacuated residents to the upper Heath South facility located at the top of Camp Meeting Road. The primary focus at this point for me as Emergency Management Coordinator was to set up the Emergency Operations Center, provide safe transportation to those evacuated [with housing assistance from the Heath South staff for those with special needs and the evacuees, the American Red Cross and the Salvation Army for providing food] and prioritize community needs as requests came in from the F.O. Volunteer Fire Department. The Emergency Operations Center was located in the F.O.V.F.D. and a 24-hour a day kitchen was established to feed residents and emergency workers as well as a small medical station for those with light injuries. The kitchen ran from Friday night until Monday evening, providing meals and a warm refuge to those who needed it. Those in the F.O.V.F.D. were heroes as they worked non-stop throughout the day and night. They were victims as well, putting the needs of others ahead of themselves.”

"Clean up began, neighbors were helping neighbors, dumpsters were brought in [approximately 46], and the damage assessment was to begin its long and tedious job of contacting insurance agencies, FEMA, local help organizations, and re-formation of family life, as best possible. This cleanup would go on for months".

### ***Leetsdale Borough***

Website: (<http://www.leetsdaleboro.net>)

Also ([http://en.wikipedia.org/wiki/Leetsdale, Pennsylvania](http://en.wikipedia.org/wiki/Leetsdale,_Pennsylvania))

County: Allegheny

Population: 1,232

Population Density: 1,246 per square mile

Square Miles: 1.1 (0.2 is water)

Governing Body: Mayor and seven (7) member council

Description: "Leetsdale is located 12 miles north of Pittsburgh on Route 65, it's the last Allegheny County community along the Ohio River. More than 3,000 people work within the borough. Leetsdale is divided almost evenly by Route 65 and the Norfolk Southern Railroad tracks. The property on the West Side of the tracks is predominately commercial and industrial with the Buncher Commerce Park and Leetsdale Industrial Park accounting for much of the approximately one hundred businesses in the borough. Leetsdale has recently gone through several major changes. An overpass, which eliminated the dangerous at-grade railroad crossing at Ferry Street was constructed, and a new municipal building was completed."

### ***Marshall Township***

Website: (<http://www.twp.marshall.pa.us>)

([http://en.wikipedia.org/wiki/Marshall Township, Pennsylvania](http://en.wikipedia.org/wiki/Marshall_Township,_Pennsylvania))

County: Allegheny

Population: 5,996

Population Density: 384.4 per square mile

Square Miles: 15.6

Governing Body: Five (5) member Board of Supervisors

Description: "Marshall Township has a rural atmosphere, yet it is situated a short 20-minute drive north of Pittsburgh's business and cultural centers via I-79/279. It is located in the northwest corner of Allegheny County. Marshall is bordered by Cranberry Township to the North, Franklin Park Borough to the South, Pine Township to the East, Economy Borough to the West, and borders Bradford Woods Borough on three sides. Incorporated June 3, 1863, it was named for Thomas Mercer Marshall, a famous trial lawyer who practiced law in Allegheny County. Two Indian trails, a meteorite, oil wells, and the Harmony Shortline are only a small part of the rich and colorful history. The Indian trails dating from the colonial times wind their way through the area. Marshall Township's Park facilities consist of 116 Acre Knob Hill Park; 8 Acre Warrendale Park; The Sean DeArment Nature Trail; and 2 Mile Thorn Hill Trail with crushed limestone surface suitable for walking, biking, or cross country skiing."

### ***New Sewickley Township***

Website: (<http://www.newsewickley.com>)

County: Beaver

Population: 7,076

Population Density: 216.6 per square mile

Square Miles: 32.7

Governing Body: Five (5) member Board of Supervisors

Description: "New Sewickley Township is a part of depreciation lands that were set aside by Act of Assembly on March 12, 1783 to be awarded to those men who served in the Revolutionary War. In 1801 the original Sewickley Township was divided and New Sewickley Township was created. At that time, New Sewickley Township was situated in the eastern part of Beaver County and was composed of about 19,279 acres of hilly, but very fertile land. Over the next 28 years, New Sewickley Township was reduced in size by forming Economy Borough, Rochester Township and Pulaski Township. Today, New Sewickley Township is a rural community with a population of approximately 7,076. The Township's skyline is easily recognized from nearly every high point in the county because of Big Knob, a dome-shaped hill nearly 200 feet higher than any of its neighbors. It is recognized as Beaver County's highest point. The Township purchased 80.5 acres from Mr. Rolland Richardson in 1965 for construction of Green Valley Park. In 1982, Mr. Blake Walker donated an additional 8.7 acres. The Park now consists of athletic fields for baseball, softball and soccer, play areas for children and picnic shelters that may be reserved."

#### **4.0 FISH AND MACROINVERTEBRATE SURVEYS**

A biological assessment was completed by the Western Pennsylvania Conservancy in July of 2008 with assistance from BAI, BSCWA, ACCD, and BCCD (Attachment C). This included a macroinvertebrate and fish survey, as well as water chemistry analysis at each site. The conclusions of the report are summarized below.

Macroinvertebrate surveys were conducted following the benthic macroinvertebrate protocol for single habitat streams, as described in the United States Environmental Protection Agency's (EPA) *Rapid Bioassessment Protocols for Use in Wadeable Streams and Rivers*. A sample area consisted of a 100 meter stream reach at sites previously selected by BAI. Two kicks were taken at each sample area using a kick net (500 micron screen). A single kick consisted of substrate disruption in front of the collection net (one square meter) for 60 seconds. Following sample collection, specimens and sediment were transferred from the examined collection net into sample bottles and preserved with 95% alcohol. Preserved samples were delivered to the laboratory for processing and identification. Laboratory procedures followed EPA protocols. Samples were taken at nine sites within the Big Sewickley Creek watershed, site names, and descriptions are included in the individual analysis section of Attachment C (Page 5-20). Macroinvertebrate samples were carefully examined and organisms were separated from the debris in the laboratory. The identified organisms were transferred to collection bottles and preserved with 70% alcohol. Organisms were identified to the family taxonomic level under a dissecting microscope. Quality control procedures included a qualified staff member sorting through a sub-section of the sample to check for missed organisms.

Fish surveys were conducted following the electrofishing protocol for single habitat streams described in *EPA's Rapid Bioassessment Protocols for Use in Wadeable Streams and Rivers*. A Smith-Root LR-24 Electrofisher electrofishing unit was implemented to temporarily immobilize the fish for the purpose of identification. The sample area consisted of a 200 meter stream reach at sites previously selected by BAI. Following sample collection, fish were identified at the end of the reach or if there was no longer room available in the bucket to continue the collection of specimens, which ever procedure was most appropriate. Specimens were identified by Mr. Gary Smith, Southwest Regional Habitat Biologist for the Pennsylvania Fish and Boat Commission (PAFBC).



Surveys were conducted at three sites within the Big Sewickley Creek watershed, site names and descriptions are included in the individual analysis section of Attachment C. Only one preserved sample was collected, Site 6:NFT2W1, as representatives of the southern redbelly dace (*Phoxinus erythrogaster*). This species is not seen very often in this part of Pennsylvania according to the PAFBC.

The following metrics were used to analyze the macroinvertebrate data for this study: (1) total number of taxa, (2) number of EPT taxa, (3) percent EPT, (4) percent Diptera, (5) Shannon Diversity Index (H), and (6) pollution tolerance index (PTI). Total number of taxa indicates the number of families present in the sample, and number of EPT taxa indicates the number of families of mayflies (Ephemeroptera), stoneflies (Plecoptera), and caddisflies (Trichoptera) present in the sample. Percent EPT to percent Diptera ratio compares the number of mayflies, stoneflies, and caddisflies to the number of true flies (Diptera). Diptera organisms are generally more tolerant of pollution than EPT organisms. An abundance of Diptera organisms indicates poorer water quality.

Diversity indices are mathematical measures of species diversity in a community. The Shannon Diversity Index provides information about species richness and also takes into account the relative abundances of different species. The higher the index value, the more diverse the community. The Pollution Tolerance Index (PTI) is based on the concept of indicator organisms and tolerance levels. Indicator organisms are those organisms sensitive to water quality changes and their presence or absence indicates the condition of the water in which they live. Pollution-intolerant organisms include mayflies, stoneflies, caddisflies, riffle beetles, and water pennies. Pollution-tolerant organisms include tubifex worms, midges, pouch snails, and leeches. Figure 31 includes the macroinvertebrate analysis and is located on page 25.

The Fish Index of Biotic Integrity (FIBI), is an index that measures the health of a stream based on multiple attributes of the resident fish assemblage. Each site was sampled and the score is based on its deviation from reference conditions and classified as "poor," "fair," "good," or "excellent." The FIBI calculates data relating to; (1) Total number of species found, (2) Number of benthic insectivorous species, (3) Number of salmonidae and centrachidae, (4) Proportion of pollution intolerant species, (5) Proportion of pollution tolerant species, (6) Proportion of generalists, (7) Proportion of insectivorous cyprinids, (8) Number of piscivorous species, (9) Number of individuals in the sample, and (10) Proportion of species with disease, excluding blackspot. The total FIBI analysis is included on page 24 of Attachment C. Section two of the FIBI, identifies benthic insectivores, meaning those fish species that are located in the lowest part of the water column and feed exclusively on aquatic insects. Section three refers to the amount of fish species found at the sampled site, such as; trout, salmon, sunfish, bass, and crappies. Section four identifies the percentage of pollution intolerant individuals such as; lamprey, cutlip minnows, southern redbelly dace, hognose suckers, trout, sculpin, and walleye. Section five identifies the percentage of pollution tolerant individuals such as; the american eel, fathead minnows, pickerels, muskellunge, pike, killifish, bluegill, and sunfish. Section six, refers to the percentage of fish species that feed on whatever may be available such as, algae and insects. Section seven identifies those fish that can survive in multiple habitats or will consume multiple food sources. These generalists species include; chubs, shiners, minnows, and daces. Section eight of the FIBI metric aids in calculating the percentage of fish species that primarily feed on other types of fish. And lastly, section ten takes into

account the percentage of fish species that had a disease or disfigurement other than blackspot, which is actually a parasitism caused by a turbellarian flatworms.

The review of biological assessment metrics showed the following ranking of the sites from best quality to worst; 6, 4, 1, 7, 8, 2, 5, 9, and 3. Macroinvertebrate sampling conducted at the nine sites within the Big Sewickley watershed resulted in an average Pollution Tolerance Index (PTI) rank of 15.11, which ranks the sites sampled within the watershed as a "fair."

The electrofishing survey of three, of the nine sites, within the Big Sewickley watershed resulted in the identification of 20 different species of fish, with 766 individuals being sampled. Overall, the Fish Index of Biotic Integrity (FIBI) score was a 39, which ranks the watershed as a "good."

The three metrics of assessment resulted in the highest ranking within the watershed for Site 6 (NFT-2W1). This may be due to the heavily vegetated riparian buffer and a reduced residential impact. The other sites may have ranked lower to due to: reduced riparian buffers, roadway runoff, storm water management issues, or residential impacts.

## **5.0 WATER QUALITY**

To get a better idea of the water quality of the watershed, BAI performed bacteria sampling at various points on each of the streams. Bacteria was an impact that was identified by the BSCWA at the beginning of the assessment as an issue of concern in the watershed. Biological Sample Results are included in Attachment D and depicted visually on Figure 5. The following sites had elevated levels for fecal coliform:

- BSC08F on Shaffer Road (56,000 colony forming units (cfu)/100 ml.)
- NF05F (34,000)
- BSC04F (4,200)

Bacteria levels in the main stem of Big Sewickley Creek should be improving most recently, since the above samples were taken, because of a recent sanitary line project in Marshall Township. Marshall Township has extended a new sanitary line down Warrendale-Bayne Road to Big Sewickley Creek Road. These construction areas were observed to be completed and recently stabilized with seed and mulch during field checks by BAI in October of 2010.


A previous study on bacteria in the watershed was conducted on the North Fork in March 2003. According to a report titled "*North Fork Big Sewickley Creek Water Quality Study of Bradford Park Area - A Boy Scout Eagle Service Project*", by Chad Kuny, the objective of the project was to investigate the influence of failing septic systems, and to establish a baseline of data for the watershed. He concluded that due to elevated fecal coliform results from the six sample sites septic tanks in the area were most likely failing. In addition, samples were taken near the salt storage depot at the Economy Borough building and elevated chloride levels were noted due to the runoff that was occurring into the stream. A sanitary system upgrade in Economy Borough was constructed since this 2003 report. BAI sample NF05F above was high in cfu. There is a possibility that some of the residents in this area are still not tied in to the sanitary sewer system for Economy Borough. More detailed sampling would need to occur to try to determine more specific causes of these elevated bacteria levels.

Overall, based on BAI field observations and recent developments with municipal sanitary systems, the bacteria levels in the streams of the watershed should be going down. The main impairment to water quality is erosion and sedimentation from development and lack of storm water management.

## 6.0 WATERSHED ISSUES

Out of the 40 sections surveyed, 48% received a good rating, 35% were fair, 10% were excellent, and 7% received a poor rating. An average score of 7.59 (lower end of “good”) was calculated for the watershed. This scoring is based on the modified USDA Visual Assessment Protocol that was utilized by BAI to visually assess the streams and surrounding areas of the watershed. A copy of all of the visual assessment field sheets is provided in Attachment E. This protocol provides a numerical score for 13 different parameters that are indicators of water quality and stream health.

<6.0	Poor
6.1-7.4	Fair
7.5-8.9	Good
>9.0	Excellent



The Big Sewickley Creek Watershed is a mix of rural, old, and new residential, and still has some large areas of undeveloped land. The goal of this project was to assess the watershed and develop recommendations for restoration and protection of the natural resources within the watershed.

The main impacts to the watershed are erosion and sedimentation. This is caused by improper storm water management, stream bank erosion, stream debris jams, stream encroachment, and riparian buffer alterations/degradation. Encroachments by landowners on the streams were evident in all parts of the watershed. Examples of this included filling, dump sites, improper stream crossings, yard waste dumping, utility crossings, and debris jams. Many of these issues were observed in the field and identified on the enclosed maps in this report (see Figure 2). These encroachments cause watercourses to change, bank erosion, sedimentation, and flooding.

Storm water management is an issue in this watershed. Big Sewickley Creek was hit by the floods of September 2004. These events, especially Hurricane Ivan, opened many people's eyes to the importance of floodplain and storm water management. Many areas of the watershed that were affected by Hurricane Ivan were also impacted earlier that summer by heavy thunderstorms. Many storm water outlets and facilities were observed throughout the watershed that seemed to have a negative effect on their receiving streams, whether it is through bank erosion or sheer volume of water being released. Some of the larger

outlets/outfalls were marked by BAI in the field and are shown as Storm water management issues/facilities on Figure 3.

In addition, current and future land use planning is a significant concern for the many remaining undeveloped land tracts within the watershed. Several large tracts of open space, with high water quality were observed in each sub-watershed. These areas hold an abundance of flora and fauna that are not found in many neighboring areas of southwestern Pennsylvania because of development. These open space areas also act as a natural filter and buffer to development. Therefore, because these areas are essential to maintaining a healthy watershed community, it is important to protect them.

*The sections of the report that follow (sections 7.0 to 11.0) describe the findings of the visual assessments that were conducted by BAI on the main stem of Big Sewickley Creek and the major tributaries in the watershed. Stream segments were broken out based on contiguous land use. Each stream segment started at the mouth of the stream and worked upstream until there was a change in land use immediately adjacent to the stream channel. BAI used the USDA Visual Assessment Protocol to assign a numerical score for a possible 13 different parameters including: channel condition, canopy cover, riparian zone, bank stability, abandoned mine drainage, manure presence, sewage, invertebrate habitat, in-stream fish cover, fish barriers, nutrient enrichment, and water appearance. Scores ranged from <6 = Poor; 6.1-7.4 = Fair; 7.5-8.9 = Good; and >9 = Excellent.*

## **7.0 BIG SEWICKLEY CREEK STREAM SEGMENT ANALYSES**

All of the stream segments/reaches described below have a number that corresponds to the map of the watershed on **Figure 1**.

### **BSC-01 through BCS-09 (fair)**

Waypoints: BSC1-BSC9 (Reach #1)

Segment: Big Sewickley Creek from bridge at entrance to park to mouth at Ohio River.

Date of Assessment: 6/5/07

#### Sewage impacts

There is a noticeable odor, excess plant growth on the substrate, and siltation.

#### Stream bank erosion and siltation

There does not appear to be a lot of bank erosion in this section of the creek. The banks appear moderately stable. There is not a significant problem with sedimentation, but the embeddedness ranges from 20-30% for this section of the creek. This is not uncommon for a flat sloped area of a stream, near the junction with the river where there could be backwaters also. There is sediment build up, creating a sand bar, at the mouth of the creek where it enters the Ohio River (see photo 1).

#### Wetlands

There is about 1 acre of wetlands (see photo 2 and Figure 6) located along this area of the Big Sewickley Creek.

### Invasive Plants

Japanese Knotweed was found growing along this reach of Big Sewickley Creek. This is to be expected because of the close proximity to the railroad lines which have an abundance of this plant.

### Trash and Litter

There is a small amount of trash scattered throughout this section.

### Conclusions and Recommendations

This section of Big Sewickley Creek received a visual assessment score of 6.27 out of 10 which means it is in Fair condition, according to the scoring system provided by the USDA visual assessment protocol. There is not a lot of erosion. There is a sewage impact and some trash in this part of the stream.

Algal growth indicates this reach of the stream is high in nutrients. This may be caused by treated effluent from the sewage treatment plant having high levels of nutrients. Effluent from the sewage treatment plant should be monitored to insure that concentrations of nutrients and Total Suspended Solids do not exceed effluent discharge limits.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks. Stream channel restoration can reduce the stream bank erosion, reduce sediment deposition in the channel, and reduce the formation of sand bars.

There is a possible stream project opportunity at Plum Street Park (Figure 7). The channel is too wide and shallow and could be restored. Trash and litter in the area needs to properly addressed.





Photo 1: Mouth of Big Sewickley Creek, discharging into the Ohio River. (BSC-01)



Photo 2: Large floodplain wetland upstream from the mouth. (BSC-08)

### **BSC-10 through BSC-16 (fair)**

Waypoints: BSC10-BSC16 (Reach #2)

Segment: Big Sewickley Creek from bridge at ballpark to concrete storm water pipe in Fair Oaks.

Date of Assessment: 6/5/07

#### Sewage impacts

There is a noticeable odor, excess plant growth on the substrate, and siltation.

#### Stream bank erosion and siltation

There is a severe amount of erosion in this section of the creek. There are undercut banks across from the ballpark and some erosion by 2 storm water outfalls. There is a huge bank erosion area that is 6 feet high and 100 feet long (see photo 1), and a few debris jams that are piling up on concrete structures in the creek (see photo 2). The debris jam at BSC14 has been cleaned out as of 9/24/10. The embeddedness ranges from 30-40% for this section of the creek.

#### Wetlands

There are no wetlands along this area of the creek.

#### Invasive Plants

Japanese Knotweed was found growing along this reach of Big Sewickley Creek.

#### Trash and Litter

There is a small amount of trash scattered throughout this section.

#### Conclusions and Recommendations

This section of Big Sewickley Creek received a visual assessment score of 6.36 out of 10 which means it is in Fair condition, according to the scoring system provided by the USDA visual assessment protocol. There is a lot of stream bank erosion in this section of main stem of Big Sewickley Creek.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks. Stream channel restoration can reduce the stream bank erosion, reduce sediment deposition in the channel, and reduce the formation of sand bars. The site pictured below at BSC12 would be a good site for a project because of ease of access from the township park.

Algal growth indicates this reach of the stream is high in nutrients. This may be caused by treated effluent from the sewage treatment plant having high levels of nutrients.

There were also some children here at the time of the assessment that can be seen holding a recent catch from a nearby pool in the stream (see photo 3). Trash along the edge of the stream channel in this section should be able to be policed by Leet Township code enforcement.





Photo 1: A six foot high by 100 foot long section of streambank erosion. (BSC-12)



Photo 2: Debris piling up on concrete in stream. (BSC-14)





Photo 3: Fish caught by children. (BSC-14)

### **BSC-17 through BSC-26 (fair)**

Waypoints: BSC17-BSC26 (Reach #3)

Segment: Big Sewickley Creek main stem above Fair Oaks.

Date of Assessment: 6/11/07

#### Sewage impacts

There is a noticeable odor, excess plant growth on the substrate, and siltation. There is also a 6-8" metal pipe discharging from the trailer court sewage plant near BSC30 (see photo 1).

#### Stream bank erosion and siltation

The banks appear to be moderately stable and there is no reported erosion throughout this section of the stream. There is however a lot of debris that is piling up on concrete structures in the creek bed (see photo 2).

The embeddedness ranges from 30-40% for this section of the creek. This is probably due to several (4) storm water pipes that discharge in this section of the stream.

#### Wetlands

There are no wetlands located along this section of Big Sewickley Creek (BSC).

#### Invasive Plants

Japanese Knotweed was found growing along this reach of BSC.

#### Trash and Litter

There is a little trash scattered throughout this section.

Conclusions and Recommendations

This section of Big Sewickley Creek received a visual assessment score of 6.27 out of 10 which means it is in Fair condition, according to the scoring system provided by the USDA visual assessment protocol. There are sewage impacts and some trash in this part of the stream.

Algal growth indicates this reach of the stream is high in nutrients. This may be caused by treated effluent from the sewage treatment plant having high levels of nutrients. Effluent from the sewage treatment plant should be monitored to insure that concentrations of nutrients and Total Suspended Solids do not exceed effluent discharge limits.



Photo 1: Sewage plant discharge from trailer court. (BSC-25)





Photo 2: More evidence of debris piling up on concrete in the stream. (BSC-26)

### **BSC-27 through BSC-33 (fair)**

Waypoints: BSC27-BSC33 (Reach #6)

Segment: Big Sewickley Creek running alongside the Big Sewickley Creek road.

Date of Assessment: 7/3/07

#### Sewage impacts

There is a noticeable odor, excess plant growth, and siltation.

#### Stream bank erosion and siltation

There is a bank that is eroded because the opposite side of the creek is a concrete wall which is constricting the creek channel (see photo 1). There is also heavy sediment build up on the right side of the bridge by Zassick's Auto (see photo 2). The embeddedness is around 30% throughout this section of the stream.

#### Wetlands

There are no wetlands located in this area of the Big Sewickley Creek.

#### Invasive Plants

Japanese Knotweed was found growing in this reach of Big Sewickley Creek.

#### Trash and Litter

There are auto parts, plastics, and flood debris littered throughout this section of the creek.

Conclusions and Recommendations

This section of Big Sewickley Creek received a visual assessment score of 6.73 out of 10 which means it is in Fair condition. There is erosion and sediment buildup in this region of the stream at BSC30.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks.



Photo 1: Concrete wall at Ed Wagner Auto Salvage constricting channel. (BSC-30)



Photo 2: Right side of bridge by Zassick's Auto is silted in. (BSC-33)

### **BSC-34 through BSC-42 (fair)**

Waypoints: BSC34-BSC42 (Reach #8)

Segment: BSC just upstream of bridge at white concrete office to Gaydos Lane Bridge.

Date of Assessment: 7/3/07

#### Sewage impacts

The Hanson-Sewickley Creek Plant is located immediately adjacent to the stream (see photo 1). There is also a sewage treatment plant (see photo 2) located on this section of the stream, and it is discharging liquid with a greenish/black color (see photo 3). There is also a Blue Heron Rookery (heronry) nearby (see photo 4). BAI observed bird droppings and dead fish around the ground which is creating a strong smell.

#### Stream bank erosion and siltation

There is no noticeable bank erosion in this area and the banks appear to be stable, with a good riparian zone. The embeddedness is 30%.

#### Wetlands

There are no wetlands located in this stream reach.

#### Invasive Plants

Japanese Knotweed was found growing along this stream reach.

#### Trash and Litter

There was some minor trash found in this section of the stream.



Conclusions and Recommendations

This section of Big Sewickley Creek received a visual assessment score of 6.91 out of 10 which means it is in Fair condition.

Algal growth indicates this reach of the stream is high in nutrients. This may be caused by treated effluent from the sewage treatment plant having high levels of nutrients. Effluent from the sewage treatment plant should be monitored to insure that concentrations of nutrients and Total Suspended Solids do not exceed effluent discharge limits.

There is a white discharge seen coming out of the creek bank (see photo 5). BAI is not sure what was causing this discharge. Often times white discharges are indicative of aluminum in abandoned mine water. Fisherman Kevin Holman is seen showing off his catch of an orange koi (see photo 6). It should be noted that this species is invasive.



Photo 1: Hanson-Sewickley Creek Plant located right up on stream bank. (BSC-34)



Photo 2: Sewage treatment plant. (BSC-36)



Photo 3: Greenish-black discharge from sewage plant. (BSC-36)





Photo 4: Blue heron nests (heronry) located on the south side of Big Sewickley Creek. (BSC-38)



Photo 5: White discharge coming from a flow on the south side of the Creek. (BSC-41)



Photo 6: A local boy catches an orange koi. (BSC-41)

### **BSC-43 through BSC-52 (fair)**

Waypoints: BSC43-BSC52 (Reach #9)

Segment: Big Sewickley Creek from Gaydos Lane Bridge to a floodplain wetland.

Date of Assessment: 7/13/07

#### Sewage impacts

There is a noticeable odor, excess plant growth and siltation. The sanitary line installation has also caused stream changes and damages (see photo 1).

#### Stream bank erosion and siltation

There are a few small bank erosions throughout this section, however there is a seven foot high bank erosion (see photo 4) which created a deep pool with a greenish color. There are also several areas of sediment buildup which have created sand bars (see photos 2&3), which in turn have created debris jams. There is also heavy sedimentation at the mouth of Cooney Hollow where homeowners are encroaching on the creek with cement blocks (see photo 5). In some areas the water is cloudy with a greenish hue and the embeddedness is between 20-30% throughout this section.

#### Wetlands

There is a floodplain wetland that is approximately 1,000 feet long by 400 feet wide along this section of the stream at BSC52.

#### Invasive Plants

Japanese Knotweed was found growing along this reach of BSC.



Trash and Litter

There was some trash found along this section of the stream.

Conclusions and Recommendations

This section of BSC received a visual assessment score of 6.55 out of 10 which means it is in Fair condition. This section of the stream has a few bank erosion areas, several sand bars, and debris jams.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks.



Photo 1: Black pipe with hose coming off of Chem-Dry property. (BSC-46)





Photo 2: Sediment bar built up in middle of stream. (BSC-45)



Photo 3: Large sediment build up and debris jam at a sanitary sewer crossing. (BSC-48)





Photo 4: Seven foot high bank erosion and a deep greenish colored pool. (BSC-48)



Photo 5: Location of the mouth of Cooney Hollow. Homeowners are encroaching the stream with concrete blocks. (BSC-50)

### **BSC-53 through BSC-60 (good)**

Waypoints: BSC53-BSC60 (Reach #10)

Segment: BSC from debris jam to incoming tributary.

Date of Assessment: 7/13/07

#### Sewage impacts

There were no notable sewage discharges but there was an abundance of brown and black algae growing in this section of the stream. This indicates possible nutrient enrichment in the stream.

#### Stream bank erosion and siltation

The banks are stable and there does not appear to be excessive erosion. The embeddedness is from 20-30%.

#### Wetlands

There are no wetlands along this stream reach.

#### Invasive Plants

Japanese Knotweed was found growing along this reach of BSC.

#### Trash and Litter

There was no trash found along this section of the stream.

#### Conclusions and Recommendations

This section of BSC received a visual assessment score of 7.7 out of 10 which means it is in Good condition, according to the scoring system provided by the USDA visual assessment protocol.

There was an abundance of dark brown and black algae growth in the area where a dam was placed in the stream by the PA Game Commission (see photo 1). The dam is there because that area is protected by the PA Game Commission as a waterfowl preservation area. The dam acts as a fish impasse as fish cannot swim past it to get up or downstream.





Photo 1: Area protected by the PA Game Commission for waterfowl. (BSC-58)

**BSC-61 through BSC-65 (fair)**

Waypoints: BSC61-BSC65 (Reach #11)

Segment: BSC from wetlands to incoming tributary.

Date of Assessment: 7/13/07

*Sewage impacts*

There are no sewage treatment plants on this stretch of stream, and no visible impacts.

*Stream bank erosion and siltation*

There are a few areas of bank erosion throughout this stream segment. One area is caused by an incoming tributary, while another erosion area is caused by a man-made rock dam (see photo 1). The water in the rock dam is also very cloudy. Further downstream there is also a tree debris jam with brown algae growing on it. The sediment from the erosion is causing the embeddedness to be around 30%.

*Wetlands*

There is a small 25 by 25 foot patch of wetlands near the start of this part of the stream at BSC61 (see photo 2).

*Invasive Plants*

Japanese Knotweed was found growing along this reach of BSC.

*Trash and Litter*

There was no trash found along this section of the stream.

Conclusions and Recommendations

This section of BSC received a visual assessment score of 7.3 out of 10 which means it is in Fair condition. This section of the stream has some bank erosion, and a man-made rock dam which is causing the water to become murky.

The eroded stream banks could be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks.

People should also be discouraged from building rock dams along the stream. These dams slow the water flow causing sediment to build up, creating sand bars and clouding the water.



Photo 1: Man-made rock dam creating bank erosion in the bend on the left. (BSC-64)





Photo 2: Floodplain wetland area. (BSC-61)

**BSC-66 through BSC-70 (good)**

Waypoints: BSC66-BSC70 (Reach #12)

Segment: BSC from bridge over Big Sewickley Creek Road to bridge at Warrendale-Bayre Road.

Date of Assessment: 7/24/07

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

The bank is eroded in a few areas in this section (see photo 1). A man made rock dam was made (see photo 2) which contributed to sediment buildup due to reduced flow of water (see photo 3). Even with the erosion, the embeddedness is still low at 20%.

Wetlands

There are no wetlands along this section of the stream.

Invasive Plants

No invasive plants were found growing along this reach.

Trash and Litter

There was no trash found along this section of the stream.

Conclusions and Recommendations

This section of Big Sewickley Creek received a visual assessment score of 7.7 out of 10 which means it is in Good condition. This section of the stream has some bank erosion. Marshall Township has completed a new sanitary line installation in this section of stream, as of October 2010. The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks.



Photo 1: Bank erosion and massive slope failure in a homeowner's front yard. (BSC-67)





Photo 2: Rock dam contributing to sediment bar problem due to reduced water flow. This has been removed as of 10/05/10 field check (BSC-69).



Photo 3: Large sediment bar built up in middle of stream. (BSC-69)



### **BSC-71 through BSC-76 (fair)**

Waypoints: BSC71-BSC76 (Reach #13)

Segment: BSC from drainage to pond off Markman Road.

Date of Assessment: 7/24/07

#### Sewage impacts

There are no visible impacts from sewage on this reach. New sanitary line recently completed in this area.

#### Stream bank erosion and siltation

The bank is eroded in a few areas in this section. There are also some sandbars caused by sediment build up which are created debris jams (see photo 1&2). Even with the erosion problems, the embeddedness is still low at 20%. Some of the debris jams in this area were removed in Fall of 2010 when sanitary line was completed.

#### Wetlands

There is a large floodplain wetland (BSC76) in this section of Big Sewickley Creek. It is approximately 4000 feet long by 500 feet wide. There is a flooded area from the pond above Markman Road upstream (see photo 3).

#### Invasive Plants

No invasive plants were found growing along this reach of BSC.

#### Trash and Litter

There was no trash found along this section of the stream.

#### Conclusions and Recommendations

This section of BSC received a visual assessment score of 6.6 out of 10 which means it is in Fair condition, according to the scoring system provided by the USDA visual assessment protocol. This section of the stream has some streambank erosion which is creating sediment islands and debris jams.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks. There could be a nice area for a streambank stabilization project at BSC76.

The debris jams along with the on stream pond at Markman Road act as fish barriers, preventing fish to travel past them.



Photo 1: Large sediment buildup in the middle of the stream. (BSC-74)



Photo 2: Debris jam creating a large pool. (BSC-75) This jam has been removed as of 10/05/10 field check.





Photo 3: An on-stream pond and wetland area near Markman Park Road. (BSC-76)

**BSC-77 through BSC-82 (good)**

Waypoints: BSC77-BSC82 (Reach #14)

Segment: BSC from Sleepy Hollow Lane to Cliff Road Bridge.

Date of Assessment: 7/24/07

*Sewage impacts*

There are no visible impacts from sewage on this reach.

*Stream bank erosion and siltation*

There is no bank erosion in this area; the banks are very stable; and they have a good riparian zone. The embeddedness is low as well at only 20%.

*Wetlands*

There is a large, floodplain wetland (see photo 1, BSC78) along a long section of this stream reach.

*Invasive Plants*

No invasive plants were found growing in this reach of Big Sewickley Creek.

*Trash and Litter*

There was no trash found in the section of the stream.

*Conclusions and Recommendations*

This section of BSC received a visual assessment score of 8.4 out of 10 which means it is in Good condition. This high ranking shows the value of a preserved riparian zone with no

encroachment on the stream channel and floodplain. This stream reach would be a tremendous area to construct a regional storm water management facility and/or wetland mitigation bank.



Photo 1: Large grassland floodplain. (BSC-77)



Photo 2: A sinuous channel that would make a good area for wetlands mitigation bank project. (BSC-78)

**BSC-83 through BSC-85 (good)**

Waypoints: BSC83-BSC85 (Reach #15)

Segment: BSC from road drainage area to Spang Road bridge.

Date of Assessment: 7/26/07

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

There is no bank erosion in this area, but drainage from the road is causing excess sediment to enter the stream (see photo 1). There are also 3 ATV crossings along the stream which can cause sedimentation while degrading the stream banks and channel. The sediment in the water has created an embeddedness of 20-30%.

Wetlands

There are no wetlands in this section of BSC.

Invasive Plants

No invasive plants were found growing in this reach of BSC.

Trash and Litter

There was no trash found in the section of the stream.



### Conclusions and Recommendations

This stream reach received a visual assessment score of 7.6 out of 10 which means it is in Good condition. This section of the stream has several ATV crossings (BSC83) that have degraded the banks, and also has a small landslide. These erosion problems contribute to the 20-30% embeddedness in the stream channel.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks. ATVs should be discouraged from driving through the channel, but this is sometimes difficult to enforce on private property.



Photo 1: Drainage area coming off of road bringing in excess sedimentation. (BSC-84)

### **BSC-86 through BSC-97 (good)**

Waypoints: BSC86-BSC97 (Reach #16)

Segment: BSC from above Spang Road bridge to incoming tributary from the west.

Date of Assessment: 7/26/07

### Sewage impacts

There are no visible impacts from sewage on this reach.

### Stream bank erosion and siltation

There is no bank erosion but there is a small landslide (see photo 1, BSC87) which has added sediment to the stream. There was a fallen tree that created a debris jam and a small sand bar, which created a deep pool (see photo 2). There is also several trees that were cut down and left by the stream (see photo 3), from nearby construction, which are adding to the debris jams. A homeowner made a dam out of a sheet of metal (see photo 4) which is creating

downstream sedimentation. The excess sediment in the water has created embeddedness ranging from 20-30%.

#### Wetlands

There are no wetlands along this section of Big Sewickley Creek.

#### Invasive Plants

No invasive plants were found growing in this reach of Big Sewickley Creek.

#### Trash and Litter

There was no trash found along this section of the stream.

#### Conclusions and Recommendations

This section of Big Sewickley Creek received a visual assessment score of 8.6 out of 10 which means it is in Good condition, according to the scoring system provided by the USDA visual assessment protocol. This section of the creek has no bank erosion but there was a landslide causing sediment to enter the stream.

There was a man made dam made from a sheet of metal (see photo 4) that is acting as a fish impasse and causing downstream sedimentation. Downstream there were also a few culverts along the stream, one of which was too small and squeezes the channel (see photo 5), and another allowing a tributary to pass under a road (see photo 6).



Photo 1: Landslide off hill into stream. (BSC-87)





Photo 2: A fallen tree creating a debris jam and deep pool. (BSC-89)



Photo 3: Trees that were cut and left in stream. There is also housing construction uphill. (BSC-91)





Photo 4: Here a homeowner placed a piece of metal in the stream, creating dam, but also a fish impasse and downstream sedimentation. (BSC-92)



Photo 5: Improperly sized culvert squeezing the channel. (BSC-94)



Photo 6: An incoming tributary from across the road. (BSC-96)

**Tributaries to Big Sewickley Creek**  
*(Western Tributaries)*

**BSC-T1W1 through BSC-T1W8 (poor)**

Waypoints: BSCT1W1-BSCT1W8 (Reach #5)

Segment: Tributary that travels from power lines, through trailer park, to BSC.

Date of Assessment: 6/21/07

**Sewage Impacts**

There are no visible impacts from sewage on this reach.

**Stream Bank Erosion and Siltation**

There are several areas of bank erosion and there is also a landslide under the power lines. The stream bank is eroded in areas and the bank is undercut near the trailer park (see photo 1). There is runoff, from a dirt and gravel road, entering the stream causing sedimentation. The landslide at the power lines (see photo 3) is creating heavy sedimentation in the stream, and erosion from the Economy Borough Sanitary line project (staging area) is having an impact on the headwaters of this tributary stream.

The above mentioned erosion and landslides (BSCT1W7) are causing a great deal of sediment to enter the stream. The embeddedness is greater than 40% and the water was very turbid and muddy during the initial site visit (see photo 4).

**Wetlands**

There were no wetlands observed on this stream reach.



### Invasive Plants

Japanese Knotweed was found growing on this tributary.

### Trash and Litter

There is dumping between the stream and the road (see photo 2, BSCT1W4).

### Conclusions and Recommendations

This tributary of Big Sewickley Creek received a visual assessment score of 5.3 out of 10 which means it is in Poor condition. This section of the tributary has severe bank erosion and there is a lot of sediment entering the stream. There is also an area where people have dumped their bulk trash.

The hill that the power lines are on must also be restored and preventative actions must be taken to stop landslides from happening in the future. The trash needs to be cleaned up, removed, and disposed of properly. Dump sites could be monitored by Economy Borough code enforcement.



Photo 1: Heavy sedimentation and undercut bank on the tributary. (BSC-T1W2)





Photo 2: A dump site identified along the stream. (BSC-T1W4)



Photo 3: A landslide occurring along a power line, dumping sediment into the stream. (BSC-T1W7)





Photo 4: View of the heavily silted stream water below the landslide. (BSC-T1W7)

**BSC-T2W1 through BSC-T2W2 (fair)**

Waypoints: BSCT2W1-BSCT2W2 (Reach #4)

Segment: Unnamed tributary that travels through residential area to power lines on top of hill.

Date of Assessment: 6/21/07

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

There are a few small areas of minor bank erosion, and the embeddedness is around 30%.

Wetlands

There were no wetlands observed on this stream reach.

Invasive Plants

There were no invasive species found growing along this tributary to BSC.

Trash and Litter

There is no trash along this section of the stream.

Conclusions and Recommendations

This tributary of Big Sewickley Creek received a visual assessment score of 8.6 out of 10 which means it is in Good condition, according to the scoring system provided by the USDA visual assessment protocol.



### **BSC-T3W1 through BSC-T3W7 (good)**

Waypoints: BSCT3W1-BSCT3W7 (Reach #36)

Segment: Starts at Zehnder Road and ends at the headwaters.

Date of Assessment: 5/13/08

#### Sewage Impacts

There are no visible impacts from sewage on this reach.

#### Stream Bank Erosion and Siltation

There are a few small areas of bank erosion near Hatton Lane (BSCT3W3). However, most of the streams banks are stable, the embeddedness is below 20%, and upstream there exists a healthy riparian zone (see photo 2). There is also a concrete retaining wall squeezing the tributary between the wall and the road (see photo 1, BSCT3W2).

#### Wetlands

There were no wetlands observed on this stream reach.

#### Invasive Plants

Japanese Knotweed was found growing along this tributary.

#### Trash and Litter

There is no trash along this section of the stream.

#### Conclusions and Recommendations

This tributary of BSC received a visual assessment score of 8.6 out of 10 which means it is in Good condition. This section of the tributary has some bank erosion.

The eroded stream banks at Hatton Lane could be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks.



Photo 1: Tributary along Shaffer Road squeezed by the road and a concrete retaining wall. (BSC-T3W2)



Photo 2: Upstream, this tributary has a good riparian zone. (BSC-T3W3)

### **BSC-T4W1 through BSC-T4W3 (fair)**

Waypoints: BSCT4W1-BSCT4W3 (Reach #40)

Segment: Tributary to BSC on Conway-Wallrose Road.

Date of Assessment: 5/13/08

#### *Sewage Impacts*

There are no visible impacts from sewage on this reach.

#### *Stream Bank Erosion and Siltation*

There is some bank erosion along the Conway-Wallrose Rd (see photo 1). Throughout the channel there are levels of embeddedness from 20-30%. Excess sedimentation was caused by recent construction near the Economy VFW (see photo 2).

#### *Wetlands*

There were no wetlands observed on this stream reach.

#### *Invasive Plants*

Japanese Knotweed was found growing along this stream reach.

#### *Trash and Litter*

There was some trash along the road.

#### *Conclusions and Recommendations*

This tributary of Big Sewickley Creek received a visual assessment score of 7.3 out of 10 which means it is in Fair condition. This tributary has problems with stream bank erosion, and litter. There is an opportunity to do a small streambank stabilization project with access from the Conway-Wallrose Road, just upstream of the confluence with BSC.





Photo 1: Tributary along Conway-Wallrose Road with some bank erosion near the mouth. (BSC-T4W1)



Photo 2: Culvert across Conway-Wallrose Road, leading to headwaters. Recent construction near the Economy VFW was leading to excess sedimentation in the tributary. (BSC-T4W3) (*Eastern Tributaries*)

### **BSC-T1E1 through BSC-T1E8 (good)**

Waypoints: BSCT1E1-BSCT1E8 (Reach #7)

Segment: Tributary of BSC that starts at the intersection of Big Sewickley and Turkeyfoot Roads, and ends at a small tributary flowing in from the north.

Date of Assessment: 6/29/07

#### Sewage Impacts

There are no visible impacts from sewage on this reach.

#### Stream Bank Erosion and Siltation

There is a small amount of bank erosion occurring across the street from Beadnell Drive (see photo 4, BSCT1E4). Sediment is also flowing into the stream from Beadnell Drive which is a dirt and gravel road (see photo 3). There is also a storm water outlet pipe sticking out of the bank too far, which is causing some erosion (see photo 5).

#### Wetlands

There were no wetlands observed on this stream reach.

#### Invasive Plants

Japanese Knotweed was found growing in this stream reach.

#### Trash and Litter

No trash or litter was found along this stream reach.

#### Conclusions and Recommendations

This tributary of Big Sewickley Creek received a visual assessment score of 8.6 out of 10 which means it is in Good condition. There is a dirt and gravel road and bank erosion causing sedimentation. There are a few culverts in this section which impede fish passage. An old tank is being used as a driveway culvert (see photo 1, BSCT1E3), and another culvert under Sevin Road is placed too high (see photo 6).

One recommendation for an improvement project would be to improve drainage on Beadnell Drive with cross pipes and even a broad-based dip on this low traffic route. This would break up storm water flows in order to prevent a large flush of water during storm events that has erosive force and deposits road materials and other sediments in the stream channel. Bell Acres Borough could apply for funding from the Allegheny County Conservation District through the dirt & gravel roads improvement program to address this road.





Photo 1: Here, an old tank was improperly used as a driveway culvert on a tributary that runs along Turkeyfoot Road. (BSC-T1E3)



Photo 2: A nice section of this tributary flowing through a wooded area. (BSC-T1E3)





Photo 3: Dirt and gravel from Beadnell Drive is going into the stream. (BSC-T1E4)



Photo 4: Bank erosion occurring across the road from Beadnell Drive. (BSC-T1E4)





Photo 5: Storm water outfall that is sticking out too far into the stream channel. (BSC-T1E4)



Photo 6: Culvert under Sevin Road at intersection with Turkeyfoot Road placed too high. This creates a passage fish barrier. (BSC-T1E6)

**BSC-T2E1 through BSC-T2E3 (excellent)**

Waypoints: BSCT2E1-BSCT2E3 (Reach #38)

Segment: Right Tributary to BSC starting at Camp Meeting Road and ending at the headwaters.

Date of Assessment: 5/13/08

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

There is no bank erosion and the level of stream embeddedness is under 20%.

Wetlands

There were no wetlands observed on this stream reach.

Invasive Plants

Japanese Knotweed was found growing along this stream reach.

Trash and Litter

There was no trash along this section of the stream.

Conclusions and Recommendations

This tributary of BSC received a visual assessment score of 9.2 out of 10 which means it is in Excellent condition. This is a very high score for this suburban watershed. This area should be protected.

**BSC-T3E1 through BSC-T3E7 (excellent)**

Waypoints: BSCT3E1-BSCT3E6 (Reach #34)

Segment: Tributary of BSC that starts in at a fenced pasture and ends at a fork in the stream, and runs through state game lands.

Date of Assessment: 5/1/08

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

There is very little to no bank erosion in this section, and the banks are very stable. There is low siltation and the embeddedness is less than 20%.

Wetlands

There were no wetlands observed on this stream reach.

Invasive Plants

Japanese Knotweed and Skunk Cabbage were found growing in this stream reach.

Trash and Litter

No trash or litter was found along this tributary to BSC.



### Conclusions and Recommendations

This tributary of Big Sewickley Creek received a visual assessment score of 9.3 out of 10 which means it is in Excellent condition. There is very little to no erosion or sedimentation. The only problem is a landowner encroachment with a mulch pile in the stream (see photo 1, BSCT3E2) causing some sedimentation in the stream.



Photo 1: Mulch pile and disturbed ground encroaching on tributary off of Markman Park Road. (BSC-T3E2)

## **8.0 EAST BRANCH BIG SEWICKLEY CREEK STREAM SEGMENT ANALYSES** **EF-01 through EF-07 (good)**

Waypoints: EFBSC1-EFBSC7 (Reach #17)

Segment: East Fork of the Big Sewickley Creek from the east side of BSC to a bridge.

Date of Assessment: 7/13/07 and 7/26/07

### Sewage impacts

There are no visible impacts from sewage on this reach.

### Stream bank erosion and siltation

This section of the stream did not appear to have any erosion and the banks looked stable. There was also a good riparian zone throughout the section. However, some of the section runs through a yard where there is some bank erosion because there is grass cut all the way up to the edge of the creek (see photo 1). The homeowner has also discarded some cut limbs in the creek.

There did not appear to be a lot of sedimentation, the water was very clear, and the embeddedness was low at only 20-30%. The only area with excess sedimentation was at the confluence of Rippling Run where there was a lot of debris and sedimentation (see photo 2).

Wetlands

There were no wetlands observed on this stream reach.

Invasive Plants

There were no invasive species of plants found growing along this reach of the stream.

Trash and Litter

There was no trash observed along this section.

Conclusions and Recommendations

This branch of Big Sewickley Creek received a visual assessment score of 8.2 out of 10 which means it is in Good condition.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks. Homeowners should be discouraged to mow grass up to the edge of the creek, and instead told to plant heavier vegetation there to protect the slopes of the creek bank. This is a hard sell for people that are used to keeping their properties neat and trimmed.



Photo 1: Near the mouth of East Branch Big Sewickley Creek, a homeowner has discarded cut limbs in the stream. There is also bank erosion due to the cutting of grass right up to the stream bank. (EF-05)





Photo 2: The confluence of Rippling Run with the East Branch is jammed with debris and excess sedimentation. (EF-06)

### **EF-08 through EF-24 (good)**

Waypoints: EFBSC8-EFBSC24 (Reach #18)

Segment: East Fork of the BSC from a private bridge through the state game lands to where a tributary enters the creek.

Date of Assessment: 8-14-07 and 8-28-07

#### Sewage impacts

There are no visible impacts from sewage on this reach.

#### Stream bank erosion and siltation

This section of the stream had some bank erosion however the banks were still very stable, and they had a good riparian zone. In the game lands there is some bank degradation where the bank has been trampled due to horse access to the stream (see photo 1). There was bank erosion just below the game lands border (see photo 2). A few other bank erosions occurred where tree jams were blocking the flow of water. One of these tree jams is also creating a sand bar.

The water was still very clear throughout and the embeddedness only ranged from 20-30% in this section of the stream

#### Wetlands

There was a small floodplain and wetlands area in this section of the creek.

#### Invasive Plants



There were no invasive species of plants found growing along this reach of the stream.

Trash and Litter

There was no trash spotted on this section.

Conclusions and Recommendations

This section of the East Fork of Big Sewickley Creek received a visual assessment score of 8.7 out of 10 which means it is in Good condition. This section of the stream has some locations of severe erosion and siltation (EF22).

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks. A bank stabilization project could be completed at EF22 with landowner cooperation.

There is also a culvert acting as a fish impasse under the entranceway to the state game lands (see photo 3). In the game lands there are also several small trees with beaver chew marks in them (see photo 4), and just upstream of those trees a small beaver dam can be seen (see photo 5).



Photo 1: This section of streambank has been disturbed due to horse access to the stream. (EF-13)



Photo 2: Bank erosion on a section of the East Fork just upstream of the Gamelands border. (EF-22)



Photo 3: A culvert under a State Gamelands access road acts as a fish impasse. (EF-18)





Photo 4: Sign of beaver activity near the stream. (EF-19)



Photo 5: Upstream from the beaver activity, this small dam was observed. (EF-20)



### **EF-25 through EF-27 (poor)**

Waypoints: EFBSC25-EFBSC27 (Reach #19)

Segment: East Fork of the BSC from homeowner's yards back into a wooded area.

Date of Assessment: 8-28-07

#### **Sewage impacts**

There was a plastic white pipe discharging water into the stream in this section (see photo 1). The water had a white precipitate and a noticeable odor.

#### **Stream bank erosion and siltation**

This section of the stream had some bank erosion. This could be related to the fact that there was grass that was mowed right up to the bank of the stream (see photo 1). The erosion is causing occasional cloudiness in the water and an embeddedness of 20-30%.

#### **Wetlands**

There was a small floodplain wetland approximately 50 feet by 50 feet near this section.

#### **Invasive Plants**

There were no invasive species of plants found growing along this reach of the stream.

#### **Trash and Litter**

There was no trash spotted along this section.

#### **Conclusions and Recommendations**

This section of the East Fork received a visual assessment score of 5.2 out of 10 which means it is in Poor condition.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks. The landowners in this section could be advised to plant more vegetation around the banks of the creek to create a better riparian zone, and not keep mowed grass running up to the edge of the bank.



Photo 1: A white pipe discharging fluids with white precipitate out of a front yard.  
(EF-26)

### **EF-28 through EF-33 (poor)**

Waypoints: EFBSC28-EFBSC33 (Reach #20)

Segment: East Fork of the BSC from top of watershed to woods below Interstate 79.

Date of Assessment: 8/28/07

#### Sewage impacts

There are no visible impacts from sewage on this reach.

#### Stream bank erosion and siltation

There were several areas of erosion along this section of the creek. There was an old wooden bridge that eroded out and is now causing a debris jam across the channel (see photo 1, EF29). There is also a washed out pipe crossing and a channel coming out from under I-79, which is severely eroded and contributing a high volume of sediment to the stream channel. There are also concrete slabs that were dumped in the creek creating a debris jam at EF31. The excess sediment in the water is causing occasional cloudiness and the embeddedness of the cobbles ranges from 30-40% throughout the section.

#### Wetlands

There is a small area of floodplain wetlands in this section of stream.

#### Invasive Plants

There were no invasive species of plants found growing along this reach of the stream.



### Trash and Litter

There was trash spotted on this section that appeared to be blowing down the hill from I-79.

### Conclusions and Recommendations

This section of the East Fork of BSC received a visual assessment score of 5.6 out of 10 which means it is in Poor condition. This section of the stream has severe erosion and siltation.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks. There may be opportunity to partner with the PA Department of Transportation on a project to stabilize the stream channel below the interstate highway.

The trash and litter in the area needs to properly be disposed of. It would be difficult to control the flow of litter from I-79.

There is a good area for a regional storm water basin on-stream immediately below I-79 (EF31). This would help prevent the erosion and sedimentation caused by excessive water runoff from the highway.



Photo 1: A collapsed wooden bridge creating a debris jam. (EF-29)

## **Tributaries to the East Branch Big Sewickley Creek**

### **EF-T1E1 through EF-T1E2 (good)**

Waypoints: EFT1E1-EFT1E2 (Reach #39)

Segment: Tributary of East Fork that starts off of Hopkins Church Road, and flows behind Linbrook Park until it enters the East Fork.

Date of Assessment: 5/13/08

#### **Sewage impacts**

There are no visible impacts from sewage on this reach.

#### **Stream bank erosion and siltation**

There is little to no bank erosion and the banks appear to be very stable with a good riparian zone that extends two active channel lengths away on each side of the stream. There is also very little siltation with the embeddedness ranging from 20-30% throughout the section.

#### **Wetlands**

There was small area of floodplain wetlands along this section of stream.

#### **Invasive Plants**

Japanese Knotweed and skunk cabbage were found growing along this tributary.

#### **Trash and Litter**

No trash or litter was found along this tributary.

#### **Conclusions and Recommendations**

This tributary of East Fork received a visual assessment score of 8.8 out of 10 which means it is in Good condition, according to the scoring system provided by the USDA visual assessment protocol.

### **EF-T2E1 through EF-T2E6 (excellent)**

Waypoints: EFT2E1-EFT2E6 (Reach #35)

Segment: Tributary of East Fork that starts at a small wetlands and ends at the mouth where it enters the main stem of East Fork.

Date of Assessment: 5/8/08

#### **Sewage impacts**

There are no visible impacts from sewage on this reach, except for some brown algae on the substrate in areas.

#### **Stream bank erosion and siltation**

There is little to no bank erosion and the banks appear to be very stable with a good riparian zone that extends two active channel lengths away from each side of the stream. There is also very little siltation with the embeddedness ranging from 20-30% throughout the segment.



### Wetlands

There are a few small patches of wetlands (EFT2E2) throughout the beginning of the stream.

### Invasive Plants

Japanese Knotweed and skunk cabbage grow along this tributary of East Fork.

### Trash and Litter

No trash or litter was found along this tributary of East Fork.

### Conclusions and Recommendations

This tributary of East Fork received a visual assessment score of 9 out of 10 which means it is in excellent condition. There was some brown algae observed in sections of the stream substrate which is usually caused by a high amount of nutrients in the water.

## **9.0 NORTH FORK BIG SEWICKLEY CREEK STREAM SEGMENT ANALYSES**

### **NF-01 through NF-14 (good)**

Waypoints: NFBSC1-NFBSC14 (Reach #21)

Segment: Section of the North Fork of the BSC from mouth to debris jam.

Date of Assessment: 10/4/07 and 10/9/07

### Sewage impacts

BAI observed some algal growth throughout this area of the stream that could be indicative of excess nutrients.

### Stream bank erosion and siltation

This section of the stream had a few areas of stream bank erosion. The banks are stable and there is a good riparian zone, however in some areas near homes there was some bank erosion due to grass being mowed right up to the bank. There were also several debris jams throughout this stretch of stream.

The water in the stream is very clear and the embeddedness is less than 20% for this section of the creek.

### Wetlands

There were no wetland areas observed on this stream reach.

### Invasive Plants

There were no invasive plants found growing in this reach of the stream.

### Trash and Litter

There was no trash observed in this area of the stream.

### Conclusions and Recommendations

This section of the North Branch of BSC received a visual assessment score of 8.1 out of 10 which means it is in Good condition. The homeowners along the creek could be informed of planting heavier vegetation closer to the stream bank to prevent further erosion. The

landowners are doing a good job of keeping the area clean and the stream well managed for conservation. There is a wide channel with sand bar areas off to the side, and backchannels cut out from extra flow events. The debris jam at NF06 needs to be pulled out because it is causing severe bank erosion into the edge of Hoenig Road.

### **NF-15 through NF-22 (good)**

Waypoints: NFBSC15-NFBSC22 (Reach #22)

Segment: Section of the North Fork of the BSC from tributary entering on the left to bridge.

Date of Assessment: 10/8/07 and 10/31/07

#### Sewage impacts

There are no visible impacts from sewage on this reach.

#### Stream bank erosion and siltation

This section of the stream did not have any observed stream bank erosion. The banks are stable and there is a good riparian zone. The water in the stream is clear and the embeddedness is around 20% for this segment of the stream.

#### Wetlands

There is a flooded wetland in this section of the stream near the intersection of Hoenig and Conway-Walrose Roads that is approximately 400 feet long by 500 feet wide (NF20).

#### Invasive Plants

There were no invasive plants found growing in this reach of the stream.

#### Trash and Litter

There was no trash observed in this section of the stream.

#### Conclusions and Recommendations

This section of the North Fork received a visual assessment score of 8.1 out of 10 which means it is in Good condition. The landowners in this area are doing a good job of keeping the area clean and the stream well managed for conservation.

### **NF-23 through NF-31 (good)**

Waypoints: NFBSC23-NFBSC31 (Reach #23)

Segment: Section of the North Fork from a large pond with bridge to private home to a bridge over Bradford Park Road.

Date of Assessment: 10/31/07

#### Sewage impacts

There are no visible impacts from sewage on this reach.

#### Stream bank erosion and siltation

There is not that much erosion through this section of the stream. There were several debris/tree jams throughout. The water along this stretch was clear with embeddedness of around 20%.

### Wetlands

There is a large pond located near private land at the start of this section. Downstream from the pond there were several trees that beavers have started to chew through and there were drag marks to the pond. Deer, ducks, and hawks were also spotted in this area (NF23).

### Invasive Plants

Japanese Knotweed was found growing in this reach of the stream.

### Trash and Litter

There was no trash observed in this section of the stream.

### Conclusions and Recommendations

This section of the North Fork of Big Sewickley Creek received a visual assessment score of 8.3 out of 10 which means it is in Good condition.

### **NF-32 through NF-39 (fair)**

Waypoints: NFBSC32-NFBSC39 (Reach #24)

Segment: Section of the North Fork from a wetland along sanitary line to a large pond below the Tri-County Soccer field.

Date of Assessment: 1/31/08

### Sewage impacts

There was a black algae growth of the substrate indicating high levels of nutrients in the water.

### Stream bank erosion and siltation

There is not that much erosion here because there are several areas of the stream that have been stabilized by homeowners using concrete blocks to line the banks of the creek (see photo 1, NF37). There are also a few storm water management pond outlets into this area, one of which needs more rock outlet protection (see photo 2). There is a little stream bank erosion near the outlet pipe of the large pond below the Tri-County Soccer facility.

The water along this stretch was occasionally cloudy with embeddedness of around 20%.

### Wetlands

There were no wetland areas observed along this section of the creek.

### Invasive Plants

Japanese Knotweed was found growing along this reach of the stream.

### Trash and Litter

There was a glass dump between the large pond and the outlet pipe below the Tri-County Soccer facility.



Conclusions and Recommendations

This section of the North Fork of Big Sewickley Creek received a visual assessment score of 6.5 out of 10 which means it is in Fair condition. There were a few areas with erosion and sedimentation problems along this section of the stream.

The eroded stream banks should be stabilized or stream channel restoration work could be done to direct the flow into the middle of the channel and away from the stream banks. The storm water outfall could be stabilized with additional rip-rap rock at NF38 in order to reduce erosion and sedimentation.



Photo 1: An improper attempt at bank stabilization using concrete blocks. (NF-37)



Photo 2: Storm water pond outlet from industrial park above that empties into the North Fork.  
(NF-38)

**NF-40 through NF-45 (fair)**

Waypoints: NFBSC40-NFBSC45 (Reach #25)

Segment: Section of the North Fork of the BSC from Lovi Road to below the bridge crossing.

Date of Assessment: 1/31/08

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

On this section of the stream there were a few erosion areas and some sedimentation. There was some erosion downstream of a possible old pond breach which caused some sedimentation in the channel. There is also a road cave-in (see photo 1) which is being washed into the stream when it rains and causing more sedimentation.

This excess sediment is causing occasional cloudiness throughout the stream and embeddedness around 30%.

Wetlands

There were several small wetlands and flooded areas in this section of the creek.

Invasive Plants

Japanese Knotweed was found growing along this reach of the stream.



### Trash and Litter

There was some yard waste thrown in the stream along with some litter from the road intersection.

### Conclusions and Recommendations

This section of the North Fork received a visual assessment score of 6.2 out of 10 which means it is in Fair condition. There were a few areas with erosion and sedimentation problems in this section of the stream.

The group could work with the local authority responsible for the road at NF40 to get that area stabilized and eliminate that source of sediment to the stream channel.

The trash should be cleaned up and disposed of properly, and homeowners should be discouraged from throwing yard waste into the stream. The yard waste that is in the stream needs to be removed.



Photo 1: Roadside cave-in that is causing excess sedimentation in the stream during rain events. (NF-40)

### **Tributaries to North Fork Big Sewickley Creek**

#### **NF-T1W1 through NF-T1W4 (excellent)**

Waypoints: NFT1W1-NFT1W4 (Reach #37)

Segment: Tributary to the North Fork of the BSC from headwaters to the North Fork branch.



Date of Assessment: 5/13/08

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

There were no reported areas of bank erosion or sedimentation. The banks are very stable and there is a good riparian zone. There were only a few debris jams in this section of the stream. The water is very clear and there was no algae observed on the substrate. The embeddedness was less than 20% throughout this section.

Wetlands

There were several small wetlands and flooded areas in this section of the stream.

Invasive Plants

Japanese Knotweed was found growing along this reach of the stream.

Trash and Litter

There was no trash spotted on this section.

Conclusions and Recommendations

This tributary of North Fork received a visual assessment score of 9.4 out of 10 which means it is in Excellent condition. There was no reported erosion or sedimentation in this section. This section was fine except for the occasional debris jam.

**NF-T2W1 through NF-T2W15 (fair)**

Waypoints: NFT2W1-NFT2W15 (Reach #28)

Segment: Tributary to the North Fork of the BSC from the bridge at the main road to the crossing under the road.

Date of Assessment: 3/24/08

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

There were many areas of bank erosion in this section of the stream. Many tributaries enter the stream through this section causing many bank erosion and sedimentation (see photo 1). There is an ATV crossing degrading the stream and causing a sediment deposit (see photo 2). There are a few debris jams throughout the section of the stream. There is also an on-stream pond that is silting-in (see photo 3) because of all of the excess sedimentation.

The siltation is causing the water to be occasionally cloudy with embeddedness between 30-40% throughout this section of stream.

Wetlands

There were no wetlands observed in this section of the creek.

### Invasive Plants

There were no invasive species of plants found growing along this reach of the stream.

### Trash and Litter

There was no trash spotted on this section, but there is silt fence still in place all the way down the stream valley from a sanitary line project which needs to be removed.

### Conclusions and Recommendations

This tributary of the North Fork received a visual assessment score of 6.2 out of 10 which means it is in Fair condition. There are several areas of stream bank erosion, an ATV crossing, and a pond being silted in.

ATVs should be discouraged from driving through the stream channel, but this is difficult to enforce.

The authority responsible for the sanitary line project needs to come back, take out, and collect the remaining silt fence.



Photo 1: At a tributary of the North Fork, this slope failure and bank erosion was observed. (NF-T2W7)



Photo 2: Another instance of erosion just upstream from a large gully on ATV trail. (NF- T2W8)



Photo 3: A pond along the tributary filled with excess sediment. (NF-T2W14)



**NF-T3W1 through NF-T3W3 (fair)**

Waypoints: NFT3W1-NFT3W3 (Reach #29)

Segment: Tributary to the North Fork from bridge to wetland area.

Date of Assessment: 2/7/08

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

This section of the stream had very little erosion. The streambanks are stable and there is a good riparian zone. However, there is a stream crossing culvert which is causing erosion and downcutting of the channel at NFT3W2 (see photo 1). There are ATV trails that are degrading the stream channel and banks. There is also a new bridge where mud is flowing into the stream.

The water throughout this section is occasionally cloudy and the embeddedness ranges from 20-30%.

Wetlands

There is a floodplain wetland in the right-of-way area along the stream channel.

Invasive Plants

There were no invasive species of plants found growing along this reach of the stream.

Trash and Litter

There was no trash spotted on this section.

Conclusions and Recommendations

This tributary of the North Fork received a visual assessment score of 6.3 out of 10 which means it is in Fair condition. There is no stream bank erosion reported in this area, but there are ATV crossings and a stream crossing culvert causing erosion and siltation.

ATVs should be discouraged from driving through the stream channel, but this is hard to enforce. The manmade improvements on this private property may be difficult to address because they are located on a small, headwater tributary.



Photo 1: A stream crossing culvert causing down cutting and erosion. (NF-T3W2)

**NF-T4W1 through NF-T4W5 (good)**

Waypoints: NFT4W1-NFT4W5 (Reach #27)

Segment: Tributary to the North Fork of the BSC from an erosion and sedimentation basin to the main stream.

Date of Assessment: 2/7/08

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

This section of the stream had very little to almost no erosion. The streambanks are stable and there is a good riparian zone. There are some trees that have fallen over the stream but nothing that has caused significant damage.

The water throughout this section is very clear and the embeddedness ranges from 20-30%.

Wetlands

There is a floodplain wetland immediately adjacent to the stream channel.

### Invasive Plants

There was no invasive species of plants found growing along this reach of the stream.

### Trash and Litter

There was no trash spotted on this section, but there is silt fence still in place all the way down the stream valley which needs to be removed.

### Conclusions and Recommendations

This tributary of the North Fork received a visual assessment score of 7.9 out of 10 which means it is in Good condition. There is no erosion reported in this section and the stream is in very good condition.

There is an interesting tunnel like structure that was observed in the hillside next to another stream nearby at NFT4W2 that appears to be an old coke oven (see photo 1). Also the silt fence that was left behind by construction needs to be removed.



Photo 1: An interesting structure (possible coke oven) noted alongside another tributary, in the hillside. (NF-T4W2)



### **NF-T5W1 through NF-T5W11 (good)**

Waypoints: NFT5W1-NFT5W11 (Reach #26)

Segment: Tributary to the North Fork of the BSC from the Whispering Pines development to the main stream.

Date of Assessment: 2/7/08

#### Sewage impacts

There are no visible impacts from sewage on this reach.

#### Stream bank erosion and siltation

This section of the stream has several areas where the stream bank has been eroded. One area is quite large where about 30 feet of the stream bank is eroded at NFT5W2. A storm water pipe support has eroded and needs to be fixed or replaced at NFT5W6 (see photo 2). There are several other smaller erosion areas from tributaries entering the stream, and another from an improperly sized pipe that is too small to convey the stream flow at NF-T5W7 (see photo 3).

The erosion is causing the water to be cloudy at times, and there is embeddedness in the stream of around 20-30% for this section.

#### Wetlands

There is a large, floodplain wetland near this section of the stream (see photo 1).

#### Invasive Plants

There were no invasive species of plants found growing along this reach of the stream.

#### Trash and Litter

There was no trash spotted on this section.

#### Conclusions and Recommendations

This section of the North Fork of Big Sewickley Creek received a visual assessment score of 7.9 out of 10 which means it is in Good condition, according to the scoring system provided by the USDA visual assessment protocol. There are several areas of erosion and some sedimentation in this section of the creek.

It is recommended that the storm water infrastructure be replaced/repared at NFT5W6 and W7 to improve water flow and reduce the causes of sedimentation in the stream channel.



Photo 1: Floodplain wetland area. (NF-T5W3)



Photo 2: A storm water outlet that needs reconstructed. (NF-T5W6)





Photo 3: Severe erosion around concrete pipe that is improperly sized. (NF-T5W7)



Photo 4: E&S Basin in Whispering Pines development. (NF-T5W11)



## **10.0 COONEY HOLLOW STREAM SEGMENT ANALYSIS**

Waypoints: CH01-CH03 (Reach #33)

Segment: Section of Cooney Hollow starting at the confluence with BSC and ending at the headwaters.

Date of Assessment: 5/1/08

### *Sewage impacts*

There are no visible impacts from sewage on this reach.

### *Stream bank erosion and siltation*

This section of the stream did not have many problems with bank erosion. It is a small creek that flows primarily through woods except for a small residential area (see photos 1 & 2). The banks appear to be very stable and there is a good riparian zone throughout the area.

The water is very clear and the embeddedness is less than 20%.

### *Wetlands*

No wetlands were observed in this area.

### *Invasive Plants*

Japanese Knotweed and Skunk Cabbage are growing along this reach of the stream.

### *Trash and Litter*

There was no trash observed along this area of the stream.

### *Conclusions and Recommendations*

Cooney Hollow received a visual assessment score of 8.8 out of 10 which means it is in Good condition.

Cooney Hollow runs along Cooney Hollow Road, behind a small development and through a culvert where it enters Big Sewickley Creek. The creek and surrounding area is well maintained by the land owners and the area is forested.



Photo 1: Cooney Hollow flows through the woods except for at the mouth. (CH-01)



Photo 2: Headwater area of Cooney Hollow. (CH-03)

## **11.0 RIPPLING RUN STREAM SEGMENT ANALYSES**

### **RR-01 through RR-10 (good)**

Waypoints: RR1-RR10 (Reach #30)

Segment: Section of Rippling Run starting at a storm water outlet and ending at Sechler's Lake.

Date of Assessment: 4/24/08

#### Sewage impacts

There are no visible impacts from sewage on this reach.

#### Stream bank erosion and siltation

This section of the stream did not have many problems with bank erosion. There was a small amount of bank erosion at a storm water outlet at RR02. There were a few log jams along this section also.

The water was very clear and the embeddedness was less than 20%.

#### Wetlands

There were a few small wetlands observed in this area (RR06).

#### Invasive Plants

Japanese Knotweed and Skunk Cabbage were found growing in this reach of the stream.

#### Trash and Litter

There was no trash in this area of the stream.

#### Conclusions and Recommendations

This section of Rippling Run received a visual assessment score of 8.2 out of 10 which means it is in Good condition.

There is a culvert under a homeowner's driveway that looks properly sized for Rippling Run at RR06 (see photo 1), however the inlet side is clogged with debris (see photo 2). Rippling run also flows through Sechler's Lake at RR09 as it makes its way to BSC (see photos 3 & 4). Landowner needs to maintain the inlet side of the stream crossing so as not to cause flooding and downstream erosion.





Photo 1: Culverts under a driveway that seem properly sized on Rippling Run. (RR-06)



Photo 2: However, the inlets to these culverts are jammed with debris. (RR-06)





Photo 3: Sechlers Lake, which Rippling Run flows through. (RR-09)



Photo 4: Outlet to Sechlers Pond. (RR-09)

**Tributaries to Rippling Run**  
(Eastern Tributaries)

**RR-11 through RR-13 (good)**

Waypoints: RR11-RR13 (Reach #31)

Segment: Section of Rippling Run starting at a homeowner's property and ending at the headwaters.

Date of Assessment: 5/1/08

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

This section of the stream did not have any problems with bank erosion. The banks were stable and the area had a good riparian zone. The water was also very clear with an embeddedness of around 20%.

Wetlands

There were no observed wetlands in this area.

Invasive Plants

There were no invasive species of plants found growing in this reach of the stream.

Trash and Litter

There was no trash observed along this stream reach.

Conclusions and Recommendations

This section of Rippling Run received a visual assessment score of 8.4 out of 10 which means it is in Good condition. The landowners are doing a good job of keeping the area clean and the stream well managed for conservation.

**RR-14 through RR-17 (good)**

Waypoints: RR14-RR17 (Reach #32)

Segment: Tributary to Rippling Run from houses to headwaters at wetlands.

Date of Assessment: 5/1/08

Sewage impacts

There are no visible impacts from sewage on this reach.

Stream bank erosion and siltation

This section of the stream did not have any problems with bank erosion. The banks were observed to be stable and the area had a good riparian zone. The water was also very clear with an embeddedness of less than 20%.



### Wetlands

There were a few wetland areas in this section (RR15). One area that was about half an acre by the road near the top of the stream, and another area about the same size near the confluence with the main stem of Rippling Run.

### Invasive Plants

Skunk Cabbage was found growing in this reach of the stream.

### Trash and Litter

There was no trash observed along this area of the stream.

### Conclusions and Recommendations

This tributary to Rippling Run received a visual assessment score of 8.5 out of 10 which means it is in Good condition. The landowners are doing a good job of keeping the area clean and the stream well managed for conservation.

## **12.0 CONCLUSIONS AND MANAGEMENT RECOMMENDATIONS**

The Big Sewickley Creek Watershed has many natural resource issues and opportunities. Major areas of concern and/or opportunity are outlined in the Management Recommendations section of the plan in Attachment A. A significant concern to the watershed is unmanaged storm water. Several older neighborhoods built before there were storm water management regulations are located in Leet Township, Franklin Park, Marshall Township, and Economy Borough. Flooding is occurring during severe storms along Big Sewickley Creek in the lower portions of the watershed. It appears to be caused by the cumulative effect of unmanaged flows and improper encroachment into the natural floodplain and floodway of the stream channels.

Storm water management improvements and maintenance should be a high priority for this watershed community. With increased development, streams are heavily impacted, and so are properties along the streams. It is recommended that the BSCWA sponsor a coalition of local and state entities to apply implementation funding to develop a storm water management plan for the Big Sewickley Creek Watershed. The Act 167 program has recently been cut from the state budget and is not likely to be reinstated in the near future. Other possible sources of funding could be EPA, Growing Greener, and PennVEST. Partners on this project would include PaDEP, Allegheny and Beaver Counties, municipalities, and the BSCWA. A plan needs to be developed that will set standards for managing storm water from new development according to the characteristics of the receiving subwatershed. PaDEP's Storm water Best Management Practices manual could be utilized to strengthen this effort. Current management facilities are clearly not doing the job of managing storm water and protecting downstream resources. Developers need to have more options for new innovative management techniques within the local ordinances. These ordinances would be amended based on the findings of a detailed storm water management assessment and plan. Another key component of this management strategy will be the monitoring and maintenance of existing storm water facilities. Other municipalities in the region are checking these facilities and finding that many of them are not constructed to the approved specifications and others are not maintained properly and therefore not functioning as they should. A comprehensive program, watershed-wide, on a municipal level needs to be done first to take inventory of what is out there and what needs to

be repaired, maintained, and/or retrofitted. This would be a great first step toward making progress and improvements for downstream communities in the watershed.

Area landowners need to be educated on the impacts and issues created from encroaching on the floodplains of local streams. These encroachments have caused numerous problem areas throughout the watershed, and especially in the lower portions of the main stem of Big Sewickley Creek. This would be a good project for the watershed association to tackle at a grassroots level in conjunction with the municipal governments within the watershed. Education followed by more strict enforcement of floodplain regulations at the local and state level would make a difference on this issue.

Many stream reaches in the watershed are eroded, entrenched, and braided from different causes. These areas need to be assessed in detail for the causes of impairment and then redesigned to restore them to their most natural course. Many specific reaches that are candidates for natural stream restoration are identified on the attached maps and tables. These types of projects will have lasting, measurable effects on the local communities that are worth the investment. Some open, upstream areas may be appropriate for regional storm water management basins. This management technique has been suggested and implemented in other local watersheds with some success. These facilities would lessen the volume of water being squeezed into the lower section of the watershed during large storm events.

Impacts from sewage was another issue that was investigated at a snapshot level during this assessment. Fecal coliform samples were taken at different locations across the watershed. There were a few samples that were considered high in bacteria counts. One of those areas was on the North Fork of Big Sewickley Creek. This area seems to have some issues with wildcat sewage. Further sampling and investigation needs to be conducted in this subwatershed to hone in on specific problem sources. The other areas of high bacteria levels were on the main stem of BSC. Marshall Township has completed a large sanitary service upgrade project as of October 2010 that has brought service to a long stretch of the upper reaches of BSC. This should have immediate impacts on the water quality in the main stem of BSC. There is also a small trailer park along the main stem that has a package plant treatment system. A check of the compliance of this system is in order along with some other scattered monitoring points downstream of these areas on BSC.

Several natural, open space areas are identified throughout this plan. These areas should be seriously looked at for preservation possibilities. There are several community parks, playgrounds, and ball fields in the different municipalities throughout the watershed. There are some nature park and reserve areas, but there are additional tracts of land that could be set aside for conservation easements. BSCWA could approach the owners of some of these properties to assess their future plans for their properties. A few priority areas should be looked at for preservation. Some of these include the area in and around the Campmeeting Woods BDA and the Bell Acres Nature Preserve; areas contiguous with the PA Gamelands #203; Cooney Hollow; and the western tributaries of the North Fork of Big Sewickley Creek. All of these areas are being pushed by development from the north and east. Some of these areas should be preserved in their natural state, for they act as natural buffers to development and sources of high water quality. This open space planning falls in line with a push for comprehensive land use planning. Both Allegheny and Beaver County have comprehensive plans that echo the aforementioned recommendations.

Overall, the BSCWA has a great opportunity to use this plan to continue their efforts and focus in on a few watershed improvement projects that will have lasting, measurable results on the natural resources of the watershed and the subsequent quality of life of residents and visitors to this watershed.

### **13.0 ACKNOWLEDGEMENTS**

This project was completed with the assistance of many organizations and individuals. The funding was provided by the PA Department of Environmental Protection through the Growing Greener program. A significant matching effort was supplied by members of BSCWA, Leet Township, Fern Hollow Nature Center, Western PA Conservancy, Allegheny County Conservation District (ACCD), and Beaver County Conservation District (BCCD). The Allegheny County Conservation District provided a great amount of support during the field assessments with the help of Mr. Rich Kowalski, Watershed Specialist, and during the report phase with Ms. Amy Miller, Watershed Specialist. Ms. Susan Barness, President of BSCWA, was the originator of the project and continued to push to completion. The macroinvertebrate and fish surveys, and watershed monitoring training were conducted by the Western PA Conservancy – Watershed Conservation Program, in coordination with Mr. Gary Smith, Regional Habitat Biologist with the PA Fish and Boat Commission in Somerset, PA. Blazosky Associates, Inc. (BAI) coordinated all of the field assessments and prepared the assessment and restoration plan with the oversight review of aforementioned partners.



ATTACHMENT A:  
MANAGEMENT RECOMMENDATIONS  
FOR THE WATERSHED

## Big Sewickley Creek Watershed Management Recommendations

Subwatershed	Areas of Concern & Opportunity	Proposed Projects	GIS/GPS Waypoint(s)	Municipality(s)	Priority Ranking	Cost Estimate
<b>Big Sewickley Creek</b>	severe bank erosion 6' high by 100' long	stream bank stabilization	BSC11-12	Leet & Harmony Townships	H	\$
	Blue Heron Rookery	Conservation easement to protect this area.	BSC38	Bell Acres Borough	H	\$\$
	sediment build up with backwater pools and debris jam at sanitary crossing. Sanitary line installation has caused stream changes/damage.	natural stream channel restoration	BSC48	Bell Acres & Economy Boroughs	H	\$
	on-stream wetland and pond	maintain buffer areas around this floodplain/wetland area	BSC76	Marshall Township	H	\$
	landslide on power line and heavy sedimentation in stream below	slope stabilization, stream channel restoration	BSCT1W7	Economy Borough	H	\$\$
	small 1 acre wetland	maintain buffer areas around this floodplain/wetland area	BSC 8	Leet Township	M	\$
	channel is too wide and straightened in many places	natural channel restoration	BSC20	Bell Acres & Economy Boroughs	M	\$\$
	auto parts, plastics, and flood debris along stream banks	Enforce local ordinances and environmental regulations in order to remove debris from stream	BSC31	Bell Acres Borough	M	\$
	sediment build up in middle of stream, channel too wide.	natural stream channel restoration	BSC45	Bell Acres & Economy Boroughs	M	\$\$
	large floodplain wetland 1000'x400'	maintain buffer areas around this floodplain/wetland area	BSC52	Bell Acres Borough	M	\$
	Abundance of brown/black algae	localized sampling to determine cause of algae	BSC58	Franklin Park Borough	M	\$
	dam with water fowl sign from PA Game Commission	maintain buffer areas around this floodplain/wetland area	BSC58	Franklin Park Borough	M	\$
	bank erosion/debris jam	stream bank stabilization	BSC68	Marshall Township	M	\$
	island in middle of stream constricting tributary, and a 6' high bank erosion just downstream	natural stream channel restoration/ stream bank stabilization	BSC74	Marshall Township	M	\$\$
	floodplain wetland/sinuuous channel	possible mitigation wetland construction area	BSC78	Marshall Township	M	\$\$\$
	dump site along stream	Enforce local ordinances and environmental regulations in order to remove debris from stream channel	BSCT1W4	Economy Borough	M	\$
	erosion and sedimentation from Beadnell Drive (dirt and gravel road)	Improvements to road to reduce volume of water coming down.	BSCT1E4	Bell Acres Borough	M	\$\$
	bank erosion	stream bank stabilization	BSCT3W3	Economy Borough	M	\$
	small 25'x25' wetlands	maintain buffer areas around this floodplain/wetland area	BSC61	Franklin Park Borough	L	\$
	several ATV crossings	Stabilize crossing with waterbars and rock to reduce sediment load	BSC83	Marshall Township	L	\$
	small landslide causing sedimentation and debris jams	slope stabilization, stream channel restoration	BSC87-90	Marshall Township	L	\$
	manmade dam	remove dam, restore channel	BSC92	Marshall Township	L	\$
	road washout at trailer park	stabilized stormwater outlet	BSCT1W1	Economy Borough	L	\$
homeowner encroachment, mulch pile in stream	education program: brochures, news articles, watershed newsletter, and enforcement	BSCT3E2	Marshall Township	L	\$	

Notes:

Cost Estimate: \$ = < \$25,000; \$\$ = \$25,000 - \$100,000; and \$\$\$ = > \$100,000

Priority Ranking is based on the level of impact to the watershed

## Big Sewickley Creek Watershed Management Recommendations

Subwatershed	Areas of Concern & Opportunity	Proposed Projects	GIS/GPS Waypoint(s)	Municipality(s)	Priority Ranking	Cost Estimate
<i>East Fork</i>	severe erosion caused by I-79 runoff	good sight for a regional stormwater basin on-stream below I-79	EFBSC30-31	Marshall Township	H	\$\$\$
	unstable banks through residential area	homeowner watershed education and small bank protection project	EFBSC25	Marshall Township	M	\$\$
	bank erosion and sand bar	natural channel restoration/ bank stabilization	EFBSC19	Marshall Township (in SGL 203)	L	\$
	beaver dam found in small wetland	maintain buffer areas around this floodplain/wetland area	EFBSC20	Marshall Township (in SGL 203)	L	\$
<i>North Fork</i>	Erosion and culvert not large enough to handle flows	replace culvert with larger pipe and repair streambank	NFT5W7	Economy Borough	H	\$\$
	wetland area 400'X500'	maintain buffer areas around this floodplain/wetland area	NFBSC20	Economy Borough	M	\$
	severe erosion	check soil types to find explanation for erosion/stream bank stabilization	NFT2W7-8	Economy Borough	M	\$\$
	possible coke oven on hillside	historical preservation	NFT4W2	Economy Borough	L	\$
	severe erosion	stream bank stabilization	NFT5W2	Economy Borough	L	\$\$
<i>Rippling Run</i>	Sechlers Lake area	maintain buffer areas around this floodplain/wetland area	RR9	Franklin Park Borough	H	\$\$
	a few small 1/2 acre wetland areas	maintain buffer areas around this floodplain/wetland area	RR15	Franklin Park Borough	M	\$
<i>Cooney Hollow</i>	Debris Jam	remove jam and work to maintain riparian areas.	CH2	Economy Borough	H	\$

**Notes:**

Cost Estimate: \$ = < \$25,000; \$\$ = \$25,000 - \$100,000; and \$\$\$ = > \$100,000

Priority Ranking is based on the level of impact to the watershed



ATTACHMENT B:  
FIELD ASSESSMENT WAYPOINT DATA

Big Sewickley Creek Watershed Stream Assessment Waypoints

Table with columns: WAYPOINTS, Y, X, ELEVATION FEET, DATE, NOTES, PH, COND, SECTION REACH, SCORE, SCORE2, DEBRIS JAMS, ATV IMPACTS, STREAM ENCROACHMENTS (DAMS, RETAINING WALLS, SEDIMENT BUILDUP), BANK EROSION, STORMWATER EROSION SITES, SW MANAGEMENT FACILITIES/SITES, POTENTIAL WATERSHED IMPROVEMENT PROJECT SITES, WETLANDS, SEWAGE IMPACTS, SITES OF INTEREST FOR HISTORY OR CONSERVATION, CHANNEL CONDITION, RIPARIAN ZONE, BANK STABILITY, WATER APPEARANCE, NUTRIENT ENRICHMENT, FISH BARRIERS, INSTREAM FISH COVER, EMBEDDENESS, INSECTIN VERTEBRATE HABITAT, CANOPY COVER, AMD IF APPLICABLE, SEWAGE IF APPLICABLE, MANURE PRESENT IF APPLICABLE.









ATTACHMENT C:  
MACROINVERTEBRATE AND FISH SURVEYS





## **Big Sewickley Creek Biological Assessment**

July 24 & 25, 2008

*Prepared by:*

Western Pennsylvania Conservancy  
Freshwater Conservation Program  
246 South Walnut Street  
Blairsville, PA 15717  
(724) 459-0953

Western Pennsylvania  
Conservancy



water, land, life.

# Big Sewickley Creek Biological Assessment

## **Macroinvertebrate and Fish Sampling**

### *Macroinvertebrate:*

Macroinvertebrate surveys were conducted following the benthic macroinvertebrate protocol for single habitat streams, as described in *EPA's Rapid Bioassessment Protocols for Use in Wadeable Streams and Rivers*. A sample area consisted of a 100 meter stream reach at sites previously selected by Blazosky & Associates. Two kicks were taken at each sample area using a kick net (500 micron screen). A single kick consisted of substrate disruption in front of the collection net (one square meter) for 60 seconds. Following sample collection, all specimens and sediment were transferred from the examined collection net into sample bottles and preserved with 95% alcohol. Preserved samples were delivered to the laboratory for processing and identification. Laboratory procedures followed EPA protocols. Samples were taken at nine sites within the Big Sewickley Creek watershed, site names, and descriptions are included in the individual analysis section (Page 5-20). A watershed map highlighting sample sites included with this document (Page 4). Macroinvertebrate samples were carefully examined and organisms were separated from the debris in the laboratory. The identified organisms were transferred to collection bottles and preserved with 70% alcohol. Organisms were identified to the family taxonomic level under a dissecting microscope. Quality control procedures included a qualified staff member sorting through a sub-section of the sample to check for missed organisms.

### *Fish:*

Fish surveys were conducted following the electrofishing protocol for single habitat streams described in *EPA's Rapid Bioassessment Protocols for Use in Wadeable Streams and Rivers*. A Smith-Root LR-24 Electrofisher electrofishing unit was implemented to temporarily immobilize the fish for the purpose of identification. The sample area consisted of a 200 meter stream reach at sites previously selected by Blazosky & Associates. Following sample collection, fish were identified at the end of the reach or if there was no longer any room available in the bucket to continue the collection of specimens, whichever procedure was most appropriate. Specimens were identified by Mr. Gary Smith, Southwest Regional Habitat Biologist for the Pennsylvania Fish and Boat Commission. Surveys were conducted at three sites within the Big Sewickley Creek watershed, site names and descriptions are included in the individual analysis section. A watershed map highlighting sample sites follows on page four. Only one preserved sample was collected, Site 6:NFT2W1, as representatives of the southern red-belly dace (*Phoxinus erythrogaster*).

### *Sample Period:*

Water chemistry analysis, macroinvertebrate collection, and fish surveys were conducted over two days, July 24 and 25, 2008. Follow-up sampling should occur during a similar time of year, as to reproduce the most accurate sample that reflects a similar sample set.

## **Data Analysis**


In addition to sampling the macroinvertebrates and conducting a fish survey, Western Pennsylvania Conservancy (WPC) also performed water chemistry analysis at all sampled sites. All water quality information can be found in Figure 26 (Page 21).

The following metrics were used to analyze the macroinvertebrate data for this study: (1) total number of taxa, (2) number of EPT taxa, (3) percent EPT, (4) percent Diptera, (5) Shannon Diversity Index (H), and (6) pollution tolerance index (PTI). Total number of taxa indicates the number of families present in the sample, and number of EPT taxa indicates the number of families of mayflies (Ephemeroptera), stoneflies (Plecoptera), and caddisflies (Trichoptera) present in the sample. Percent EPT to percent Diptera ratio compares the number of mayflies, stoneflies, and caddisflies to the number of true flies (Diptera). Diptera organisms are generally more tolerant of pollution than EPT organisms. An abundance of Diptera organisms indicates poorer water quality. Diversity indices are mathematical measures of species diversity in a community. The Shannon Diversity Index provides information about species richness and also takes into account the relative abundances of different species. The higher the index value, the more diverse the community. The Pollution Tolerance Index (PTI) is based on the concept of indicator organisms and tolerance levels. Indicator organisms are those organisms sensitive to water quality changes and their presence or absence indicates the condition of the water in which they live. Pollution-intolerant organisms include mayflies, stoneflies, caddisflies, riffle beetles, and water pennies. Pollution-tolerant organisms include tubifex worms, midges, pouch snails, and leeches. Figure 31 includes all of the macroinvertebrate analysis and is located on page 25.

The Fish Index of Biotic Integrity (FIBI), is an index that measures the health of a stream based on multiple attributes of the resident fish assemblage. Each site was sampled and the score is based on its deviation from reference conditions and classified as “poor,” “fair,” “good,” or “excellent.” The FIBI calculates data relating to; (1) Total number of species found, (2) Number of benthic insectivorous species, (3) Number of salmonidae and centrachidae, (4) Proportion of pollution intolerant species, (5) Proportion of pollution tolerant species, (6) Proportion of generalists, (7) Proportion of insectivorous cyprinids, (8) Number of piscivorous species, (9) Number of individuals in the sample, and (10) Proportion of species with disease, excluding blackspot. The total FIBI analysis is included on in Figure 30 (Page 24). Section two of the FIBI, identifies benthic insectivores, meaning those fish species that are located in the lowest part of the water column and feed exclusively on aquatic insects. Section three refers to the amount of fish species found at the sampled site, such as; trout, salmon, sunfish, bass, and crappies. Section four identifies the percentage of pollution intolerant individuals such as; lamprey, cutlip minnows, southern redbelly dace, hognose suckers, trout, sculpin, and walleye. Section five identifies the percentage of pollution tolerant individuals such as; the american eel, fathead minnows, pickerels, muskellunge, pike, killifish, bluegill, and sunfish. Section six, refers to the percentage of fish species that feed on whatever may be available such as, algae and insects. Section seven identifies those fish that can survive in multiple habitats or will consume multiple food sources. These generalists species include; chubs, shiners, minnows, and daces. Section eight of the FIBI metric aids in calculating the percentage of fish species that primarily feed on other types of fish. And lastly, section ten takes into account the percentage of fish species that had a disease or disfigurement other than blackspot, which is actually a parasitism caused by a turbellarian flatworms.



# Big Sewickley Creek Biological Assessment Map





**Big Sewickley Creek Biological Assessment (Macroinvertebrates)**

**Site 1: BSC 11-12** GPS: N 40.58128 W 80.21394

Site 1 is located a few blocks south of the Leet Township building and is adjacent to a recreational park. This site was only sampled for macroinvertebrates. The stream is approximately twenty feet in width and the substrate is primarily composed of gravel and sand.



Figure 1 exhibits the water chemistry analysis for this site. Site 1 had one of the four highest pH levels at 8.20 and all other measurable levels were relatively average. The water chemistry analysis summary can be found in Figure 26 (Page 21).

Figure 2 outlines the summary of the biotic metric; the analysis of the macroinvertebrates sampled. The Shannon Diversity Index (H) resulted in a score of 1.58649. Shannon Diversity indicated that this site had an average rank, meaning that this site had an average richness and relative abundance of macroinvertebrate species. The Pollution Tolerance Index (PTI) resulted in an “excellent” ranking.

Figure 1

**Big Sewickley Creek Watershed: Site Specific Water Quality Data**

Ph	TDS (ppm)	DO (mg/L)	Conductivity (uS)	Temp (F)	Turbidity (Fau)	Phos (Mg/L)	Nitra (Mg/L)
8.20	420	6.92	650	70.9	7	1.07	0.8

Figure 2

**Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis**

<b>Richness</b>	13
<b>Evenness (E)</b>	0.6.185
<b>Shannon Diversity (H)</b>	1.58649
<b>Hilsenhoff (B)</b>	4.83
<b>Hilsenhoff Rank</b>	Good
<b>% Ephemeroptera</b>	10.77
<b>% Plecoptera</b>	0
<b>% Trichoptera</b>	35
<b>% EPT</b>	45
<b>% Chironomidae</b>	39
<b># Intolerant Taxa(0,1,2)</b>	0
<b>PTI</b>	26
<b>PTI Rank</b>	Excellent

## ***Big Sewickley Creek Biological Assessment (Macroinvertebrates and Fish)***

**Site 2: BSC 13-14** GPS: N 40.58500 W 80.21097



Site 2 is located a few blocks south of the Leet Township building off of Neely Street, bordered by a residential area. This site was sampled for macroinvertebrates and a fish survey was also conducted. The stream is approximately twenty feet in width and the substrate is composed of cobble, gravel, sand, and some exposed bedrock.

Figure 3 (Page7) exhibits the water chemistry analysis. This site resulted in the highest phosphate level. Otherwise, the site ranked relatively average compared to other sites. The water chemistry analysis summary can be found in Figure 26 (Page 21).

The following Figures; 4 (Page 7), 5 and 6 (Page 8) outline summaries of biotic metrics, the analysis of the macroinvertebrates, abundance and the proportion of fish species sampled, and the Fish Index of Biotic Integrity (FIBI).

Figure 4 (Page 7) lists the metrics that the macroinvertebrates were measured against. The Shannon Diversity Index (H) resulted in a score of 1.45596 Shannon Diversity indicated that this site had an average rank, meaning that this site had an average richness and relative abundance of macroinvertebrate species. The Pollution Tolerance Index (PTI) resulted in a “fair” ranking.

Site 2 is the first site where a fish survey was conducted. The data from the survey resulted in the highest count of species, 14 of the 20 species, found at the three sites. This site also resulted in the largest amount of individuals identified (491 of the 766). Thus, Site 2 composed 64% of the total individuals identified in the watershed. Six of the 14 species identified at Site 2 contained five or fewer individuals collected in the sample. This group consisted of 42.8% of all species found on site and 2.8% of all individuals on site. Eight of the 14 species collected included eight or greater individuals collected at Site 2. This group consisted of 57.1% of the species sampled on site and 97.4% of the individuals sampled at Site 2. Figure 5 (Page7) reflects the fish species and their abundance at this site.

It is important to note that some of the fish species were relatively atypical for the watershed. One of these atypical species is the rainbow trout (*Oncorhynchus mykiss*), which its presence would signify a spring stocked hatchery fish. Additionally, four other species that were surveyed in very low quantities and were atypical for this watershed were the; freshwater drum (*Aplodinotus grunniens*), golden redhorse (*Moxostoma erythrurum*), shorthead redhorse (*Moxostoma macrolepidotum*) and the walleye (*Sander vitreus*). The previously listed four species most likely migrated upstream from the nearby Ohio River.



Species that were predominately found at this site included the central stoneroller (*Campostoma anomalum*), Illustration 1, which composed 40.3% of the individuals found at the site and 198 individuals. The second species was the rainbow darter (*Etheostoma caeruleum*), Illustration 2, which composed 54.17% of the sample and included 68 individuals.

Illustration 1 Central Stoneroller (*Campostoma anomalum*)



Species composition and abundance is directly impacted by the variation and availability of habitat found at the sample site. The riffle zone found at this location was nearly balanced with the pool zone. The pool zone was also equally divided into a more shallow and a deeper section. This provided habitat niches for the variety of species surveyed. These sites were notably residential and lacked a riparian buffer, but did have tree canopy cover.

Illustration 2 Rainbow Darter (*Etheostoma caeruleum*)



This site's FIBI (Fish Index of Biotic Integrity) resulted in a score of 42, which ranks the site as "good." Figure 6 showing this data is listed at the Site 2 summary (Page 8).

Figure 3

**Big Sewickley Creek Watershed: Site Specific Water Quality Data**

Ph	TDS (ppm)	DO (mg/L)	Conductivity (uS)	Temp (F)	Turbidity (Fau)	Phos (Mg/L)	Nitra (Mg/L)
8.10	410	8.02	630	70.0	8	1.37	2.2

Figure 4

**Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis**

Richness	11
Evenness (E)	0.6072
Shannon Diversity (H)	1.45596
Hilsenhoff (B)	4.64
Hilsenhoff Rank	Good
% Ephemeroptera	16.66
% Plecoptera	0
% Trichoptera	48
% EPT	65
% Chironomidae	25
# Intolerant Taxa(0,1,2)	1
PTI	12
PTI Rank	Fair

Figure 5




Figure 6

Fish Index of Biotic Integrity (FIBI) for Big Sewickley Creek: BSC 13-14		
<b>Species Richness &amp; Composition</b>		
1	Total number of species found	5
2	Number of benthic insectivorous species	5
3	Number of trout and sunfish species	1
4	Number of intolerant species	5
5	Proportion of tolerant individuals	4.48%
<b>Trophic Composition</b>		
6	Proportion of generalists	4.48%
7	Proportion of insectivorous cyprinids	41.95%
8	Proportion as trout or piscivores	5.49%
<b>Fish Abundance &amp; Condition</b>		
9	Number of individuals in the sample	491
10	Proportion with disease (excluding blackspot)	0
<b>Pollution Tolerance Index Results</b>		<b>42 Good</b>

**Big Sewickley Creek Biological Assessment (Macroinvertebrates)**

**Site 3: BSCT1W 4-5** GPS: N 40.59972 W 80.20001

Site 3 is located near a State Game Lands, parallel to a gravel road, and located at a lower elevation from a sewage treatment facility. This site was only sampled for macroinvertebrates. The stream is approximately six feet in width and the substrate is composed of gravel and silt.



Figure 7 exhibits the water chemistry analysis. This site had one of the four highest pH levels at 8.20 and the highest turbidity level. However, this site also had the lowest recorded water temperature at 65.6 degrees Fahrenheit. It must also be noted that this site was one of three sites with the lowest reading of nitrates. The water chemistry analysis summary can be found in Figure 26 (Page 21).

Figure 8 lists the metrics that the macroinvertebrates were measured against. The Shannon Diversity Index (H) resulted in a score of 0.41605. This site scored the lowest on the Shannon Diversity Index, showing this site had the lowest richness and relative abundance of macroinvertebrate species. Pollution Tolerance Index (PTI) resulted in a “poor” ranking.

Figure 7

**Big Sewickley Creek Watershed: Site Specific Water Quality Data**

Ph	TDS (ppm)	DO (mg/L)	Conductivity (uS)	Temp (F)	Turbidity (Fau)	Phos (Mg/L)	Nitra (Mg/L)
8.20	460	8.40	720	65.6	31	0.15	0.0

Figure 8

**Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis**

<b>Richness</b>	11
<b>Evenness (E)</b>	0.1735
<b>Shannon Diversity (H)</b>	0.41605
<b>Hilsenhoff (B)</b>	4.00
<b>Hilsenhoff Rank</b>	Very Good
<b>% Ephemeroptera</b>	2.00
<b>% Plecoptera</b>	0
<b>% Trichoptera</b>	2
<b>% EPT</b>	4
<b>% Chironomidae</b>	1
<b># Intolerant Taxa(0,1,2)</b>	0
<b>PTI</b>	10
<b>PTI Rank</b>	Poor



## Big Sewickley Creek Biological Assessment (Macroinvertebrates and Fish)

**Site 4:** BSCT1E 3-4 GPS: N 40.59332 W 80.18881

Site 4 is located on Turkeyfoot Road through the intersection at Wine Concrete Products. The site is composed of a narrow stream with few pools and steep banks. This site was sampled for macroinvertebrates and the where the second fish survey was conducted. The stream is approximately four feet in width and the substrate is composed of cobble and gravel.




Figure 9 (Page 11) exhibits the water chemistry analysis. This site demonstrated one of the four highest pH levels at 8.20. Conversely, this site also resulted in one of the four lowest readings of turbidity. The water chemistry analysis summary can be found in Figure 26 (Page 21).


The following Figures; 10 (Page 11) and 11 and 12 (Page 12) outline summaries of biotic metrics; the analysis of the macroinvertebrates, abundance, and the proportion of fish species sampled, and the Fish Index of Biotic Integrity (FIBI).

Figure 10 (Page 11) lists the metrics that the macroinvertebrates were measured against. The Shannon Diversity Index (H) resulted in a score of 1.45037. Shannon Diversity indicated that this site had an average rank, meaning that this site had an average richness and relative abundance of macroinvertebrate species. Pollution Tolerance Index (PTI) resulted in a “good” ranking.

The second fish survey conducted at Site 4 resulted in the lowest amount of species found, two of the 20 species identified within the watershed. Site 4 resulted in only 10% of total species assemblage found in the watershed. Also, The smallest quantities of individuals were surveyed at this site, which resulted in only 12% of the total sample (92 of the 766).

The only two species that were surveyed at this site were the blacknose dace (*Rhinichthys atratulus*), Illustration 3, and the creek chub (*Semotilus atromaculatus*), Illustration 4. These species were found in nearly equal quantities; creek chub (52.17% of the sample and 48 individuals) and the blacknose dace (47.82% of the sample and 44 individuals). Figure 11 (Page 12) reflects the fish species and their abundance at this site.

Illustration 3 Blacknose Dace (*Rhinichthys atratulus*)



This site’s habitat was relatively even with shallow riffles, with the exception of two small pools. This site was adjacent to a dirt and gravel road and within a forested area and had ample tree canopy cover.

Illustration 4 Creek Chub (*Semotilus atromaculatus*)



This site’s FIBI (Fish Index of Biotic Integrity) resulted in a score of 28, which ranks the site as “poor.” The table showing this data, Figure 12, can be found on (Page 11).

Figure 9

**Big Sewickley Creek Watershed: Site Specific Water Quality Data**

<b>Ph</b>	<b>TDS (ppm)</b>	<b>DO (mg/L)</b>	<b>Conductivity (uS)</b>	<b>Temp (F)</b>	<b>Turbidity (Fau)</b>	<b>Phos (Mg/L)</b>	<b>Nitra (Mg/L)</b>
8.20	500	8.01	760	67.8	0	0.25	0.1

Figure 10

**Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis**

<b>Richness</b>	13
<b>Evenness (E)</b>	0.5655
<b>Shannon Diversity (H)</b>	1.45037
<b>Hilsenhoff (B)</b>	4.28
<b>Hilsenhoff Rank</b>	Very Good
<b>% Ephemeroptera</b>	3.65
<b>% Plecoptera</b>	2
<b>% Trichoptera</b>	5
<b>% EPT</b>	11
<b>% Chironomidae</b>	17
<b># Intolerant Taxa(0,1,2)</b>	1
<b>PTI</b>	18
<b>PTI Rank</b>	Good

Figure 11




Figure 12

<b>Fish Index of Biotic Integrity (FIBI) for Big Sewickley Creek: BS CT1E 3-4</b>		
<b>Species Richness &amp; Composition</b>		
1	Total number of species found	1
2	Number of benthic insectivorous species	1
3	Number of trout and sunfish species	1
4	Number of intolerant species	1
5	Proportion of tolerant individuals	0%
<b>Trophic Composition</b>		
6	Proportion of generalists	0%
7	Proportion of insectivorous cyprinids	52.17%
8	Proportion as trout or piscivores	0%
<b>Fish Abundance &amp; Condition</b>		
9	Number of individuals in the sample	92
10	Proportion with disease (excluding blackspot)	0
<b>Pollution Tolerance Index Results</b>		<b>28 Poor</b>



## ***Big Sewickley Creek Biological Assessment (Macroinvertebrates)***

**Site 5: BSC 38** GPS: N 40.60052 W 80.18775



Site 5 is located upstream of Hanson and a sewage treatment facility. This site was only sampled for macroinvertebrates. The stream is approximately 35 feet in width and the substrate is composed of cobbles, boulders, and gravel.

Figure 13 (Page 14) exhibits the water chemistry analysis. This site had one of the four highest pH levels at 8.20. Conversely, this site demonstrated the highest dissolved oxygen, one of the four lowest turbidity readings, and one of the three lowest nitrate readings. The water chemistry analysis summary can be found in Figure 26 (Page 21).

Figure 14 (Page 14) lists the metrics that the macroinvertebrates were measured against. The Shannon Diversity Index (H) resulted in a score of 0.41605. Shannon Diversity indicated that this site had an average rank, meaning that this site had an average richness and relative abundance of macroinvertebrate species. Pollution Tolerance Index (PTI) resulted in a “fair” ranking. Figure 14 lists details the macroinvertebrate assessment (Page 14).

Figure 13

**Big Sewickley Creek Watershed: Site Specific Water Quality Data**

<b>Ph</b>	<b>TDS (ppm)</b>	<b>DO (mg/L)</b>	<b>Conductivity (uS)</b>	<b>Temp (F)</b>	<b>Turbidity (Fau)</b>	<b>Phos (Mg/L)</b>	<b>Nitra (Mg/L)</b>
8.20	410	9.04	630	71.4	0	0.38	0.0

Figure 14

**Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis**

<b>Richness</b>	12
<b>Evenness (E)</b>	0.7
<b>Shannon Diversity (H)</b>	0.41605
<b>Hilsenhoff (B)</b>	4.083
<b>Hilsenhoff Rank</b>	Very Good
<b>% Ephemeroptera</b>	6.00
<b>% Plecoptera</b>	2
<b>% Trichoptera</b>	56
<b>% EPT</b>	64
<b>% Chironomidae</b>	25
<b># Intolerant Taxa(0,1,2)</b>	3
<b>PTI</b>	15
<b>PTI Rank</b>	Fair

## ***Big Sewickley Creek Biological Assessment (Macroinvertebrates and Fish)***

**Site 6: NFT2W1** GPS: N 40.63084 W 80.12098



Site 6 is located off the Hoeng Road, through an open grassy field which is adjacent to a home. The stream is narrow and well vegetated. This site was sampled for macroinvertebrates and the third and final fish survey was conducted. The stream is approximately six and a half feet in width and the substrate is composed of gravel and cobble.

Figure 15 (Page16) exhibits the water chemistry analysis. This site demonstrated one of the two lowest pH levels at 7.80, one of the two lowest total dissolved solids (TDS) levels at 320ppm, and did not register any phosphates or nitrates. However, this site also had the lowest dissolved oxygen and the highest water temperature at 74.5 degrees Fahrenheit. Site 6 possessed the best water quality readings overall, of the nine sampled sites in the Big Sewickley Watershed assessment. The water chemistry analysis summary can be found in Figure 26 (Page 21).

The following Figures; 16 (Page 16), 17 and 18(Page 17) outline summaries of biotic metrics; the analysis of the macroinvertebrates, abundance and the proportion of fish species sampled, and the Fish Index of Biotic Integrity (FIBI).

Figure 16 (Page16) lists the metrics that the macroinvertebrates were measured against. The Shannon Diversity Index (H) resulted in a score of 2.07291. This site scored the highest on the Shannon Diversity Index, showing this site had the highest richness and relative abundance of macroinvertebrates. Pollution Tolerance Index (PTI) resulted in a “good” ranking.

The data from the Site 6 survey resulted in the neither the highest nor the lowest count of species for the three fish survey sites. This site yielded 11 of the 20 species found in the watershed. Site 6 composed 23.89% of total sampled individuals (183 of the 766). Five of the 14 species identified included five or less individuals collected in the sample, 25% of the total species found, and 1.8% of all the individuals surveyed. Six of the 14 species identified comprised six or greater individuals collected, 22% of all of the species sampled, and 22% of all the individuals surveyed. Figure 17 on (Page 17) reflects the fish species and their abundance at this site.



Chart 1 Pennsylvania Range of the Southern Redbelly Dace

It is important to note that one atypical fish species, the southern redbelly dace (*Phoxinus erythrogaster*), was identified at this site, Illustration 5. This is an atypical sampling since this species is found in low levels of abundance throughout the state. The southern redbelly dace is a temperate freshwater fish found in spring-fed headwater creeks. Southern redbelly daces are found throughout North America, but are found in isolated communities in Pennsylvania, see Chart 1. Current records show southern redbelly daces occurring in three Pennsylvania counties.



This species is listed as threatened, through the Pennsylvania Natural Heritage Index and is considered “Critically Imperiled” on a national level. A sample specimen was collected by Mr. Gary Smith as a representative species.

Illustration 5 Southern Redbelly Dace (*Phoxinus erythrogaster*) Photo: WPC Field Survey



The species that were predominately found at this site were the creek chub (*Semotilus atromaculatus*), see Illustration 4 (Page 10), which composed 22.9% of the individuals found at the site and 42 individuals. The second species was the mottled sculpin (*Cottus bairdi*), Illustration 5. Mottled sculpins composed 51.36% of the sample and contained individuals and generated 74.3% of the total sample.

Illustration 6 Mottled Sculpin (*Cottus bairdi*)



The habitat at this site was composed primarily riffle zones and a few pools. This site had a well defined riparian vegetated buffer next to an open grassy field adjacent to a home. However, this site was located downstream of a housing development. This site’s FIBI (Fish Index of Biotic Integrity) resulted in a score of 35, which ranks the site as “fair.” The Figure showing this data can be found on page 16.

Figure 15

**Big Sewickley Creek Watershed: Site Specific Water Quality Data**

Ph	TDS (ppm)	DO (mg/L)	Conductivity (uS)	Temp (F)	Turbidity (Fau)	Phos (Mg/L)	Nitra (Mg/L)
7.80	320	6.82	480	74.5	16	0	0.0

Figure 16

**Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis**

<b>Richness</b>	17
<b>Evenness (E)</b>	0.7316
<b>Shannon Diversity (H)</b>	2.07291
<b>Hilsenhoff (B)</b>	3.73
<b>Hilsenhoff Rank</b>	Very Good
<b>% Ephemeroptera</b>	18.00
<b>% Plecoptera</b>	23
<b>% Trichoptera</b>	19
<b>% EPT</b>	60
<b>% Chironomidae</b>	27
<b># Intolerant Taxa(0,1,2)</b>	4
<b>PTI</b>	18
<b>PTI Rank</b>	Good

Figure 17




Figure 18

<b>Fish Index of Biotic Integrity (FIBI) for Big Sewickley Creek: NFT2W 1</b>		
<b>Species Richness &amp; Composition</b>		
1	Total number of species found	3
2	Number of benthic insectivorous species	5
3	Number of trout and sunfish species	1
4	Number of intolerant species	5
5	Proportion of tolerant individuals	3.82%
<b>Trophic Composition</b>		
6	Proportion of generalists	3.82%
7	Proportion of insectivorous cyprinids	24.59%
8	Proportion as trout or piscivores	0%
<b>Fish Abundance &amp; Condition</b>		
9	Number of individuals in the sample	183
10	Proportion with disease (excluding blackspot)	0
<b>Pollution Tolerance Index Results</b>		<b>35 Fair</b>

**Big Sewickley Creek Biological Assessment (Macroinvertebrates)**

**Site 7: BSCT3E3** GPS: N 40.62559 W 80.10851

Site 7 is located north off Markman Park Road and was accessed through trails within a State Game Land. This site was only sampled for macroinvertebrates. The stream is approximately ten feet in width and the substrate is composed of silt and gravel.



Figure 19 exhibits the water chemistry analysis. This site had the lowest level of conductivity and one of the four lowest levels of turbidity. The water chemistry analysis summary can be found in Figure 26 (Page 21).

Figure 20 lists the metrics that the macroinvertebrates were measured against. The Shannon Diversity Index (H) resulted in a score of 1.92131. Shannon Diversity indicated that this site had an average rank, meaning that this site had an average richness and relative abundance of macroinvertebrate species. Pollution Tolerance Index (PTI) resulted in a “fair” ranking.

Figure 19

**Big Sewickley Creek Watershed: Site Specific Water Quality Data**

Ph	TDS (ppm)	DO (mg/L)	Conductivity (uS)	Temp (F)	Turbidity (Fau)	Phos (Mg/L)	Nitra (Mg/L)
8.00	400	8.10	610	66.4	0	0.04	0.9

Figure 20

**Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis**

<b>Richness</b>	20
<b>Evenness (E)</b>	0.6414
<b>Shannon Diversity (H)</b>	1.92131
<b>Hilsenhoff (B)</b>	5.00
<b>Hilsenhoff Rank</b>	Good
<b>% Ephemeroptera</b>	1.33
<b>% Plecoptera</b>	1
<b>% Trichoptera</b>	7
<b>% EPT</b>	9
<b>% Chironomidae</b>	18
<b># Intolerant Taxa(0,1,2)</b>	3
<b>PTI</b>	17
<b>PTI Rank</b>	Fair



**Big Sewickley Creek Biological Assessment (Macroinvertebrates)**

**Site 8:** EF 29-30 GPS: N 40.62559 W 80.10851



Site 8 is located adjacent to a State Game Land’s access area and is parallel to Interstate 79. This site was only sampled for macroinvertebrates. The stream is approximately eight feet in width and the substrate is composed of cobble, gravel, and silt.

Figure 21 exhibits the water chemistry analysis. This site had one of the two lowest pH levels of 7.80. Conversely, this site also has the highest levels of; total dissolved solids, conductivity, and nitrates. The water chemistry analysis summary can be found in Figure 26 (Page 21).

Figure 22 lists the metrics that the macroinvertebrates were measured against. The Shannon Diversity Index (H) resulted in a score of 1.14577. Shannon Diversity indicated that this site had an average rank, meaning that this site had an average richness and relative abundance of macroinvertebrate species. Pollution Tolerance Index (PTI) resulted in a ranking of “fair.”

Figure 21

**Big Sewickley Creek Watershed: Site Specific Water Quality Data**

Ph	TDS (ppm)	DO (mg/L)	Conductivity (uS)	Temp (F)	Turbidity (Fau)	Phos (Mg/L)	Nitra (Mg/L)
7.80	690	7.95	1090	71.0	7	0.12	3.3


Figure 22

**Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis**

<b>Richness</b>	14
<b>Evenness (E)</b>	0.4342
<b>Shannon Diversity (H)</b>	1.14577
<b>Hilsenhoff (B)</b>	5.56
<b>Hilsenhoff Rank</b>	Fair
<b>% Ephemeroptera</b>	2
<b>% Plecoptera</b>	0
<b>% Trichoptera</b>	15
<b>% EPT</b>	17
<b>% Chironomidae</b>	71
<b># Intolerant Taxa(0,1,2)</b>	1
<b>PTI</b>	17
<b>PTI Rank</b>	Fair

**Big Sewickley Creek Biological Assessment (Macroinvertebrates)**

**Site 9: BSC 70** GPS: N 40.63406 W 80.18188



Site 9 is located prior to the bridge on Warrendale-Bayne Road, through an open weedy field. The stream consisted of mostly riffles and some pools, adjacent to a few residences. This site was only sampled for macroinvertebrates. The stream is approximately eight feet in width and the substrate is composed of gravel and silt.

Figure 23 exhibits the water chemistry analysis. This site had one of the two lowest recorded levels for total dissolved solids (TDS) and one of the four lowest turbidity levels. The water chemistry analysis summary can be found in Figure 26 (Page 21).

Figure 24 lists the metrics that the macroinvertebrates were measured against. The Shannon Diversity Index (H) resulted in a score of 1.57764. Shannon Diversity indicated that this site had an average rank, meaning that this site had an average richness and relative abundance of macroinvertebrate species. Pollution Tolerance Index (PTI) resulted in a “fair” ranking.

Figure 23

**Big Sewickley Creek Watershed: Site Specific Water Quality Data**

Ph	TDS (ppm)	DO (mg/L)	Conductivity (uS)	Temp (F)	Turbidity (Fau)	Phos (Mg/L)	Nitra (Mg/L)
7.90	320	8.26	490	67.4	0	0.03	1.7

Figure 24

**Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis**

<b>Richness</b>	10
<b>Evenness (E)</b>	0.6852
<b>Shannon Diversity (H)</b>	1.57764
<b>Hilsenhoff (B)</b>	5.41
<b>Hilsenhoff Rank</b>	Good
<b>% Ephemeroptera</b>	0.66
<b>% Plecoptera</b>	0
<b>% Trichoptera</b>	26
<b>% EPT</b>	27
<b>% Chironomidae</b>	45
<b># Intolerant Taxa(0,1,2)</b>	1
<b>PTI</b>	11
<b>PTI Rank</b>	Fair

# Big Sewickley Creek Biological Assessment

## Conclusion

The review of all biological assessment metrics showed the following ranking of the sites; 6, 4, 1, 7, 8, 2, 5, 9, and 3. The adjacent chart outlines the preceding ranking.

Macroinvertebrate sampling conducted at all nine sites within the Big Sewickley watershed resulted in an average Pollution Tolerance Index (PTI) rank of 15.11, which ranks the sites sampled within the watershed as a “fair.”

The electrofishing survey of three, of the nine sites, within the Big Sewickley watershed resulted in the identification of 20 separate species of fish, with 766 individuals being sampled. Overall, the

Fish Index of Biotic Integrity (FIBI) score is a 39, which ranks the watershed as a “good.” Figure 30 lists all FIBI data pertaining to the three sample sites (Page 24).

The water chemistry analysis showed a somewhat similar ranking as the biological assessment ranking as; Site 6, 5, 9, 7, 3, 4, 1, 2, and 8.

Figure 25




Figure 26

Site #	Site ID	Ph	TDS (ppm)	DO (mg/L)	Conduct (uS)	Temp (F)	Turbidity (Fau)	Phos (Mg/L)	Nitra (Mg/L)
1	BSC11-12	8.2	420	6.92	650	70.9	7	1.07	0.8
2	BSC 13-14	8.1	410	8.02	630	70.0	8	1.37	2.2
3	BSCT1W 4-5	8.2	460	8.4	720	65.6	31	0.15	0
4	BSCT1E 3-4	8.2	500	8.01	760	67.8	0	0.25	0.1
5	BSC 38	8.2	410	9.04	630	71.4	0	0.38	0
6	NFT2W1	7.8	320	6.82	480	74.5	16	0.00	0
7	BSCT3E3	8.0	400	8.1	610	66.4	0	0.04	0.9
8	EF 29-30	7.8	690	7.95	1090	71.0	7	0.12	3.3
9	BSC 70	7.9	320	8.26	490	67.4	0	0.03	1.7

All three metrics of assessment resulted in the highest ranking within the watershed for Site 6 NFT2W1. This may be due to the heavily vegetated riparian buffer and a reduced residential impact. The other sites may have ranked lower to due to; reduced riparian buffers, roadway runoff, stormwater management issues, or residential impacts.



Figure 27




Figure 28

*Big Sewickley Watershed: Majority (87%) of Fish Species Surveyed*

Fish Species	Percentage Composition
Central Stoneroller ( <i>Catostomus anomalum</i> )	27%
Mottled Sculpin ( <i>Cottus bairdi</i> )	18%
Creek Chub ( <i>Semotilus atromaculatus</i> )	12%
Rainbow Darter ( <i>Etheostoma caeruleum</i> )	9%
Blacknose Dace ( <i>Rhinichthys atratulus</i> )	7%
Green-Sided Darter ( <i>Etheostoma blennioides</i> )	7%
Northern Hognose Sucker ( <i>Hypentelium nigricans</i> )	7%

Figure 29

**Total Fish Species Surveyed at 3 Sites in Big Sewickley Creek Watershed**

<b>Species</b>	<b>Scientific Name</b>	<b>Total Found</b>
Blacknose Dace	<i>Rhinichthys atratulus</i>	55
Bluntnose Minnow	<i>Pimephales notatus</i>	2
Central Stoneroller	<i>Campostoma anomalum</i>	203
Creek Chub	<i>Semotilus atromaculatus</i>	90
Freshwater Drum	<i>Aplodinotus grunniens</i>	1
Golden Redhorse	<i>Moxostoma erythrurum</i>	4
Green-Sided Darter	<i>Etheostoma blennioides</i>	56
Johnny Darter	<i>Etheostoma nigrum</i>	2
Logperch	<i>Percina caprodes</i>	1
Longnose Dace	<i>Rhinichthys cataractae</i>	9
Mottled Sculpin	<i>Cottus bairdi</i>	140
Northern Hognose Sucker	<i>Hypentelium nigricans</i>	57
Rainbow Darter	<i>Etheostoma caeruleum</i>	68
Rainbow Trout	<i>Oncorhynchus mykiss</i>	3
Red-Sided Dace	<i>Clintostomus elongatus</i>	3
Shorthead Redhorse	<i>Moxostoma macrolepidotum</i>	4
Silverjaw Minnow	<i>Ericymba buccata</i>	1
Small Mouth Bass	<i>Micropterus dolomieu</i>	22
Southern Redbelly Dace	<i>Phoxinus erythrogaster</i>	15
Walleye	<i>Sander vitreus</i>	1
White Sucker	<i>Catostomus commersoni</i>	29
<b>Total Individuals Identified During Survey</b>		<b>766</b>

Figure 30

**FIBI Data: Individual Sites & Big Sewickley Creek Total Data**

	<b>Site 1 BSC13-14</b>	<b>Site2 BSCT 1E 3-4</b>	<b>Site 3 NFT 2W1</b>	<b>BS WS Total</b>
<b>Species Richness &amp; Composition</b>				
Total number of species found	5	1	3	5
Number of benthic insectivorous species	5	1	5	5
Number of trout and sunfish species	1	1	1	1
Number of intolerant species	5	1	5	5
Proportion of tolerant individuals	5	5	5	5
<b>Trophic Composition</b>				
Proportion of generalists	5	5	5	5
Proportion of insectivorous cyprinids	3	5	3	0
Proportion as trout or piscivores	3	1	1	3
<b>Fish Abundance &amp; Condition</b>				
Number of individuals in the sample	5	3	3	5
Proportion with disease (excluding blackspot)	5	5	5	5
<b>IBI Score</b>	<b>42</b>	<b>28</b>	<b>35</b>	<b>39</b>
	<b>Good</b>	<b>Poor</b>	<b>Fair</b>	<b>Good</b>

Condition Categories for FIBI Classifications

<b>Excellent</b>	<b>45-50</b>	Comparable to the best situations with minimal human disturbance; all regionally expected species for the habitat and the stream size; most intolerant forms are present and there is a balanced trophic structure
<b>Good</b>	<b>37-44</b>	Species richness below expectation, especially due to the loss of some tolerant species; some species present with less than optimal abundances or size distributions; trophic structure show some signs of stress (increasing frequency of generalists and tolerant species)
<b>Fair</b>	<b>29-36</b>	Signs of additional deterioration include fewer species, loss of most tolerant species, highly skewed trophic structure (high frequency of generalists and tolerant species); older age classes of trout and/or top carnivores may be rare
<b>Poor</b>	<b>10-28</b>	Low species richness, dominated by generalists and tolerant species, few (if any) trout or top carnivores, individuals may show signs of disease or parasites and the site may have an overall low abundance of fish.



Figure 31

<b>Big Sewickley Creek Watershed Assessment: Macroinvertebrate Analysis</b>						
Site ID	Richness	Evenness (E)	Shannon Diversity (H)	% EPT	PTI	PTI Rank
<b>BSC11- 12</b>	12	0.6221	1.5459	46	26	Excellent
<b>BSC 13-14</b>	10	0.6141	1.4141	66	12	Fair
<b>BSCT1W 4-5</b>	9	0.1626	0.3572	4	10	Poor
<b>BSCT1E 3-4</b>	12	0.5766	1.4328	11	18	Good
<b>BSC 38</b>	12	0.7000	1.7396	64	15	Fair
<b>NFT2W1</b>	15	0.7536	2.0408	61	18	Good
<b>BSCT3E3</b>	17	0.6164	1.7463	12	17	Fair
<b>EF 29-30</b>	13	0.4395	1.1271	17	17	Fair
<b>BSC 70</b>	10	0.6852	1.5776	27	11	Poor

Figure 32

**Big Sewickley Creek Watershed Assessment: Site Locations and Descriptions**

	<b>SITE ID</b>	<b>Site Description</b>	<b>GPS (N)</b>	<b>GPS (W)</b>	<b>Substrate Type</b>	<b>Average Stream Channel Width</b>	<b>Site Comments</b>
<b>1</b>	BSC11- 12	Adjacent to a recreational park, high banks	40.58128	80.21394	Gravel & Sand	20'	Sewer lines running parallel to the stream bank. Little riparian buffer. Mostly a residential area. Primarily a riffle zone little to no pools.
<b>2</b>	BSC 13-14	Near the Leet Township building.	40.58500	80.21097	Cobble, gravel, some exposed bedrock	20'	Some riparian buffering, primarily a residential area. 2-3 very deep pools followed by a section of riffles.
<b>3</b>	BSCT1W 4-5	Parallel to narrow gravel road, tributary to Big Sewickley	40.59972	80.20001	Gravel & Silt	6'	Near the right-of-way of a sewage distribution facility, located above the site. Very narrow stream. Near State Game Lands. Noticeable erosion.
<b>4</b>	BSCT1E 3-4	Right turn onto Turkey foot Rd, below Beadnit Rd intersection at Wine Concrete products.	40.59332	80.18881	Cobble & Gravel	4'	Highly eroded left stream bank. Deep channel. 1-2 small pools. Some exposed bedrock in a few locations.
<b>5</b>	BSC 38	Upstream of Hanson & of the Sewage Treatment Plant	40.60052	80.18775	Cobble & Boulders	35'	Brown algae over large percentage of stream bottom. Relatively shallow stream with pockets of pools.
<b>6</b>	NFT2W1	Some residences.	40.63.084	80.12098	Silt & Cobble	6.5'	Narrow stream near a home. Well vegetated buffer. Primarily riffles, with a few pools.
<b>7</b>	BSCT3E3	Just below I-79	40.62559	80.10851	Silt & Gravel	10'	Accessed through multiple trails in State Game Lands. Narrow headwater stream.
<b>8</b>	EF 29-30	150' prior to Markman Road	40.62277	80.13931	Cobble	8'	Located outside housing developments in a State Game Lands. Near a road with a riparian buffer.
<b>9</b>	BSC 70	Warrendale-Bayne Road	40.63406	80.18188	Gravel & Silt	8'	Through overgrown roadside area of teasel & thistle. Near a home on right stream bank. Some exposed bedrock downstream.

## **References**

- Barbour, M.T., J. Gerritsen, B.D. Snyder, and J.B. Stribling. 1999. Rapid Bioassessment Protocols for Use in Streams and Wadeable Rivers: Periphyton, Benthic Macroinvertebrates and Fish, Second Edition. EPA 841-B-99-002. U.S. Environmental Protection Agency; Office of Water; Washington, DC.
- New Jersey Department of Environmental Protection. 2008. Fish IBI Report 2006 Sampling Round 2, Year 2 of 5, Volume 1 of 2 . New Jersey. January 2008.
- Vile, John. 1989. Biological Criteria for the Protection of Aquatic Life: Volume III: Standardized Biological Field Sampling and Laboratory Methods for Assessing Fish and Macroinvertebrate Communities. State of Ohio Environmental Protection Agency. Ohio. September 20, 1989.



ATTACHMENT D:  
BACTERIA SAMPLING

BIG SEWICKLEY CREEK  
WATERSHED ASSESSMENT, RESTORATION AND PROTECTION PLAN

Attachment D  
Bacteria Sampling

Sample ID	Sample Date	Sample Time	Field Test Results <sup>1</sup>					Lab Test Results <sup>2</sup>
			pH	Conductivity (µS/cm)	Temperature (°C)	Dissolved Oxygen	Salinity	Bacteria
BSC01F	6/12/2008	10:30	7.73	550	22.11	7.17	0.26	580
BSC02F	6/12/2008	10:55	7.70	531	22.56	6.80	0.26	3,600
BSC03F	6/12/2008	11:09	7.70	525	19.39	7.70	0.26	63
BSC04F	6/12/2008	11:25	7.64	470	23.47	6.98	0.23	4,200
BSC05F	6/12/2008	11:35	7.51	462	21.14	7.07	0.22	320
BSC06F	6/12/2008	11:45	7.40	587	20.73	8.50	0.28	350
BSC07F	6/12/2008	12:00	7.65	517	21.10	9.20	0.25	622
BSC08F	6/12/2008	12:10	7.55	635	19.50	6.70	0.31	56,000
NF01F	6/12/2008	13:55	7.67	477	23.10	7.98	0.23	108
CH01F	6/12/2008	13:45	7.57	507	20.20	8.02	0.25	36
BSC09F	6/12/2008	13:30	7.51	622	20.10	8.72	0.30	72
EF01F	6/12/2008	13:25	7.55	475	21.10	9.41	0.23	440

Sample ID	Sample Date	Sample Time	Field Test Results <sup>1</sup>					Lab Test Results <sup>2</sup>
			pH	Conductivity (µS/cm)	Temperature (°C)	Dissolved Oxygen	Salinity	Bacteria
NF01AF	6/18/2008	12:00	7.37	553	23.24	4.71	NR	1,216
NF02F	6/18/2008	12:05	7.57	167	21.48	4.80	NR	240
NF03F	6/18/2008	12:10	7.30	372	20.74	4.87	NR	540
NF04F	6/18/2008	12:20	7.27	394	20.46	4.32	NR	63
NF05F	6/18/2008	12:25	7.47	613	16.53	5.44	NR	34,000
BSC2F	6/18/2008	12:45	7.58	571	15.98	5.67	NR	240
BSC88F	6/18/2008	13:15	7.60	336	15.32	5.74	NR	490
BSC82F	6/18/2008	13:25	7.21	318	17.95	4.96	NR	400
EF01AF	6/18/2008	13:35	7.46	382	17.93	5.19	NR	380
EF28F	6/18/2008	13:45	7.26	608	17.42	5.34	NR	1,153
EF07F	6/18/2008	13:55	7.35	537	15.68	5.43	NR	540
RR01F	6/18/2008	14:00	7.37	557	16.73	5.01	NR	320
RR11F	6/18/2008	14:05	7.39	640	16.49	5.04	NR	2,200
BSC02F	1/6/2009	10:23	8.30	692	0.30		298.00	189
BSC04F	1/6/2009	10:35	8.16	699	0.40		297.00	198
BSC08F	1/6/2009	10:45	8.40	825	0.90		357.00	72
SHAF1F	1/6/2009	10:54	8.26	804	1.60		352.00	560
RR11F	1/6/2009	11:45	8.17	953	0.60		417.00	76,000
NF05F	1/6/2009	12:00	8.52	903	0.60		386.00	99

\* Total

<sup>1</sup> measured in mg/L

<sup>2</sup> measured in CFU/100 mL

Fecal Coliform Bacteria samples analyzed by Environmental Service Laboratories, Inc. of Indiana, PA

ND = Non Detect; TNTC = Too Numerous To Count



ATTACHMENT E:  
VISUAL ASSESSMENT FIELD SHEETS



Parameter	Score	Explanation of Score Given								
Channel condition										
Riparian zone										
Bank stability										
Water appearance										
Nutrient enrichment										
Fish barriers										
In-stream fish cover										
Embeddedness										
Invertebrate habitat										
Canopy Cover										
AMD (if applicable)										
Sewage (if applicable)										
Manure presence (if applicable)										
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	_____	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 – 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 – 8.9</td> <td>= GOOD</td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 – 7.4	= FAIR	7.5 – 8.9	= GOOD	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 – 7.4	= FAIR									
7.5 – 8.9	= GOOD									
> 9.0	= EXCELLENT									



**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition											
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1		

**aggradation:** *The process by which a stream's gradient steepens due to increased deposition of sediment.*

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side.  Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side.  Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side.  Or Lack of regeneration.  Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability											
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1		

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Remember to look at the water, not the substrate. **Dip a clear glass jar in water and observe the clarity.**

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community <b>little algal growth present.</b>			Fairly clear or slightly greenish water along entire reach; <b>moderate algal growth</b> on stream substrates.			Greenish water along entire reach; <b>abundant algal growth</b> , especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms <b>create thick algal mats</b> in stream.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would **impede fish passage.**

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as **the degree to which objects in the stream bottom are surrounded by fine sediment**. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle**. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.				1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
<p><b>Key:</b> This pertains to waterways <b>where channel is 50 feet wide or less.</b> Coldwater fishery</p>										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.				20 to 50% shaded.		<20% of water surface in reach shaded.	
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)										
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.			
		5			4		3		2	
									1	

If AMD is found, complete AMD site diagram and **mark discharge point on map, and/or with GPS unit.**



<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	<b>5</b>	<b>4</b>	<b>3</b> <b>2</b> <b>1</b>

**Mark discharge(s) on map and/or with GPS unit.**

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	<b>5</b>	<b>4</b>	<b>3</b> <b>2</b> <b>1</b>

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names SA / CB Date: 06/29/07  
 Sub-Watershed UNT to BSC Stream Section Name BSC T1E1 → 8  
 Stream Name " Reference Section \_\_\_\_\_  
 Weather Conditions Today partly sunny, ~70°F Past 2-5 Days scattered T-storms  
 Active Channel Width: \_\_\_\_\_ feet

LAND USE WITHIN DRAINAGE (%):				
Grazing Pasture		Grassy Field		Row Crops
Forest		Residential		Industrial
Commercial		Abandoned Mine Lands		Other

SUBSTRATE (%):				
Boulder		Cobble		Mud
		Gravel		Silt

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**

**GPS POINTS / PHOTOS:**

Waypoint	Photo	Description	pH	Cond.
BSC T1E1	1	int. of BSC Rd. and Turkey Foot Rd.	7.58	770
T1E2		stream piped under entrance / parking lot for Sewickley Coast.		
T1E3	2	old tank used for driveway X-ing		
	3	nice shot upstream in woods.		
T1E4	4-6	erosion / sedm. from Beadwell Drive.		
	7	s.w. outlet pipe sticking out too far.		
T1E5		small snake - fish	7.54	770
T1E6	8-9	road X-ing under Sevin Rd. @ int. w/ Turkey Foot Rd.		
		and int. of trib. from Bell Acres Nature Trail	7.59	660
T1E7		small trib. flowing in from the south.	7.64	810
T1E8		" " " " " the north	7.61	700
		* erosion from storm outlet		

Invasive plants present: Yes / No     Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes / No \_\_\_\_\_

Floodplain wetlands: Yes / No    If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes:

Parameter	Score	Explanation of Score Given
Channel condition	8	Some culverts
Riparian zone	9	By Road but few houses
Bank stability	10	Lots of vegetation
Water appearance	10	Clear
Nutrient enrichment	10	Little to no algae
Fish barriers	5	Culverts above channel impedes fish passage
In-stream fish cover	6	Overhead veg but not many pools or large rocks
Embeddedness	10	
Invertebrate habitat	8	
Canopy Cover	10	
AMD (if applicable)	N/A	
Sewage (if applicable)	N/A	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	86/10 <u>8.60</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR 7.5 - 8.9 = <u>GOOD</u> > 9.0 = EXCELLENT



**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

Keys: look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions. Culverts

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.
10	9	8	7	6	5	4	3	2	1	

Keys: Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.		Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

Keys: All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
<u>10</u>	9	8	7	6	5	4	3	2	1

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
<u>10</u>	9	8	7	6	5	4	3	2	1

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	<u>5</u>	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	<u>7</u>	<u>6</u>	5	4	3	2	1

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).		3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2			1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS/SA Date: 5-1-08  
 Sub-Watershed Trib to BSC Stream Section Name \_\_\_\_\_  
 Stream Name Big Sewickley Creek Reference Section \_\_\_\_\_  
 Weather Conditions Today 70's Rain/Sun Past 2-5 Days 60's Rain  
 Active Channel Width: 6-7 feet

### LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field	5	Row Crops	
Forest	95	Residential		Industrial	
Commercial		Abandoned Mine Lands		Other	

### SUBSTRATE (%):

Boulder	10	Cobble	40	Gravel	30	Silt	10	Mud	10
---------	----	--------	----	--------	----	------	----	-----	----

### DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

Through game lands

### GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
T3E1 98		Start		
99		Homeowner encroachment / split		
100		trib from right going upstream	7.7	160
101		split in trib		
102		End of day - right fork		
103		End of day - left fork		
104				
105				
106				
107				
108				
109	1	Homeowner encroachment - mulch pile in stream		
110	2	View looking upstream before 1st split		

Invasive plants present: Yes / No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes / No  Skunk co. 10

Floodplain wetlands: Yes / No If so, approximate size: Length \_\_\_\_ / Width \_\_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes: Trib through game lands, at the start there is a fenced pasture-type area at the road 1055.

Parameter	Score	Explanation of Score Given								
Channel condition	9									
Riparian zone	10									
Bank stability	9									
Water appearance	10									
Nutrient enrichment	10									
Fish barriers	9									
In-stream fish cover	9									
Embeddedness	9									
Invertebrate habitat	8									
Canopy Cover	10									
AMD (if applicable)	NA									
Sewage (if applicable)	NA									
Manure presence (if applicable)	NA									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$\frac{92}{10}$ <u>9.3</u>	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 - 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 - 8.9</td> <td>= GOOD</td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 - 7.4	= FAIR	7.5 - 8.9	= GOOD	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 - 7.4	= FAIR									
7.5 - 8.9	= GOOD									
> 9.0	= EXCELLENT									



### Scoring Descriptions

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.	Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.	Natural vegetation extends one active channel width on each side.  Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side.  Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side.  Or Lack of regeneration.  Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.	Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1

**Keys:** **All** outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness				
Gravel or cobble particles are <20% embedded.	Gravel or cobble particles are 20 to 30% embedded.	Gravel or cobble particles are 30 to 40% embedded.	Gravel or cobble particles are >40% embedded.	Completely embedded.
10      9	8      7      6	5      4	3      2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded:

Insect/invertebrate Habitat				
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).	3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.	1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.	None to 1 type of habitat.	
10      9      8	7      6      5      4	3      2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover				
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery				
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.	> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.	20 to 50% shaded.	<20% of water surface in reach shaded.	
10      9      8	7      6      5      4	3      2	1	

Abandoned Mine Drainage (if applicable)				
(Intentionally blank)	Evidence of iron staining. Or Noticeable iron precipitate.	Iron precipitate visible, muddy orange appearance.	Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.	
	5      4	3      2	1	

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Assessor Names KS/SA Date: 5-13-08

Watershed \_\_\_\_\_ Stream Section Name \_\_\_\_\_

Stream Name Right trib to BSC Reference Section \_\_\_\_\_

Weather Conditions Today \_\_\_\_\_ Past 2-5 Days \_\_\_\_\_

Active Channel Width: 1-3 feet

### LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field		Row Crops	
Forest	<u>90</u>	Residential	<u>10</u>	Industrial	
Commercial		Abandoned Mine Lands		Other	

### SUBSTRATE (%):

Boulder	<u>30</u>	Cobble	<u>25</u>	Gravel	<u>30</u>	Silt	<u>10</u>	Mud	<u>5</u>
---------	-----------	--------	-----------	--------	-----------	------	-----------	-----	----------

### DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

### GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
<u>12</u>	<u>1, 2</u>	<u>Start / Camp meet Rd. EXT INT</u>	<u>7.85</u>	<u>370</u>
<u>13</u>	<u>3, 4</u>	<u>Trib from left (going up stream)</u>		
<u>14</u>	<u>5</u>	<u>Headwaters</u>		

Invasive plants present:  Yes /  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Debris / Litter: Yes /  No

Upland wetlands:  Yes /  No If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet

Shaded areas: Yes  No (Wetland or other) \_\_\_\_\_

Notes: Clear stream, no algae

Parameter	Score	Explanation of Score Given								
Channel condition	9									
Riparian zone	10									
Bank stability	10									
Water appearance	9									
Nutrient enrichment	9									
Fish barriers	8									
In-stream fish cover	9									
Embeddedness	9									
Invertebrate habitat	9									
Canopy Cover	10									
AMD (if applicable)	NA									
Sewage (if applicable)	NA									
Manure presence (if applicable)	NA									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$\frac{92}{10} = 9.2$	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 – 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 – 8.9</td> <td>= GOOD</td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 – 7.4	= FAIR	7.5 – 8.9	= GOOD	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 – 7.4	= FAIR									
7.5 – 8.9	= GOOD									
> 9.0	= EXCELLENT									

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

Structure at INT of BSC

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone											
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1		

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.		Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.



Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness				
Gravel or cobble particles are <20% embedded.	Gravel or cobble particles are 20 to 30% embedded.	Gravel or cobble particles are 30 to 40% embedded.	Gravel or cobble particles are >40% embedded.	Completely embedded.
10	9	8 7 6	5 4	3 2 1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat			
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).	3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.	1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.	None to 1 type of habitat.
10	9	8 7 6 5 4	3 2 1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover			
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery			
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.	> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.	20 to 50% shaded.	<20% of water surface in reach shaded.
10	9 8	7 6 5 4	3 2 1

Abandoned Mine Drainage (if applicable)			
(Intentionally blank)	Evidence of iron staining. Or Noticeable iron precipitate.	Iron precipitate visible, muddy orange appearance.	Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.
	5 4	3 2	1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**





Parameter	Score	Explanation of Score Given
Channel condition	6	
Riparian zone	7	
Bank stability	7	
Water appearance	8	
Nutrient enrichment	8	
Fish barriers	5	
In-stream fish cover	7	
Embeddedness	8	
Invertebrate habitat	8	
Canopy Cover	9	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$\frac{73}{10} =$ <u>7.3</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR 7.5 - 8.9 = GOOD > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition											
Natural channel; no structures, dikes. No evidence of down-Cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1		

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability											
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1		

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.			Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.	
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1		

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



Parameter	Score	Explanation of Score Given
Channel condition	8	
Riparian zone	8	
Bank stability	8	
Water appearance	10	
Nutrient enrichment	10	
Fish barriers	6	
In-stream fish cover	9	
Embeddedness	9	
Invertebrate habitat	9	
Canopy Cover	9	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	80/10 <u>8.0</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR (7.5 - 8.9 = GOOD) > 9.0 = EXCELLENT

### Scoring Descriptions

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.	Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levies are set back to provide access to an adequate flood plain.				Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10      9 <b>8</b>	7	6	5	4	3	2	1		

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.	Natural vegetation extends one active channel width on each side.  Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side.  Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side.  Or Lack of regeneration.  Or Filtering function severely compromised.	
10      9 <b>8</b>	7	6	5	4	3	2	1		

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.	Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.				Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10      9 <b>8</b>	7	6	5	4	3	2	1		

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.



Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness				
Gravel or cobble particles are <20% embedded.	Gravel or cobble particles are 20 to 30% embedded.	Gravel or cobble particles are 30 to 40% embedded.	Gravel or cobble particles are >40% embedded.	Completely embedded.
10	9	8 7 6	5 4	3 2 1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat			
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).	3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.	1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.	None to 1 type of habitat.
10	9	8 7 6 5 4	3 2 1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover			
Key: This pertains to waterways where channel is 50 feet wide or less.			
Coldwater fishery			
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.	> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.	20 to 50% shaded.	<20% of water surface in reach shaded.
10	9	8 7 6 5 4	3 2 1

Abandoned Mine Drainage (if applicable)			
(Intentionally blank)	Evidence of iron staining. Or Noticeable iron precipitate.	Iron precipitate visible, muddy orange appearance.	Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.
	5 4	3 2	1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KW/CB Date: 06/21/07  
 Sub-Watershed B5C Stream Section Name B5CT2W1 → 2  
 Stream Name UNT to B5C Reference Section \_\_\_\_\_  
 Weather Conditions Today mostly sunny, breezy, ~80°F Past 2-5 Days scattered rain showers

Land use within drainage (%):				
Grazing Pasture		Grassy Field <u>crevetory</u>	20	Row Crops
Forest	70	Residential	10	Industrial
Commercial		Abandoned Mine Lands		Other

Substrate (%):								
Boulder		Cobble	40	Gravel	50	Silt	10	Mud

Active Channel Width: 1.5 meters

Floodplain wetlands: Yes / No Approximate size: Length \_\_\_\_ / Width \_\_\_\_ (feet or meters)

Flooded areas? (Wetland or other) \_\_\_\_\_

pH \_\_\_\_\_ Conductivity \_\_\_\_\_

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**  
 Type of forest, farmland, residential, and/or commercial:  
Homes on hilltops, steep, forested slopes, power-line cutting thru.

GPS Waypoints				
	Latitude	Longitude	Photo #s	Description
Start				
End				
Other				
<u>B5CT2W1</u>				<u>30" Ø pipe X-ing &amp; small trib. int. (pH = 7.59 / cond. = 360)</u>
<u>T2W2</u>				<u>small trib. from west (pH = 7.74 / cond. = 530)</u>

Photographs	
Photo #	Description

Discharges			
Size	Type	Waypoint	Photo #

Invasive plants present?  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other  
NO

Trash / Litter? not really



Parameter	Score	Explanation of Score Given
Channel condition	<input checked="" type="checkbox"/> 8	
Riparian zone	<input checked="" type="checkbox"/> 8	would be 10, but lower section of channel runs thru a few yards.
Bank stability	<input checked="" type="checkbox"/> 7	
Water appearance	<input checked="" type="checkbox"/> 9	
Nutrient enrichment	<input checked="" type="checkbox"/> 9	
Fish barriers	<input checked="" type="checkbox"/> 5	culvert @ T2W1 (not necessary, old logging X-ing??)
In-stream fish cover	<input checked="" type="checkbox"/> 5	
Embeddedness	<input checked="" type="checkbox"/> 6	
Invertebrate habitat	<input checked="" type="checkbox"/> 7	
Canopy Cover	<input checked="" type="checkbox"/> 9	
AMD (if applicable)	<input type="checkbox"/> N/A	
Sewage (if applicable)	<input type="checkbox"/> N/A	
Manure presence (if applicable)	<input type="checkbox"/> N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>7.3</u>	< 6.0 = POOR 6.1 - 7.4 = FA 7.5 - 8.9 = GOC > 9.0 = EXCELLEN

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	<u>9</u>	8	7	6	5	4	3	2	1

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	<u>9</u>	8	7	6	5	4	3	2	1

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	<u>5</u>	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	<u>5</u>	4	3	2	1

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)										
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.			
		5			4		3		2	
									1	

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



**Big Sewickley Creek Visual Assessment**

**Stream Section Name:**

T2W1-9-2

**Date:**

06/21/07

<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

Name: B SCT 1 W 1 → 8  
6/21/07

## Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names CB/KS Date: 06/21/07  
 Sub-Watershed BSC Stream Section Name B SCT 1 W 1 → 8  
 Stream Name UNT 1 W to BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today sunny, ~ 80°F Past 2-5 Days rain Tuesday night

Land use within drainage (%):				
Grazing Pasture		Grassy Field		Row Crops
Forest	65	Residential	20	Industrial
Commercial		Abandoned Mine Lands		Other <u>Power Line/Sun. Lines</u> 15

Substrate (%):				
Boulder	Cobble	Gravel	Silt	Mud

Active Channel Width: 2 meters  
 Floodplain wetlands: Yes/No No Approximate size: Length \_\_\_\_ / Width \_\_\_\_ (feet or meters)  
 Flooded areas? (Wetland or other) \_\_\_\_\_  
 pH \_\_\_\_\_ Conductivity \_\_\_\_\_

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**  
 Type of forest, farmland, residential, and/or commercial:  
Steep, wooded slopes, residential on top of hill and at bottom of watershed.  
Trailer park near confluence of UNT and Big Sewickley Creek.

GPS Waypoints				
	Latitude	Longitude	Photo #s	Description
Start				
End				
Other	<u>B SCT 1 W 1</u>		<u>1-2</u>	<u>road work out @ trailer park into stream</u>
	<u>B SCT 1 W 2</u>		<u>4</u>	<u>int. of 2 streams left branch pH = 7.10</u>
	<u>B SCT 1 W 3</u>		<u>6</u>	<u>cross pipe from cond = 440</u>
	<u>B SCT 1 W 4</u>		<u>7</u>	<u>pared road and loose dump site along stream. Fill. (right branch pH = 7.51 cond = 310)</u>
	<u>B SCT 1 W 5</u>			<u>int. of small streams near road X-ing (pH = 7.34 / cond = 920)</u>
	<u>B SCT 1 W 6</u>			<u>spring flow (pH = 7.60 / cond = 220) Photographs</u>
Photo #	Description			
<u>1</u>	<u>runoff from D/G road down into pared road.</u>			
<u>2</u>	<u>heavy sedm. and undercut banks on trib.</u>			
<u>3-6</u>	<u>landslide on powerline.</u>			
<u>7</u>	<u>landslide on powerline → heavy sedimentation in stream below.</u>			
<u>8</u>	<u>waste area causing severe Discharges → Economy Boro sanitary line.</u>			
	Type	erosion.	Waypoint	Photo #

FOR AIR QUALITY

live plants present?  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other \_\_\_\_\_  
 Litter? Yes, dumping between stream channel and road @ w.p. T1W4

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names CB/KS Date: 06/21/07  
 Sub-Watershed BSC Stream Section Name BSC T1W 1 → 8  
 Stream Name UNT 1W to BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today sunny, ~80°F Past 2-5 Days rain tuesday night

Land use within drainage (%):				
Grazing Pasture		Grassy Field		Row Crops
Forest	65	Residential	20	Industrial
Commercial		Abandoned Mine Lands		Other Power Line/San. Lines
				15

Substrate (%):				
Boulder		Cobble		Mud
		Gravel		Silt

Active Channel Width: 2 meters  
 Floodplain wetlands: Yes  No  Approximate size: Length \_\_\_\_ / Width \_\_\_\_ (feet or meters)  
 Flooded areas? (Wetland or other) \_\_\_\_\_  
 pH \_\_\_\_\_ Conductivity \_\_\_\_\_

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**  
 Type of forest, farmland, residential, and/or commercial:  
Steep, wooded slopes, residential on top of hill and at bottom of watershed.  
Trailer park near confluence of UNT and Big Sewickley Creek.

GPS Waypoints				
	Latitude	Longitude	Photo #s	Description
Start				
End				
Other	BSC T1W 1		1-2	road washout @ trailer park into stream
	BSC T1W 2		4	int. of 2 streams left branch pH = 7.10
	T1W 3		6	cross pipe from cond = 440
	T1W 4		7	parked road and loose dump site along stream. right branch pH = 7.51 Fill. cond = 310
	T1W 5			int. of small streams near road X-ing (pH = 7.34 / cond = 920)

T1W 6 spring flow (pH = 7.60 / cond = 220) Photographs	
Photo #	Description
3	runoff from D/G road down into paved road.
5	heavy sedm. and undercut banks on trib.
8-10	landslide on powerline.

T1W 7 landslide on powerline → heavy sedimentation in stream below.

T1W 8 waste area causing severe Discharges → Economy Boro sanitary line.			
Size	Type	Waypoint	Photo #
	erosion.		

Invasive plants present?  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other \_\_\_\_\_  
 Trash / Litter? Yes, dumping between stream channel and road @ w.p.  
T1W 4

Parameter	Score	Explanation of Score Given
Channel condition	<input checked="" type="checkbox"/> 6	
Riparian zone	<input checked="" type="checkbox"/> 8	
Bank stability	<input checked="" type="checkbox"/> 4	
Water appearance	<input checked="" type="checkbox"/> 1	cloudy / turbid from springs picking up silt from landslide site.
Nutrient enrichment	<input checked="" type="checkbox"/> 9	
Fish barriers	<input checked="" type="checkbox"/> 5	
In-stream fish cover	<input checked="" type="checkbox"/> 4	
Embeddedness	<input checked="" type="checkbox"/> 3	clay/silt freshly deposited from sites in upper watershed.
Invertebrate habitat	<input checked="" type="checkbox"/> 4	
Canopy Cover	<input checked="" type="checkbox"/> 9	
AMD (if applicable)	<input type="checkbox"/> N/A	
Sewage (if applicable)	<input type="checkbox"/> N/A	
Manure presence (if applicable)	<input type="checkbox"/> N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>5.3</u>	<p>&lt; 6.0 = POOR</p> <p>6.1 - 7.4 = FAIR</p> <p>7.5 - 8.9 = GOOD</p> <p>&gt; 9.0 = EXCELLENT</p>



**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers										
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1	

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4	3	2	1			

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS/SA Date: 7-26-07  
 Sub-Watershed \_\_\_\_\_ Stream Section Name BSC 86-97  
 Stream Name \_\_\_\_\_ Reference Section \_\_\_\_\_  
 Weather Conditions Today 90° Cloudy Past 2-5 Days Same  
 Active Channel Width: 20 feet

### LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field	
Forest	80	Residential	20
Commercial		Abandoned Mine Lands	
		Row Crops	
		Industrial	
		Other	

### SUBSTRATE (%):

Boulder	Cobble	Gravel	Silt	Mud
---------	--------	--------	------	-----

### DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

### GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
BSC86	1	Start, above bridge		
BSC87	23	Small bridge, debris jam		
BSC88	34	Ironing Tab (W)		
BSC89	5	Debris jam		
BSC90	69	Debris Dams		
BSC91	8	Trees cut due to house construction		
BSC92	9	Manned Dam	7.22	450
BSC93		Strong smell of gas		
BSC94	10	Culvert		
BSC95		Driveway crossing/culvert		
BSC96	11	Ironing Tab W		
BSC97		Ironing Tab from W (not ID'd on topo)		

Invasive plants present: Yes /  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other \_\_\_\_\_

Trash / Litter: Yes /  No \_\_\_\_\_

Floodplain wetlands: Yes /  No If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet

Flooded areas: Yes /  No (Wetland or other) \_\_\_\_\_

Notes: Some backwater channels

Parameter	Score	Explanation of Score Given								
Channel condition	8	Culverts under a few driveways one homeowner had own "dam"								
Riparian zone	10									
Bank stability	9									
Water appearance	9	Pools looked "bluish"								
Nutrient enrichment	9									
Fish barriers	6	1 dam / pretty shallow turnout								
In-stream fish cover	8									
Embeddedness	8									
Invertebrate habitat	9									
Canopy Cover	10	Lots trees!								
AMD (if applicable)										
Sewage (if applicable)										
Manure presence (if applicable)										
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$\frac{86}{10}$ <u>8.6</u>	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 - 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 - 8.9</td> <td>= GOOD</td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 - 7.4	= FAIR	7.5 - 8.9	= GOOD	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 - 7.4	= FAIR									
7.5 - 8.9	= GOOD									
> 9.0	= EXCELLENT									

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_



Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).		3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.			
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less.										
Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.			
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)											
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.				
		5			4		3		2		1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS, CB Date: 07/24/07  
 Sub-Watershed BSC Stream Section Name BSC 83 → 85  
 Stream Name BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today partly sunny, ~77°F Past 2-5 Days scattered showers  
 Active Channel Width: ~7 feet

### LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field	5	Row Crops	
Forest	80	Residential	15	Industrial	
Commercial		Abandoned Mine Lands		Other	

### SUBSTRATE (%):

Boulder		Cobble	10	Gravel	10	Silt/Mud	10	Bedrock		
								<del>Mud</del>		70

### DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

### GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
84	23	Drain from road - sedimentation		
85		Bridge on Spang Rd. - end of section		
* 83	21	15" CPP s.w. pipe - ATV X-ing on channel		
	22	view upstream @ small riffle across bedrock substrate		

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other \_\_\_\_\_

Trash / Litter: Yes  No  \_\_\_\_\_

Floodplain wetlands: Yes  No  If so, approximate size: Length \_\_\_\_ / Width \_\_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes: → heavy algae on substrate; jumped back along stream, just d.s.  
 → ATV trails crossing stream in (3) places along this stretch of Spang Rd. bridge

Parameter	Score	Explanation of Score Given
Channel condition	8	
Riparian zone	8	
Bank stability	8	Gabian wall @ house w/ ATVs
Water appearance	9	
Nutrient enrichment	6	heavy algae on bedrock substrate
Fish barriers	8	
In-stream fish cover	5	bedrock
Embeddedness	8	
Invertebrate habitat	7	
Canopy Cover	9	
AMD (if applicable)	N/A	
Sewage (if applicable)	N/A	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>7.6</u>	< 6.0 = POOR 6.1 – 7.4 = FAIR <u>7.5 – 8.9 = GOOD</u> > 9.0 = EXCELLENT



### Scoring Descriptions

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.		Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1		

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

**Big Sewickley Creek Visual Assessment**

**Stream Section Name:**

BSC 83-985

**Date:**

7/24/07

<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS, CB Date: 07/24/07  
Sub-Watershed B5C Stream Section Name B5C 83 → 85  
Stream Name B5C Reference Section \_\_\_\_\_  
Weather Conditions Today partly sunny, ~77°F Past 2-5 Days scattered showers  
Active Channel Width: ~7 feet

## LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field	5	Row Crops	
Forest	80	Residential	15	Industrial	
Commercial		Abandoned Mine Lands		Other	

## SUBSTRATE (%):

Boulder		Cobble	10	Gravel	10	Silt/mud	10	Bedrock	70
---------	--	--------	----	--------	----	----------	----	---------	----

## DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

## GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
84	23	Drain from road - sedimentation		
85		Bridge on Spang Rd. - end of section		
* 83	21	15" CPV s.w. pipe - ATV x-ing on channel		
	22	view upstream @ small riffle across bedrock substrate		

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other  
Trash / Litter: Yes /  No   
Floodplain wetlands:  Yes  No If so, approximate size: Length \_\_\_\_ / Width \_\_\_\_ feet  
Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes: → heavy algae on substrate; jumped buck along stream, just d.s. of Spang Rd. bridge  
→ ATV trails crossing stream in (3) places along this stretch.

Parameter	Score	Explanation of Score Given
Channel condition	8	
Riparian zone	8	
Bank stability	8	Gabion wall @ house w/ ATVs
Water appearance	9	
Nutrient enrichment	6	heavy algae on bedrock substrate
Fish barriers	8	
In-stream fish cover	5	bedrock
Embeddedness	8	
Invertebrate habitat	7	
Canopy Cover	9	
AMD (if applicable)	N/A	
Sewage (if applicable)	N/A	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>7.6</u>	< 6.0 = POOR 6.1 – 7.4 = FAIR 7.5 – 8.9 = <u>GOOD</u> > 9.0 = EXCELLENT

### Scoring Descriptions

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side.  Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side.  Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side.  Or Lack of regeneration.  Or Filtering function severely compromised.
10	9	8	7	6	5	4	3	2	1	

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.		Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_



Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4	3	2	1			

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names RK, KS, CB Date: 07/24/07  
 Sub-Watershed BSC Stream Section Name BSC 70 → 76  
 Stream Name BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today sunny, ~77°F Past 2-5 Days scattered showers  
 Active Channel Width: ~7 feet

LAND USE WITHIN DRAINAGE (%):					
Grazing Pasture		Grassy Field	10	Row Crops	
Forest	80	Residential	10	Industrial	
Commercial		Abandoned Mine Lands		Other	

SUBSTRATE (%):									
Boulder	10	Cobble	20	Gravel	10	Silt/mud	20	Bedrock <del>Mud</del>	40

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**

**GPS POINTS / PHOTOS:**

Waypoint	Photo	Description	pH	Cond.
71		drainage way from opp. side from road.	7.57	630
72	8	Terra-cotta pipe (12" Ø) and small drainage way from the road		
	9			
	10	bank erosion - view downstream		
73	11	drainage from end of road / driveway		
74	12	island in middle of stream @ conpl. w/ trib.?		
	13	6' high bank erosion, just d.s. of Markman Pk. Rd.		
75	14	sinuous stream section w/ debris jams		
76	15	on-stream wetland / pond off of Markman Pk. Rd.		
	16	* bad bank erosion betw. road and wetland (7' high) ~150' long.		

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other \_\_\_\_\_

Trash / Litter: Yes  No

Floodplain wetlands: Yes / No  If so, approximate size: Length 4,000 / Width 500 feet

Flooded areas: Yes / No  (Wetland or other) From pond above Markman Pk. Rd. upstream

Notes: sections with bedrock substrate have some bank erosion

Parameter	Score	Explanation of Score Given
Channel condition	6	
Riparian zone	8	
Bank stability	6	
Water appearance	8	
Nutrient enrichment	8	
Fish barriers	1	On-stream pond @ Markman Park Rd.
In-stream fish cover	7	
Embeddedness	8	
Invertebrate habitat	7	
Canopy Cover	7	
AMD (if applicable)	N/A	
Sewage (if applicable)	N/A	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>6.6</u>	< 6.0 = POOR 6.1 – 7.4 = FAIR 7.5 – 8.9 = GOOD > 9.0 = EXCELLENT



**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition											
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1		

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability											
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1		

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.			None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)										
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.			Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1			

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names RK, KS, CB Date: 7/27/07  
 Sub-Watershed Big Sewickley Creek Stream Section Name BSC 66 → 70  
 Stream Name BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today sunny, ~77°F Past 2-5 Days scattered showers, 75°F avg.  
 Active Channel Width: ~8 feet

### LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field	10	Row Crops	
Forest	70	Residential	20	Industrial	
Commercial		Abandoned Mine Lands		Other	

### SUBSTRATE (%):

Boulder	10	Cobble	30	Gravel	20	Silt/Mud	20	Bedrock	20
---------	----	--------	----	--------	----	----------	----	---------	----

### DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

Area along Warrandale - Bayne Rd.

### GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
66	1	int./Bridge over BSC on Big Sew. Cr. Rd.	7.64	630
67	2-3	banks erosion, debris jam recently removed		
68	4	big debris jam		
69	5-6	man made dam, debris jam		
70	7	END/ drainage coming from Warrandale - Bayne Rd. / (@ bridge) end of section		

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes / No none

Floodplain wetlands: Yes  No  If so, approximate size: Length \_\_\_\_ / Width \_\_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes:

Parameter	Score	Explanation of Score Given
Channel condition	7	
Riparian zone	9	
Bank stability	8	
Water appearance	8	
Nutrient enrichment	6	algae on rocks in substrate
Fish barriers	5	man-made dams on-stream
In-stream fish cover	8	
Embeddedness	8	
Invertebrate habitat	9	
Canopy Cover	9	
AMD (if applicable)	N/A	
Sewage (if applicable)	N/A	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>7.7</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR 7.5 - 8.9 = <u>GOOD</u> > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levies are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.
10	9	8	7	6	5	4	3	2	1	

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.		Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.		Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4	3	2	1			

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



**Big Sewickley Creek Visual Assessment**

**Stream Section Name:** BSC 66-70

**Date:** 7/24/07

<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream. Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



Parameter	Score	Explanation of Score Given
Channel condition	7	
Riparian zone	9	
Bank stability	7	
Water appearance	7	
Nutrient enrichment	7	
Fish barriers	5	
In-stream fish cover	8	
Embeddedness	7	
Invertebrate habitat	8	
Canopy Cover	8	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	73/10 <u>7.3</u>	< 6.0 = POOR <u>6.1 - 7.4 = FAIR</u> 7.5 - 8.9 = GOOD > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.		Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).		Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community <b>little algal growth present.</b>			Fairly clear or slightly greenish water along entire reach; <b>moderate algal growth</b> on stream substrates.			Greenish water along entire reach; <b>abundant algal growth</b> , especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms <b>create thick algal mats</b> in stream.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers											
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.			Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1		

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_



Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1		

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS/SA Date: 7/13/07  
 Sub-Watershed \_\_\_\_\_ Stream Section Name BSC 53 - BSC-60  
 Stream Name BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today 80's, Dry, Sunny Past 2-5 Days Same  
 Active Channel Width: 30 feet

### LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field	20	Row Crops	
Forest	60	Residential	10	Industrial	
Commercial	10	Abandoned Mine Lands		Other	

Bedrock 20

### SUBSTRATE (%):

Boulder	30/10	Cobble	20	Gravel	30	Silt	10	Mud	10
---------	-------	--------	----	--------	----	------	----	-----	----

DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

### GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
BSC53		Start point Leobias jam		
BSC54		Under road culvert	7.0	500
BSC55	#1	Rebas Jam		
BSC56	#2	Incoming Tilt <u>(west)</u> <del>East</del> / south		
BSC57		Culvert <u>Open business</u> Dry / Start of bedrock section		
BSC58	#34	Dam, water level sign		
BSC59	#5	Incoming trib <u>(E 2)</u> <del>West</del> / north PA Game Commission		
BSC60		End point		

Invasive plants present:  Yes  No     Japanese Knotweed  Garlic mustard  Purple loosestrife  C  
 Trash / Litter: Yes /  No  
 Floodplain wetlands: Yes /  No    If so, approximate size: Length \_\_\_ / Width \_\_\_ feet  
 Flooded areas: Yes /  No (Wetland or other) \_\_\_\_\_

Notes:

Parameter	Score	Explanation of Score Given
Channel condition	8	
Riparian zone	9	
Bank stability	8	
Water appearance	9	
Nutrient enrichment	5	No notable sewage/pipes but lots of brown/black algae
Fish barriers	5	
In-stream fish cover	9	
Embeddedness	7	
Invertebrate habitat	9	
Canopy Cover	8	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	77/10 <u>7.7</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR 7.5 - 8.9 = <u>GOOD</u> > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levies are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.



Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers										
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1	

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.		Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).		3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.			None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.			<20% of water surface in reach shaded.	
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.			Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.	
		5	4		3	2			1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names SA/CB Date: 07/03/07  
 Sub-Watershed BSC Stream Section Name BSC 43 → 52  
 Stream Name BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today sunny, ~80°F Past 2-5 Days Mostly sunny  
 Active Channel Width: 15 feet

LAND USE WITHIN DRAINAGE (%):							
Grazing Pasture		Grassy Field		Row Crops			
Forest	70	Residential	20	Industrial			
Commercial	5	Abandoned Mine Lands		Other (roads)		5	
SUBSTRATE (%):							
Boulder	5	Cobble	25	Gravel	30	Silt/mud	35
						Bedrock	5
DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:							
Few, small commercial establishments, then mostly private homes surrounded by forested slopes.							
GPS POINTS / PHOTOS:							
Waypoint	Photo	Description	pH	Cond.			
43		start point @ Gaydos Lane bridge					
44		trib. from west @ int. of BSC rd. and Shaffer Rd.					
45	1	sediment build-up in middle of stream					
46	2	Chen Dry - black plastic pipes					
47	3	confluence with North Fork	8.21	580			
<del>48</del>	<del>4</del>	(above confl.) BSC main stem	7.99	650			
48	4	Sedm. build up w/ backwater pools and debris jam @ sanitary X-ing.					
	5	bank erosion with deep hole					
	6	shot up @ Sycamore/sky.					
49	7	seep down hillside from elder house.					
50	8	trib. coming in by house - heavy sedimentation					
51	9	debris jam					
52		flood plain wetland / end point.					
					coming flooded		

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other \_\_\_\_\_  
 Trash / Litter: Yes  No  very little  
 Floodplain wetlands Yes  No  If so, approximate size: Length 1,000 / Width 400 feet  
 Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes: sanitary line installation has caused stream changes / damage.

Parameter	Score	Explanation of Score Given
Channel condition	5	
Riparian zone	7	
Bank stability	5	
Water appearance	7	
Nutrient enrichment	6	
Fish barriers	6	
In-stream fish cover	8	
Embeddedness	7	
Invertebrate habitat	8	
Canopy Cover	8	
AMD (if applicable)	N/A	
Sewage (if applicable)	5	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>6.55</u>	< 6.0 = POOR 6.1 – 7.4 = FAIR 7.5 – 8.9 = GOOD > 9.0 = EXCELLENT



**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition											
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1		

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability											
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1		

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available		4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.				1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.			
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)										
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.			
		5			4		3		2	
									1	

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

wildlife : blue herons, bird w/ nest in bank, fish, crayfish

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names SA/CB Date: 07/03/07  
 Sub-Watershed BSC Stream Section Name BSC 34 → 42  
 Stream Name BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today Sunny, ~80°F Past 2-5 Days \_\_\_\_\_  
 Active Channel Width: \_\_\_\_\_ feet

LAND USE WITHIN DRAINAGE (%):					
Grazing Pasture		Grassy Field		Row Crops	
Forest	70	Residential	15	Industrial	15
Commercial		Abandoned Mine Lands		Other	

SUBSTRATE (%):					
Boulder	105	Cobble	25	Gravel	
				Silt/mud	20
				<del>Mud</del> bedrock	50

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**

k. lot of algae on rocks.

**GPS POINTS / PHOTOS:**

Waypoint	Photo	Description	pH	Cond.
34		just upstream of bridge @ 'Wine Concrete' office		
35	1	Hansen - Sewickley Creek plant	7.54	670
	2	shot upstream along Hansen property		
36	3-4-5	sewage treatment plant, green/black discharge point		
	6-7	Blue heron walking upstream		
37		sewage plant outlet structure → can't see end of pipe		
38	9-11	Heron Rookery - crap, dead fish, strong smell		
39	12	private heron, small green plastic pipe coming out	7.69	<del>650</del> 650
	13	tire bank stabilization		
40		4" Ø green plastic pipe - sewage?		
	14	view downstream		
41	15	white discharge out of streambank	7.54	1110
	16-17	k. Holman w/ orange fish		

Invasive plants present: Yes / No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other  
 Trash / Litter:  Yes  No very little  
 Floodplain wetlands: Yes / No If so, approximate size: Length \_\_\_\_ / Width \_\_\_\_ feet  
 Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes:

Kevin ~~CB~~ Holman caught orange fish



Parameter	Score	Explanation of Score Given
Channel condition	8	
Riparian zone	8	
Bank stability	8	
Water appearance	7	
Nutrient enrichment	5	
Fish barriers	6	
In-stream fish cover	8	
Embeddedness	6	
Invertebrate habitat	8	
Canopy Cover	8	
AMD (if applicable)	N/A	
Sewage (if applicable)	4	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>6.91</u>	< 6.0 = POOR 6.1 – 7.4 = FAIR 7.5 – 8.9 = GOOD > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition											
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1		

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability											
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1		

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobbles, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4	3	2	1			

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

**Big Sewickley Creek Visual Assessment**

**Stream Section Name:** 34 → 42

**Date:** 7/3/07

<b>Sewage (if applicable)</b>					
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.		
	5	4	3	2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>					
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream. Or Untreated human waste discharge pipes present.		
	5	4	3	2	1

**NOTES**



# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names SA/CB Date: 06/29/07

Sub-Watershed BSC Stream Section Name BSC 27 → 33

Stream Name BSC Reference Section \_\_\_\_\_

Weather Conditions Today overcast, ~75°F Past 2-5 Days scattered T-storms

Active Channel Width: 32.5 feet

LAND USE WITHIN DRAINAGE (%):										
Grazing Pasture				Grassy Field				Row Crops		
Forest		60		Residential				Industrial		
Commercial				Abandoned Mine Lands				Other (roads)		
								30		
								10		
SUBSTRATE (%):										
Boulder		Cobble		Gravel		Silt		Bedrock		
		30		15		10		<del>100</del> 45%		
DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:										
Along Big Sewickley Creek Rd.										
GPS POINTS / PHOTOS:										
Waypoint	Photo	Description							pH	Cond.
27	1	view upstream from bridge								
28		act. channel width measurement							7.23	630
29	1	spring flow from road @ old manhole							7.33	680
	2	shot upstream.								
30	3-4	bank erosion / concrete wall constricting channel								
31	5	tributary from Turkey Foot Rd. @ Ed Wagner Auto Salvage.								
32	6	12" Ø concrete pipe w/ trickle flow (pink algae)								
33	7	bridge over BSC by Zassick's Auto								
		(right side of bridge silted-in.)								

Invasive plants present: Yes / No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter:  Yes / No auto parts, plastic, flood debris

Floodplain wetlands: Yes /  No If so, approximate size: Length \_\_\_ / Width \_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes:

~~(7.23) 255 - 3229~~

Parameter	Score	Explanation of Score Given
Channel condition	7	
Riparian zone	5	
Bank stability	8	
Water appearance	7	
Nutrient enrichment	5	
Fish barriers	8	
In-stream fish cover	6	
Embeddedness	6	
Invertebrate habitat	8	
Canopy Cover	9	
AMD (if applicable)	N/A	
Sewage (if applicable)	5	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>6.73</u>	< 6.0 = POOR 6.1 – 7.4 = <u>FAIR</u> 7.5 – 8.9 = GOOD > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.				1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.				20 to 50% shaded.		<20% of water surface in reach shaded.	
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1		

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Big Sewickley Creek Visual Assessment

Stream Section Name: \_\_\_\_\_

Date: 6/29/07

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names CB / KS Date: 06/11/07  
 Sub-Watershed BSC Stream Section Name BSC 17 → BSC 26  
 Stream Name BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today sunny, ~ 80°F Past 2-5 Days rain Friday<sup>6/8</sup> p.m.

Land use within drainage (%):			
Grazing Pasture		Grassy Field	
Forest		Residential	Industrial
Commercial		Abandoned Mine Lands	Other

Substrate (%):					
Boulder		Cobble		Gravel	
				Silt	
					Mud

Active Channel Width: \_\_\_\_\_ meters

Floodplain wetlands: Yes / No    Approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ (feet or meters)

Flooded areas? (Wetland or other) \_\_\_\_\_

pH 8.34    Conductivity 640

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**  
 Type of forest, farmland, residential, and/or commercial:

GPS Waypoints				
	Latitude	Longitude	Photo #s	Description
Start	<u>BSC 17 / N 40.58507</u>	<u>W 080.20989</u>		<u>start point</u>
End				
Other	<u>BSC 18</u>			<u>s.w. discharge from end of street</u>
	<u>BSC 19</u>			<u>" " (15" Ø SPP)</u>
	<u>BSC 20</u>		<u>#9</u>	<u>discharge from 3' Ø pipe</u>
	<u>BSC 21</u>		<u>10-11</u>	<u>pH = 7.37</u>
	<u>BSC 22</u>			<u>pH = 8.34 / cond = 640</u>
	<u>BSC 23</u>			<u>cond = 690</u>
	<u>BSC 24</u>			<u>Flw = 5 gpm</u>
				<u>s.w. pipe - 15" Ø SCP</u>
				<u>s.w. pipe - " "</u>

Photographs	
Photo #	Description
<u>12</u>	<u>new, private bridge under const. below Benkey's</u>

Discharges			
Size	Type	Waypoint	Photo #
<u>6-8" metal</u>	<u>sewage plant from trailer court</u>	<u>BSC 25</u>	<u>13</u>

pH = 7.7 / cond = 370    stream    BSC 26    14  
 Invasive plants present?  Japanese Knotweed     Garlic mustard     Purple loosestrife     Other

Trash / Litter? very little

Parameter	Score	Explanation of Score Given
Channel condition	<input checked="" type="checkbox"/> 4	too wide/straightened in <sup>many</sup> sections
Riparian zone	<input checked="" type="checkbox"/> 7	
Bank stability	<input checked="" type="checkbox"/> 7	
Water appearance	<input checked="" type="checkbox"/> 7	
Nutrient enrichment	<input checked="" type="checkbox"/> 4	
Fish barriers	<input checked="" type="checkbox"/> 8	
In-stream fish cover	<input checked="" type="checkbox"/> 7	
Embeddedness	<input checked="" type="checkbox"/> 5	
Invertebrate habitat	<input checked="" type="checkbox"/> 7	
Canopy Cover	<input checked="" type="checkbox"/> 9	
AMD (if applicable)	<input type="checkbox"/> N/A	
Sewage (if applicable)	<input checked="" type="checkbox"/> 4	
Manure presence (if applicable)	<input type="checkbox"/> N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>6.27</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR 7.5 - 8.9 = GOOD > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.		Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).		Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers											
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.			Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1		

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.	
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2		1	

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5	3      2	1

(4)

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream. Or Untreated human waste discharge pipes present.
	5      4	3      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names CB / KS Date: 06/11/07  
 Sub-Watershed BSC Stream Section Name BSC10 → BSC16  
 Stream Name BSC Reference Section \_\_\_\_\_

Weather Conditions Today mostly sunny, ~ 80°F Past 2-5 Days mostly sunny, rain on 6/8

Land use within drainage (%):					
Grazing Pasture		Grassy Field		Row Crops	
Forest	25	Residential	45	Industrial	25
Commercial	5	Abandoned Mine Lands		Other	

Substrate (%):							
Boulder		Cobble	25	Gravel	25	Silt	25
						Mud	

Active Channel Width: \_\_\_\_\_ meters Bedrock 25

Floodplain wetlands: Yes  No  Approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ (feet or meters)

Flooded areas? (Wetland or other) \_\_\_\_\_

pH \_\_\_\_\_ Conductivity \_\_\_\_\_

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**  
 Type of forest, farmland, residential, and/or commercial:  
residential and light industrial

GPS Waypoints				
	Latitude	Longitude	Photo # s	Description
Start	BSC10			Bridge @ ball park
End	BSC16			bend in stream w/ backwater
Other				
BSC11			1	undercut banks across from ball field. also (2) s.w. outfalls from road.
BSC12			3	6' high bank erosion / ~ 100' long & small trib. from under road / pH = 7.37
BSC13			4	24" Ø concrete pipe s.w. / cond = 620

Photographs	
Photo #	Description
2	<del>undercut banks @ BSC</del> dead sucker / ~ 20 suckers in stream
BSC14	debris jam
BSC15	36" concrete pipe (low flow / pH = 7.35 / cond = 730)
5-8	stream, kids

Discharges			
Size	Type	Waypoint	Photo #

Invasive plants present?  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter? Little

Parameter	Score	Explanation of Score Given
Channel condition	7	
Riparian zone	6	
Bank stability	7	
Water appearance	7	
Nutrient enrichment	5	
Fish barriers	7	
In-stream fish cover	7	
Embeddedness	5	
Invertebrate habitat	6	
Canopy Cover	8	
AMD (if applicable)	<input type="checkbox"/>	no discharges visible
Sewage (if applicable)	5	algae on substrate
Manure presence (if applicable)	<input type="checkbox"/>	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>6.36</u>	<p>&lt; 6.0 = POOR</p> <p>6.1 – 7.4 = FAIR</p> <p>7.5 – 8.9 = GOOD</p> <p>&gt; 9.0 = EXCELLENT</p>

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levies are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.		Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).		Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers											
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.			Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1		

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover											
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available			2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1		

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_



Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.	
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4	3	2	1			

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5	4	3      2      1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream. Or Untreated human waste discharge pipes present.
	5	4	3      2      1

**NOTES**

- fawn
- Cody and Jake Bluming w/ fish (sheepshead)

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names CB / KS Date: 06/05/07  
 Sub-Watershed Big Sewickley Creek Stream Section Name BSC 1 → BSC 9  
 Stream Name " " Reference Section " "  
 Weather Conditions Today light scattered rain, ~60°F Past 2-5 Days had rain showers

Land use within drainage (%):					
Grazing Pasture		Grassy Field		Row Crops	
Forest	5	Residential	10	Industrial	65
Commercial	20	Abandoned Mine Lands		Other	

Substrate (%):									
Boulder	5	Cobble	40	Gravel	15	Silt	25	Mud	15

Active Channel Width: 23 <sup>feet</sup> meters  
 Floodplain wetlands:  Yes  No Approximate size: Length BSC 8 / Width        (feet or meters) ~ 1 acre  
 Flooded areas? (Wetland or other)         
 pH        Conductivity       

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**  
 Type of forest, farmland, residential, and/or commercial:  
 - Industrial around R.R. tracks down to Ohio River.  
 - thin strip of forest along stream

BSC 7 - 18" CPP S.W. discharge / BSC 8 - floodplain wetland (photo - #12)

GPS Waypoints				
	Latitude	Longitude	Photo #s	Description
Start BSC 1			1, 2,	
End BSC 9				Bridge over stream at entrance to Park.
Other BSC 2			6	view downstream under old R.R. trestle (pH = 6.54 / cond. = 630)
BSC 3				pH = 6.87 / cond = 630
BSC 4			8	stormwater discharge under Beaver St. bridge
BSC 5			9	low dam
BSC 6				S.W. discharges (3) 2 15" CPP and 1 10" CPP

Photographs	
Photo #	Description
1, 2, 3, 4	Mouth of BSC @ confluence w/ Ohio River
5	Brownfield site on east side of BSC.
7	view upstream of Norfolk Southern R.R. Trestle
8	S.W. discharge under Beaver St. bridge
9	(1-2' high) low - man-made dam across stream (looks to be built by fisherman)

Discharges Photos			
Size #	Type	Waypoint	Photo #
11	Fishing hole against rock wall		15
	Shot upstream of riffle - pool sequences.		

Invasive plants present?  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other  
High on banks on both sides

Trash / Litter?

Parameter	Score	Explanation of Score Given
Channel condition	<input checked="" type="checkbox"/> 5	
Riparian zone	<input checked="" type="checkbox"/> 5	
Bank stability	<input checked="" type="checkbox"/> 7	
Water appearance	<input checked="" type="checkbox"/> 7	
Nutrient enrichment	<input checked="" type="checkbox"/> 5	
Fish barriers	<input checked="" type="checkbox"/> 7	
In-stream fish cover	<input checked="" type="checkbox"/> 7	
Embeddedness	<input checked="" type="checkbox"/> 7	
Invertebrate habitat	<input checked="" type="checkbox"/> 6	
Canopy Cover	<input checked="" type="checkbox"/> 8	
AMD (if applicable)	<input type="checkbox"/> N/A	
Sewage (if applicable)	<input checked="" type="checkbox"/> 5	
Manure presence (if applicable)	<input type="checkbox"/> N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>6.27</u>	<p>&lt; 6.0 = POOR                      6.1 – 7.4 = FAIR                      7.5 – 8.9 = GOOD                      &gt; 9.0 = EXCELLENT</p>

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition											
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levies are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1		

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability											
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1		

**Keys:** **All** outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.



Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers										
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness				
Gravel or cobble particles are <20% embedded.	Gravel or cobble particles are 20 to 30% embedded.	Gravel or cobble particles are 30 to 40% embedded.	Gravel or cobble particles are >40% embedded.	Completely embedded.
10	9	8	7	6
			5	4
				3
				2
				1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat				
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).	3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.	1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.	None to 1 type of habitat.	
10	9	8	7	6
			5	4
				3
				2
				1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover				
Key: This pertains to waterways where channel is 50 feet wide or less.				
Coldwater fishery				
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.	> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.	20 to 50% shaded.	<20% of water surface in reach shaded.	
10	9	8	7	6
			5	4
				3
				2
				1

Abandoned Mine Drainage (if applicable)				
(Intentionally blank)	Evidence of iron staining. Or Noticeable iron precipitate.	Iron precipitate visible, muddy orange appearance.	Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.	
	5	4	3	2
				1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5	4	3      2      1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5	4	3      2      1

**NOTES**

★ WCP - World Class processing, company located near mouth of BSC in Ohio River

- possible stream project @ Plum St. Park  
→ channel too wide / shallow



Parameter	Score	Explanation of Score Given
Channel condition	10	
Riparian zone	10	
Bank stability	8	
Water appearance	9	
Nutrient enrichment	9	
Fish barriers	8	
In-stream fish cover	8	
Embeddedness	9	
Invertebrate habitat	8	
Canopy Cover	9	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<sup>89/10</sup> <u>8.8</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR <u>7.5 - 8.9 = GOOD</u> > 9.0 = EXCELLENT



### Scoring Descriptions

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.	Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.	Natural vegetation extends one active channel width on each side.  Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side.  Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side.  Or Lack of regeneration.  Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.	Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness				
Gravel or cobble particles are <20% embedded.	Gravel or cobble particles are 20 to 30% embedded.	Gravel or cobble particles are 30 to 40% embedded.	Gravel or cobble particles are >40% embedded.	Completely embedded.
10	9	8 7 6	5 4	3 2 1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded:

Insect/invertebrate Habitat				
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).	3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.	1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.	None to 1 type of habitat.	
10	9	8	7 6 5 4	3 2 1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover				
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery				
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.	> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.	20 to 50% shaded.	<20% of water surface in reach shaded.	
10	9	8	7 6 5 4	3 2 1

Abandoned Mine Drainage (if applicable)				
(Intentionally blank)	Evidence of iron staining. Or Noticeable iron precipitate.	Iron precipitate visible, muddy orange appearance.	Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.	
	5	4	3	2 1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**





Parameter	Score	Explanation of Score Given
Channel condition	10	
Riparian zone	10	
Bank stability	9	
Water appearance	9	
Nutrient enrichment	7	
Fish barriers	9	
In-stream fish cover	9	
Embeddedness	8	
Invertebrate habitat	9	
Canopy Cover	10	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$90/10 =$ <u>9.0</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR 7.5 - 8.9 = GOOD <u>&gt; 9.0 = EXCELLENT</u>

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).		Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers											
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.			Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1		

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover											
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available			2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1		

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).		3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2			1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS/SA

Date: 5-13-08

Sub-Watershed Trib to EFBSC

Stream Section Name \_\_\_\_\_

Stream Name Behind Linbrook Park

Reference Section \_\_\_\_\_

Weather Conditions Today 70's Sunny

Past 2-5 Days 100's rainy

Active Channel Width: 2 feet Really shallow

### LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field		Row Crops	
Forest	<u>100</u>	Residential		Industrial	
Commercial		Abandoned Mine Lands		Other	

### SUBSTRATE (%):

Boulder	<u>5</u>	Cobble	<u>10</u>	Gravel	<u>70</u>	Silt	<u>10</u>	Mud	<u>5</u>
---------	----------	--------	-----------	--------	-----------	------	-----------	-----	----------

### DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

ALL FORESTED, HEADWATERS OFF HOPKINS CHURCH RD., FLOWS TO EAST FORK AT LINBROOK PARK

### GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
<u>E1 15</u>	<u>1/15</u>	<u>START / INT @ EFBSC</u>	<u>7.6</u>	<u>120</u>
<u>E1 16</u>	<u>2/16</u>	<u>END / headwaters - DRY</u>		
<del>E1 17</del>	<del>3/17</del>	<u>trib looking ↑ stream behind linbrook park</u>		

Invasive plants present:  Yes /  No     Japanese Knotweed     Garlic mustard     Purple loosestrife     Other

Trash / Litter: Yes /  No

Skunk bag

Floodplain wetlands:  Yes /  No    If so, approximate size: Length \_\_\_\_ / Width \_\_\_\_ feet

Flooded areas:  Yes /  No (Wetland or other)    Small

Notes: Really shallow, clear, no algae.

Parameter	Score	Explanation of Score Given
Channel condition	10	
Riparian zone	10	
Bank stability	9	
Water appearance	9	
Nutrient enrichment	9	
Fish barriers	7	
In-stream fish cover	9	
Embeddedness	8	
Invertebrate habitat	8	
Canopy Cover	9	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$\frac{88}{10} = 8.8$	< 6.0 = POOR 6.1 – 7.4 = FAIR 7.5 – 8.9 = GOOD > 9.0 = EXCELLENT

### Scoring Descriptions

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.	Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levies are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.	Natural vegetation extends one active channel width on each side.  Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side.  Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side.  Or Lack of regeneration.  Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.	Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)										
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.			
		5			4		3		2	1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



**Big Sewickley Creek Visual Assessment**

**Stream Section Name:** \_\_\_\_\_

**Date:** \_\_\_\_\_

<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names SA/CB Date: 8/28/07  
 Sub-Watershed E. Branch B.S.C. Stream Section Name EBBSC 28 → 33  
 Stream Name " Reference Section \_\_\_\_\_  
 Weather Conditions Today Sunny, ~80°F Past 2-5 Days mostly sunny  
 Active Channel Width: \_\_\_\_\_ feet

## LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field		Row Crops	
Forest	<del>60</del> 70	Residential	10	Industrial	
Commercial		Abandoned Mine Lands	<del>20</del>	Other	

## SUBSTRATE (%):

Boulder		Cobble	30	Gravel	30	Silt	40	Mud	
---------	--	--------	----	--------	----	------	----	-----	--

## DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

woods below / above I-79; new and old residential development in very top of the watershed.

## GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
28		START of new section		
29	6	Bridge and debris jam across channel		
30	7-09	Washed-out pipe X-ing / severely eroded * possible SWM property within sight of I-79		
31	10-11-03	Channel coming under I-79 / severe erosion / siltation. dumped concrete slabs.		
32		pH checks @ road crossing		
33	14	confluence of tribs that go under Neely <del> Rd.</del> School	7.80 / 800 → trib. up N. <del> Rd.</del> 7.73 / 900 → trib. <del> Rd.</del>	7.98 / 700 School
	15	Stm sewer covered by debris, causing erosion downstream		

Invasive plants present: Yes / No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other  
 Trash / Litter:  Yes / No  From I-79

Floodplain wetlands:  Yes / No  If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes: Good area for regional stormwater basin on-stream, immediately below I-79

Big Sewickley Creek Visual Assessment

Stream Section Name: EBBSC 27 + 35  
 Date: 8/28/07

Parameter	Score	Explanation of Score Given
Channel condition	3	
Riparian zone	8	
Bank stability	5	
Water appearance	7	
Nutrient enrichment	8	
Fish barriers	1	pipe X-ing @ w.p. 30
In-stream fish cover	4	
Embeddedness	5	
Invertebrate habitat	6	
Canopy Cover	9	
AMD (if applicable)	N/A	
Sewage (if applicable)	N/A	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>5.6</u>	< 6.0 = <b>POOR</b> 6.1 - 7.4 = FAIR 7.5 - 8.9 = GOOD > 9.0 = EXCELLENT

### Scoring Descriptions

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community <b>little algal growth present.</b>			Fairly clear or slightly greenish water along entire reach; <b>moderate algal growth</b> on stream substrates.			Greenish water along entire reach; <b>abundant algal growth</b> , especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms <b>create thick algal mats</b> in stream.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers										
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.			Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1	

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would **impede fish passage**.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available			2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other:

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less.										
Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4	3	2	1			

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



**Big Sewickley Creek Visual Assessment**

**Stream Section Name:** \_\_\_\_\_

EBBSC 28 → 35

**Date:** \_\_\_\_\_

8/29/17

<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names SA / CB Date: 08/28/07  
 Sub-Watershed East Br. BSC Stream Section Name EBBSC 25 → 27  
 Stream Name '' Reference Section \_\_\_\_\_  
 Weather Conditions Today sunny, ~80°F Past 2-5 Days mostly sunny  
 Active Channel Width: \_\_\_\_\_ feet

### LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field	<del>5</del> 10	Row Crops	
Forest	<del>0</del> 70	Residential	<del>0</del> 20	Industrial	
Commercial		Abandoned Mine Lands		Other	

### SUBSTRATE (%):

Boulder		Cobble		Gravel		Silt		Mud	
---------	--	--------	--	--------	--	------	--	-----	--

### DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

Grassy field / lawn areas by two private residences, along Geneva Rd.

### GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
25	2-3	START / HOME LANDOWNER / HOMES / bank erosion		
26	4-5	private bridge / plastic, white outlet (sewage?)		
27		END / end of mowed area, back into woods on both sides		

Invasive plants present: Yes / No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other  
 Trash / Litter: Yes  No  
 Floodplain wetlands: Yes / No  If so, approximate size: Length 50 / Width 50 feet  
 Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes: Spoke w/ landowner of second home. He said that the stream tears its banks frequently in this area, and it seems to happen more often since the township put in new storm sewers on the roads.

Parameter	Score	Explanation of Score Given
Channel condition	7	
Riparian zone	3	grass moved up to edge of stream
Bank stability	4	
Water appearance	6	
Nutrient enrichment	6	
Fish barriers	9	
In-stream fish cover	3	
Embeddedness	6	
Invertebrate habitat	5	
Canopy Cover	3	
AMD (if applicable)	N/A	
Sewage (if applicable)	5	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>5.2</u>	<p>&lt; 6.0 = POOR                      6.1 - 7.4 = FAIR                      7.5 - 8.9 = GOOD                      &gt; 9.0 = EXCELLENT</p>

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or if less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers										
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1	

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.	
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1		

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



**Big Sewickley Creek Visual Assessment**

**Stream Section Name:** EBBSC 25 → 27

**Date:** 8/28/07

<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names SA / CB Date: 08/14/07 <sup>8/28/07</sup>  
 Sub-Watershed East Branch BSC Stream Section Name EFBSC 8 → 24  
 Stream Name \_\_\_\_\_ Reference Section \_\_\_\_\_  
 Weather Conditions Today Sunny, ~ 75°F Past 2-5 Days heavy rain last Th.  
 Active Channel Width: 6-8 feet

## LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field		Row Crops	
Forest	90	Residential	10	Industrial	
Commercial		Abandoned Mine Lands		Other	

## SUBSTRATE (%):

Boulder	5	Cobble	30	Gravel	20	Silt/sand	25	Bedrock	20
---------	---	--------	----	--------	----	-----------	----	---------	----

## DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

State Game Land, Route 79, Game Land Rd., shooting range, forested

## GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
EF8(1)		private bridge		
9	1	concrete slabs streambank stabilization		
10	2	metal line (gas?) crossing stream in air		
11		small trib coming in from the east		580
12	3	tree down, debris jam		
13	4	horse access to stream channel.		
14	5	Trees down across stream in two (2) places		
15		stormwater runoff from int. of roads above.		
16		trib. from west		
17		fork in trib. (similar flows) * main stream chert → 950		trib. → 910
	7	gas liner (metal) cross-crossing stream channel.		
18	8	CMP culvert under game land access road (blocks fish passage)		
	9	wetland plant (~ 5' tall)		
	10	trees chewed by beaver, near gas pipeline.		
19	11	bank erosion / tree jam / sand bar.		
	12	shale wall		
20	13	beaver dam? across from shooting range.		
	14	frisbee on stick.		
	15	concrete cylinder used for bank stabilization		
21		(END OF DAY 8/14)		
22	1	culvert crossing for game land entrance - d.s. erosion.		
23		TRIB from across the road	7.69	200

Invasive plants present: Yes (No)  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes / No not much, few tires near parking area in top of section.

Floodplain wetlands: Yes / No If so, approximate size: Length \_\_\_ / Width \_\_\_ feet [btw 16-17]

Flooded areas: Yes / No (Wetland or other) flood plain

Notes:

24 - end of section / trib. from across the road  
 (photo ~~the~~)

pH 7.03 Cond. 410

Parameter	Score	Explanation of Score Given								
Channel condition	9									
Riparian zone	10									
Bank stability	9									
Water appearance	8									
Nutrient enrichment	8									
Fish barriers	7									
In-stream fish cover	9									
Embeddedness	8									
Invertebrate habitat	9									
Canopy Cover	10									
AMD (if applicable)	N/A									
Sewage (if applicable)	N/A									
Manure presence (if applicable)	N/A									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	87	<table border="0"> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 - 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 - 8.9</td> <td>= <b>GOOD</b> +</td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 - 7.4	= FAIR	7.5 - 8.9	= <b>GOOD</b> +	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 - 7.4	= FAIR									
7.5 - 8.9	= <b>GOOD</b> +									
> 9.0	= EXCELLENT									

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levies are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.
10	9	8	7	6	5	4	3	2	1	

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.		Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available		4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.				Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.
10	9	8	7	6	5	4	3	2	1	

Keys: Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.				1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1	

Cover types: Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less.										
Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.				20 to 50% shaded.		<20% of water surface in reach shaded.	
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)													
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.				Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.					
N/A		5				4		3		2		1	

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

EAST  
FORK

Evaluators' Names KS/SA

Date: 7/13 & 7/24/07

Sub-Watershed \_\_\_\_\_ Stream Section Name EAST FORK BSC EFBSC1-7

Stream Name EAST FORK BSC Reference Section \_\_\_\_\_

Weather Conditions Today \_\_\_\_\_ Past 2-5 Days \_\_\_\_\_

Active Channel Width: 20 feet

**LAND USE WITHIN DRAINAGE (%):**

Grazing Pasture		Grassy Field		Row Crops	
Forest		Residential		Industrial	
Commercial		Abandoned Mine Lands		Other	

**SUBSTRATE (%):**

Boulder		Cobble		Gravel		Silt		Mud	
---------	--	--------	--	--------	--	------	--	-----	--

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

EFBSC 1 Start (on east side BSC) **GPS POINTS / PHOTOS:**

Waypoint	Photo	Description	pH	Cond.
<del>EFBSC 2</del>	<del>12</del>	<del>Debris Tree Jam</del>		
<del>EFBSC 3</del>	<del>13</del>	<del>Park</del>		
EFBSC 4(8)	13	Downing Trib (Day)		
5	14	Downing Trib (Day) / Tree Limbs		
6	15	Trib (Clipping Run 22)		
7		Endpoint / bridge		

Invasive plants present: Yes / No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes / No \_\_\_\_\_

Floodplain wetlands: Yes / No If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes:

Parameter	Score	Explanation of Score Given
Channel condition	8 9	
Riparian zone	8 9	
Bank stability	7 8	
Water appearance	8	
Nutrient enrichment	8	
Fish barriers	7	
In-stream fish cover	8	
Embeddedness	8	
Invertebrate habitat	9	
Canopy Cover	8	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	82/10 <u>8.2</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR 7.5 - 8.9 = GOOD > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.		Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available		4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).		3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
			5	4			3	2	1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS / CB Date: 02 / 07 / 08  
 Sub-Watershed NFBSC Stream Section Name NF 46-9 56  
 Stream Name UNT to NFBSC Reference Section \_\_\_\_\_  
 Weather Conditions Today scattered light snow ~35°F Past 2-5 Days rain, snow  
 Active Channel Width: ~4 feet

LAND USE WITHIN DRAINAGE (%):									
Grazing Pasture		Grassy Field	✓	10	Row Crops				
Forest	✓	75	Residential	✓	15	Industrial			
Commercial			Abandoned Mine Lands			Other			
SUBSTRATE (%):									
Boulder		Cobble	40	Gravel	40	Silt	20	Mud	
DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:									
Mostly forested area with homes on hillside above the stream valley. sewer line running up stream valley. <del>Abundant</del> Abundant wildlife sign including deer.									
GPS POINTS / PHOTOS:									
Waypoint	Photo	Description	pH	Cond.					
1	NF 46	Near confluence w/ main stem	7.65	480					
	1	small concrete structure w/ discharge pipe near road							
2	NF 47	bank erosion (~30' long)							
3	NF 48	small trib. from hollow/wetland (some bank erosion)	7.34	410					
	4	big wetland in flood plain on posted ground							
4	NF 49	Trib. flowing in from east; open field / lawn area	7.49	1360					
5	NF 50	Trib. cascading down hill from the west	7.59	60					
6	NF 51	small trib. flowing in from east, beside big homes	7.53	770					
	7	SWM outlet pipe (~18" spp) road							
7	NF 52	confluence w/ trib. from west end old <del>road</del> X-ing	7.58	210					
		Severe erosion around 36" concrete pipe (not large enough for stream flow)							
8	NF 53	S.W.M. outlet							
9	NF 54	rock flow structure (or) in stream behind log house							
		small trib. from east	7.54	580					
10	NF 55	confluence with trib. from the north	7.56	610					
11	NF 56	SWM outlet to stream (15" spp) near X-ing under road							
	13	E.S. basin at cul-de-sac in "Whispering Pines" development							
	14	view upstream between E.S. basins							
		and road							

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes /  No

Floodplain wetlands  Yes / No  If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet

Flooded areas: Yes / No (Wetland or other) Large wetland

Notes:

Parameter	Score	Explanation of Score Given								
Channel condition	8									
Riparian zone	9									
Bank stability	7									
Water appearance	7									
Nutrient enrichment	9									
Fish barriers	8									
In-stream fish cover	7									
Embeddedness	7									
Invertebrate habitat	8									
Canopy Cover	9									
AMD (if applicable)	N/A									
Sewage (if applicable)	N/A									
Manure presence (if applicable)	N/A									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$79 \div 10$ <u>7.9</u>	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 - 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 - 8.9</td> <td>= <u>GOOD</u></td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 - 7.4	= FAIR	7.5 - 8.9	= <u>GOOD</u>	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 - 7.4	= FAIR									
7.5 - 8.9	= <u>GOOD</u>									
> 9.0	= EXCELLENT									

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available		4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness				
Gravel or cobble particles are <20% embedded.	Gravel or cobble particles are 20 to 30% embedded.	Gravel or cobble particles are 30 to 40% embedded.	Gravel or cobble particles are >40% embedded.	Completely embedded.
10 9	8 7 6	5 4	3 2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat				
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).	3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.	1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.	None to 1 type of habitat.	
10 9	8 7 6 5 4	3 2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover				
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery				
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.	> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.	20 to 50% shaded.	<20% of water surface in reach shaded.	
10 9	8 7 6 5 4	3 2	1	

Abandoned Mine Drainage (if applicable)				
(Intentionally blank)  N/A	Evidence of iron staining. Or Noticeable iron precipitate.	Iron precipitate visible, muddy orange appearance.	Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.	
	5 4	3 2	1	

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Big Sewickley Creek Visual Assessment

Stream Section Name: MF 46-9 56

Date: 02/07/08

Sewage (if applicable)			
(Intentionally blank)  N/A	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth.  And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)  N/A	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS / CB Date: 02/07/08  
 Sub-Watershed NFBSC Stream Section Name NF57 → NF61  
 Stream Name UNT to NFBSC. Reference Section \_\_\_\_\_  
 Weather Conditions Today overcast scattered snow Past 2-5 Days rain, snow  
 Active Channel Width: 3-4 feet

LAND USE WITHIN DRAINAGE (%):			
Grazing Pasture		Grassy Field	✓ 10
Forest	✓ 80	Residential	✓ 10
Commercial		Abandoned Mine Lands	
		Row Crops	
		Industrial	
		Other	

SUBSTRATE (%):							
Boulder		Cobble	40	Gravel	40	Silt	20
							Mud

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**

Forested area stream draining from pond on old farm at top of this sub watershed. very steep with hemlock trees and ferns on the slopes. New sewage line installed down stream valley.

**GPS POINTS / PHOTOS:**

Waypoint	Photo	Description	pH	Cond.
W1NF57	14	small trib. from north	7.66	690
	15	views <del>down</del> down stream valley		
W1NF58	16	Fallen trees across stream channel		
W2NF59	17	small trib from South	7.93	230
W2NF60	18	cote oven? in hillside along stream		
W1NF61		Near mouth of stream @ X-ing under main Road	7.80	380

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other \_\_\_\_\_  
 Trash / Litter: Yes  No   
 Floodplain wetlands  Yes / No  If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet  
 Flooded areas:  Yes / No  (Wetland or other) immediately adjacent to stream and sewer line

Notes:  
 - Silt fence still in place all the way down stream valley needs removed.  
 - Hemlock / ferns on hillside

Parameter	Score	Explanation of Score Given								
Channel condition	8									
Riparian zone	8									
Bank stability	8									
Water appearance	8									
Nutrient enrichment	7									
Fish barriers	9									
In-stream fish cover	6									
Embeddedness	8									
Invertebrate habitat	9									
Canopy Cover	8									
AMD (if applicable)	N/A									
Sewage (if applicable)	N/A									
Manure presence (if applicable)	N/A									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$79 \div 10$ <u>7.9</u>	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 - 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 - 8.9</td> <td>= <u>GOOD</u></td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 - 7.4	= FAIR	7.5 - 8.9	= <u>GOOD</u>	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 - 7.4	= FAIR									
7.5 - 8.9	= <u>GOOD</u>									
> 9.0	= EXCELLENT									

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.
10	9	8	7	6	5	4	3	2	1	

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.		Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers											
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.			Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1		

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.				1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.				20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)  N/A		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1		

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Big Sewickley Creek Visual Assessment

Stream Section Name:

NF57 → 61

Date:

02/07/08

Sewage (if applicable)			
(Intentionally blank)  N/A	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth.  And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)  N/A	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



Parameter	Score	Explanation of Score Given								
Channel condition	5									
Riparian zone	7									
Bank stability	7									
Water appearance	7									
Nutrient enrichment	8									
Fish barriers	6									
In-stream fish cover	4									
Embeddedness	6									
Invertebrate habitat	6									
Canopy Cover	7									
AMD (if applicable)	N/A									
Sewage (if applicable)	N/A									
Manure presence (if applicable)	N/A									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$63 \div 10$ <u>6.3</u>	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 - 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 - 8.9</td> <td>= GOOD</td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 - 7.4	= FAIR	7.5 - 8.9	= GOOD	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 - 7.4	= FAIR									
7.5 - 8.9	= GOOD									
> 9.0	= EXCELLENT									

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded:

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)  N/A		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4	3	2	1			

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)  N/A	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth.  And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)  N/A	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names CB / KS Date: 03/24/08  
 Sub-Watershed NFBSC Stream Section Name NF 62 → 76  
 Stream Name UNT to NFBSC Reference Section \_\_\_\_\_  
 Weather Conditions Today mostly sunny, ~40°F Past 2-5 Days light snow  
 Active Channel Width: \_\_\_\_\_ feet

## LAND USE WITHIN DRAINAGE (%):

Grazing Pasture	10	Grassy Field	-	Row Crops	0
Forest	75	Residential	15	Industrial	-
Commercial	-	Abandoned Mine Lands	-	Other	-

## SUBSTRATE (%):

Boulder	10	Cobble	25	Gravel	25	Silt	30	Mud	10
---------	----	--------	----	--------	----	------	----	-----	----

## DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

## GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
NF 62		start; bridge @ main road	7.90	350
NF 63	1	debris jam in stream		
NF 64	2	stream jumped banks @ recent flood.		
NF 65		small trib. from east	7.81	230
NF 66	3	Large trib. from the west.	7.56	420
	4	skid stream at small waterfall		
NF 67		small stream from hunkles to the east.	8.06	150
NF 68		Sediment deposits in channel @ ATV trail X-ing.		
	6	Bank slide / debris jam.		
NF 69	7	Bully erosion from farm lane into stream		
		Large trib. from east	7.82	260
NF 70	8	Debris jam at intersection w/ old road.		
NF 71		Major Trib. from the west	7.58	360
NF 72		small trib from east / debris jam	7.68	180
NF 73		trib from East	7.76	460
NF 74		main stem water quality check	7.78	580
NF 75	9	small trib. below pond. / pond silting-in.	7.67	840
	10	old farm windmill.		
NF 76		Endpoint; X-ing under road near where we parked	7.81	470
NF 77	11	ATV trails / Right of way / new bridge with mud parked into stream		
NF 78	12	15" Ø SPP for X-ing		
NF 79	13	wetland / bival area → top of sub watershed.		

Invasive plants present: Yes/No  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes / No not much, some near top of section where

Floodplain wetlands: Yes / No If so, approximate size: Length \_\_\_ / Width \_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes: → Sewage Auth. needs to come back and collect all of their silt fence.  
 → Need to check soil types in this area to see why so much erosion.

Parameter	Score	Explanation of Score Given								
Channel condition	4									
Riparian zone	9									
Bank stability	3									
Water appearance	7									
Nutrient enrichment	8									
Fish barriers	3									
In-stream fish cover	7									
Embeddedness	5									
Invertebrate habitat	8									
Canopy Cover	8									
AMD (if applicable)	N/A									
Sewage (if applicable)	N/A									
Manure presence (if applicable)	N/A									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$\frac{62}{10}$ 6.2	<table border="0"> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 - 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 - 8.9</td> <td>= GOOD</td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 - 7.4	= FAIR	7.5 - 8.9	= GOOD	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 - 7.4	= FAIR									
7.5 - 8.9	= GOOD									
> 9.0	= EXCELLENT									

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.		Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).		Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat											
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.				1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1		

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.				20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)  N/A		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1		

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Big Sewickley Creek Visual Assessment

Stream Section Name: \_\_\_\_\_

Date: \_\_\_\_\_

NF 62 → 76

~~03/27/08~~  
03/24/08

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
N/A			
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
N/A			
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS/SA Date: 5-13-08

Sub-Watershed \_\_\_\_\_ Stream Section Name \_\_\_\_\_

Stream Name left trib to North Fork Reference Section \_\_\_\_\_

Weather Conditions Today 70's Sunny Past 2-5 Days 60's rain

Active Channel Width: 1-3 feet

LAND USE WITHIN DRAINAGE (%):									
Grazing Pasture		Grassy Field		Row Crops					
Forest	<u>95</u>	Residential	<u>5</u>	Industrial					
Commercial		Abandoned Mine Lands		Other					
SUBSTRATE (%):									
Boulder	<u>5</u>	Cobble	<u>5</u>	Gravel	<u>80</u>	Silt	<u>5</u>	Mud	<u>5</u>
DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:									
<u>All forested, where it meets NFBSC there is one homeowner, goes under Hocnig Rd &amp; through field where they've planted trees</u>									
GPS POINTS / PHOTOS:									
Waypoint	Photo	Description						pH	Cond.
<u>W1 8</u>	<u>1</u>	<u>INT OF TRIB &amp; NORTH FORK</u>						<u>7.71</u>	<u>320</u>
<u>W2 9</u>		<u>Dcb's Jam</u>							
<u>W3 10</u>		<u>Dcb's Jam</u>							
<u>W4 11</u>	<u>2,3</u>	<u>Headwater area</u>						<u>7.61</u>	<u>260</u>

Invasive plants present:  Yes /  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes /  No

Floodplain wetlands:  Yes /  No If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet

Flooded areas:  Yes /  No (Wetland or other) \_\_\_\_\_

Notes: Small areas  
Stream is very clear, no algae

Parameter	Score	Explanation of Score Given								
Channel condition	10									
Riparian zone	10									
Bank stability	9									
Water appearance	10									
Nutrient enrichment	9									
Fish barriers	9									
In-stream fish cover	9									
Embeddedness	9									
Invertebrate habitat	9									
Canopy Cover	10									
AMD (if applicable)	NA									
Sewage (if applicable)	NA									
Manure presence (if applicable)	NA									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$\frac{9 \times 10}{10} = 9.4$	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 - 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 - 8.9</td> <td>= GOOD</td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 - 7.4	= FAIR	7.5 - 8.9	= GOOD	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 - 7.4	= FAIR									
7.5 - 8.9	= GOOD									
> 9.0	= EXCELLENT									

### Scoring Descriptions

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition										
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.	Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.					Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
<b>10</b>	9	8	7	6	5	4	3	2	1	

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.	Natural vegetation extends one active channel width on each side.  Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side.  Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side.  Or Lack of regeneration.  Or Filtering function severely compromised.	
<b>10</b>	9	8	7	6	5	4	3	2	1	

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.	Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.				Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	<b>9</b>	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.	Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).	3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.				1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.			None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less.									
Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.	>.50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.				20 to 50% shaded.			<20% of water surface in reach shaded.	
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)	Evidence of iron staining. Or Noticeable iron precipitate.				Iron precipitate visible, muddy orange appearance.			Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.	
	5	4	3	2	1				

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



<b>Sewage (if applicable)</b>			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

<b>Manure Presence (if applicable)</b>			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS/CB Date: 01/31/08  
 Sub-Watershed NFBSC Stream Section Name NF 40 → 45  
 Stream Name NFBSC Reference Section \_\_\_\_\_  
 Weather Conditions Today overcast, ~25°F Past 2-5 Days scattered rain/snow  
 Active Channel Width: 3-4 feet

### LAND USE WITHIN DRAINAGE (%):

Grazing Pasture	✓	Grassy Field	✓	10	Row Crops	
Forest	✓	Residential	✓	15	Industrial	
Commercial		Abandoned Mine Lands			Other	

### SUBSTRATE (%):

Boulder		Cobble	25	Gravel	40	Silt	25	Mud	10
---------	--	--------	----	--------	----	------	----	-----	----

### DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

residential, wooded lots, Commercial park at top of watershed.

### GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
NF 40	16	Int. of Woodlawn, Pleasant Hill, Lovi, & Golden Grove Rd. @ drain under Lovi Rd. →	7.80	1170
NF 41	17	debris jam in channel (landowner dumped yard waste)		
NF 42	18	possible old pond breach, downstream erosion/sedimentation		
NF 43	19	very black stream bottom, sewage?		
NF 44	20	confluence with tributary	7.60	950
NF 45	21	plastic geomembrane below bridge crossing		
		* working from top of sub-watershed down.		

Invasive plants present: Yes / No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter:  Yes / No yard waste, litter from road intersection

Floodplain wetlands:  Yes / No If so, approximate size: Length \_\_\_ / Width \_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes:



Parameter	Score	Explanation of Score Given								
Channel condition	6									
Riparian zone	7									
Bank stability	6									
Water appearance	6									
Nutrient enrichment	6									
Fish barriers	5									
In-stream fish cover	5									
Embeddedness	6									
Invertebrate habitat	7									
Canopy Cover	8									
AMD (if applicable)	N/A									
Sewage (if applicable)	N/A									
Manure presence (if applicable)	N/A									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$62 \div 10$ <u>6.2</u>	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 - 7.4</td> <td><b>FAIR</b></td> </tr> <tr> <td>7.5 - 8.9</td> <td>= GOOD</td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 - 7.4	<b>FAIR</b>	7.5 - 8.9	= GOOD	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 - 7.4	<b>FAIR</b>									
7.5 - 8.9	= GOOD									
> 9.0	= EXCELLENT									

### Scoring Descriptions

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition											
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1		

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side.  Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side.  Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side.  Or Lack of regeneration.  Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability											
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1		

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers											
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.			Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1		

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover											
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available			2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1		

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded:

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1		

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names CB / KS Date: 1/31/08  
 Sub-Watershed NF BSC Stream Section Name NF BSC 32 → 39  
 Stream Name NF BSC Reference Section \_\_\_\_\_  
 Weather Conditions Today overcast, ~25°F Past 2-5 Days scattered rain / snow  
 Active Channel Width: 4-5 feet

LAND USE WITHIN DRAINAGE (%):					
Grazing Pasture			Grassy Field	✓	15
Forest	✓	50	Residential	✓	15
Commercial		20	Abandoned Mine Lands		
			Row Crops		
			Industrial		
			Other		

SUBSTRATE (%):							
Boulder		Cobble	40	Gravel	40	Silt	20
						Mud	

**DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:**

Back yards of residential; large wooded lots, Thorn Hill Ind. Park at top of watershed with two large SWM basins @ headwaters. Areas along stream channel were cleared for sewage line (Economy Bow) that were put in 3-4

**GPS POINTS / PHOTOS:** year ago.

Waypoint	Photo	Description	pH	Cond.
32		start point		
33	1	Confluence of tribs. / wetland along sewage line <small>small trib.</small>	6.8	1130
			<small>MAIN STEM →</small>	1380
34	2	small debris jam from firewood falling into stream		
35		18" Ø SPP outlet from road drainage system		
36	3 4	Confluence with small trib.	8.08	580 *
	5	pipe / driveway X-ing (~4 of them in this stretch)		
	6	raft drain energy dissipator		
37	7-8	"old school" bank stabilization (block walls failing)		
38	9	S.W.M. pond outlet from Ind. Park		
	10	- spillway needs rocks - water in pond		
11-12		huge buck rubs		
	13	Bigger S.W.M. pond (frozen)		
39	14-15	Large pond below Tri-County Soccer Facility		
		streambank erosion outlet pipe (below)		
		also small STP w/ discharge →	7.70	640
	3	residential bank stabilization		

Invasive plants present: Yes / No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: (Yes) No glass dump between ~~NF 34~~ pond and STP @ NF 39

Floodplain wetlands: Yes / No If so, approximate size: Length \_\_\_ / Width \_\_\_ feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes:

Parameter	Score	Explanation of Score Given
Channel condition	6	
Riparian zone	6	sewer line installation
Bank stability	7	
Water appearance	7	
Nutrient enrichment	6	'Black' growth on rocks on substrate
Fish barriers	5	multiple driveway crossings near NF 36
In-stream fish cover	5	
Embeddedness	8	
Invertebrate habitat	7	
Canopy Cover	8	
AMD (if applicable)	N/A	
Sewage (if applicable)	N/A	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$65 \div 10$ <u>6.5</u>	<p>&lt; 6.0 = POOR                      6.1 - 7.4 = FAIR                      7.5 - 8.9 = GOOD                      &gt; 9.0 = EXCELLENT</p>

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition											
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	8	7	6	5	4	3	2	1		

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability											
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	9	8	7	6	5	4	3	2	1		

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers										
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1	

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover										
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1	

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded:

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less.										
Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)										
(Intentionally blank)  N/A		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.			
		5			4		3		2	
									1	

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)  N/A	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth.  And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)  N/A	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names CB / SA Date: 10/31/07

Sub-Watershed Nick Fork BSC Stream Section Name NFBSC 23 → 31

Stream Name " Reference Section "

Weather Conditions Today sunny, breezy, ~65°F Past 2-5 Days sunny, ~55°F as high

Active Channel Width: ~10 feet

LAND USE WITHIN DRAINAGE (%):				
Grazing Pasture		Grassy Field	10	Row Crops
Forest	50	Residential	40	Industrial
Commercial		Abandoned Mine Lands		Other
SUBSTRATE (%):				
Boulder		Cobble		Mud
		Gravel		Silt
DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:				
This stream section runs through forested areas that are bound by sparsely populated residential areas with large lot sizes and a lot of green space.				
GPS POINTS / PHOTOS:				
Waypoint	Photo	Description	pH	Cond.
23	4	start: big pond w/ bridge to private home		
	5-7	beavers (cleared trees and "drag path" to pond)		
24		debris / tree jam		
25		trib. from the right.		
26		debris / tree jam		
27		trib. from the left	7.88	670
28		" " " "		
29		trib. from the left.		
30		debris / tree jam.		
31		End of section @ bridge over Bradford Park Rd.		
		near int. w/ Summerfield Dr.		
	8	cover shot downstream		

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes  No

Floodplain wetlands: Yes  No  If so, approximate size: Length \_\_\_ / Width \_\_\_ feet

Flooded areas: Yes  No  (Wetland or other) \_\_\_

Notes: ducks, deer, beaver evidence, large hawk or owl?  
 ↳ mallards and others  
 Landowners have kept stream bottom clean and managed for conservation.  
 \* jumped nice buck just below Bradford Park Rd.

Parameter	Score	Explanation of Score Given								
Channel condition	7									
Riparian zone	9									
Bank stability	9									
Water appearance	8									
Nutrient enrichment	8									
Fish barriers	7									
In-stream fish cover	8									
Embeddedness	8									
Invertebrate habitat	9									
Canopy Cover	10									
AMD (if applicable)	N/A									
Sewage (if applicable)	N/A									
Manure presence (if applicable)	N/A									
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$\frac{83}{10} = 8.3$	<table> <tr> <td>&lt; 6.0</td> <td>= POOR</td> </tr> <tr> <td>6.1 – 7.4</td> <td>= FAIR</td> </tr> <tr> <td>7.5 – 8.9</td> <td>= <b>GOOD</b></td> </tr> <tr> <td>&gt; 9.0</td> <td>= EXCELLENT</td> </tr> </table>	< 6.0	= POOR	6.1 – 7.4	= FAIR	7.5 – 8.9	= <b>GOOD</b>	> 9.0	= EXCELLENT
< 6.0	= POOR									
6.1 – 7.4	= FAIR									
7.5 – 8.9	= <b>GOOD</b>									
> 9.0	= EXCELLENT									

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).		Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available		4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded:

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).		3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)										
(Intentionally blank)  N/A		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.			
		5			4		3		2	1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)  N/A	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth.  And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)  N/A	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS / SA / CB Date: 10-8-07 & 10/31/07  
 Sub-Watershed \_\_\_\_\_ Stream Section Name NFBSC 15 → 22  
 Stream Name NORTH FORK Reference Section \_\_\_\_\_  
 Weather Conditions Today 70'S, CLOUDY Past 2-5 Days Sunny, ~ 55° F avg.  
 Active Channel Width: 20 feet

LAND USE WITHIN DRAINAGE (%):									
Grazing Pasture		Grassy Field	10	Row Crops					
Forest	70	Residential	20	Industrial					
Commercial		Abandoned Mine Lands		Other					
SUBSTRATE (%):									
Boulder		Cobble	25	Gravel	20	Silt	15	Bedrock	40
DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:									
sparsely residential with large lot sizes/acreage, steep, wooded hillsides.									
GPS POINTS / PHOTOS:									
Waypoint	Photo	Description	pH	Cond.					
NFBSC 15		START / TRIB ON LEFT (NEW SECT. DUE TO LESS ALGAE)	7.0	670					
NFBSC 16	13	BROOK / TRIB ON RIGHT							
NFBSC 17		END OF DAY / HOMEOWNER BRIDGE							
	1	shot upstream							
18		small trib. from the right							
19	2	shale cliffs along stream							
20		floodplain wetland (near int. w/ Conway-Walrose Rd.)							
21		confluence w/ trib. from left / west	7.94	770					
22	3	bad bridge (2 small pipes)							

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter: Yes / No very little

Floodplain wetlands:  Yes / No  If so, approximate size: Length 400 / Width 500 feet

Flooded areas: Yes / No (Wetland or other) \_\_\_\_\_

Notes:

Parameter	Score	Explanation of Score Given
Channel condition	8	
Riparian zone	8	
Bank stability	8	
Water appearance	8	
Nutrient enrichment	7	
Fish barriers	9	
In-stream fish cover	8	
Embeddedness	8	
Invertebrate habitat	8	
Canopy Cover	9	
AMD (if applicable)	N/A	
Sewage (if applicable)	N/A	
Manure presence (if applicable)	N/A	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	$\frac{8.1}{1}$	< 6.0 = POOR 6.1 – 7.4 = FAIR 7.5 – 8.9 = GOOD > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

Keys: look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.
10	9	8	7	6	5	4	3	2	1	

Keys: Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

Keys: **All** outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance											
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.			Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment											
Clear water along entire reach; diverse aquatic plant community little algal growth present.			Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.		
10	9	8	7	6	5	4	3	2	1		

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers											
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.			Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1		

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover											
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available			2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1		

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).			3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.		
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.			> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.		
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)  N/A		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.		
		5	4		3	2	1		

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)  N/A	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth.  And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)  N/A	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

NRUP  
York  
Schiller

Assessors' Names KS/SA Date: 10-4-07  
 Sub-Watershed \_\_\_\_\_ Stream Section Name 10/8/07  
 Stream Name BIG SEWICKLEY NORTH FORK Reference Section \_\_\_\_\_  
 Weather Conditions Today 80'S Past 2-5 Days SAME DRY  
 Active Channel Width: 35 feet

## LAND USE WITHIN DRAINAGE (%):

Grazing Pasture		Grassy Field	20	Row Crops	
Forest	60	Residential	20	Industrial	
Commercial		Abandoned Mine Lands		Other	

## SUBSTRATE (%):

<del>BEDROCK</del> Boulder	15	Cobble	20	Gravel	50	Silt	10	Mud	5
-------------------------------	----	--------	----	--------	----	------	----	-----	---

## DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:

## GPS POINTS / PHOTOS:

Waypoint	Photo	Description	pH	Cond.
NFBSC 01		START / Algae	8.01	530
NFBSC 02	1	concrete debris		
NFBSC 03	2/3	Bedrock outcrops / tons of fish / around bend		
NFBSC 04	4	Looking downstream - wrap channel / bedrock / lots fish		
NFBSC 05	5	Debris Jam		
NFBSC 06	6	Tree down		
NFBSC 07	7	Debris Jam		
NFBSC 08	8	Trib from across Hornig Rd.	7.92	530
NFBSC 09	9	Bank erosion near houses		
NFBSC 10	9	END 10/4/07		
NFBSC 11	10	START (cont) Eroded Bank / Debris Jam by houses		
NFBSC 12	11	Debris Jam		
NFBSC 13		Trib on left / Debris Jam	7.58	540
NFBSC 14	12	Debris Jam		
NFBSC 15		Trib on left	7.0	670
NFBSC 16	13	brook / trib on right		
NFBSC 17		end / bridge (home garden driveway)		

Deep  
Stonet

Invasive plants present: Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other  
 Trash / Litter: Yes  No   
 Floodplain wetlands: Yes  No  If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet  
 Flooded areas: Yes  No  (Wetland or other) \_\_\_\_\_

Notes: WIDE channel, lots of sand bar areas off to side, backchannels cut out for extra flow events

Parameter	Score	Explanation of Score Given
Channel condition	9	
Riparian zone	9	
Bank stability	8	
Water appearance	9	
Nutrient enrichment	7	Algae but NO sewer odors, not many homes along stretch
Fish barriers	9	
In-stream fish cover	9	
Embeddedness	9	
Invertebrate habitat	9	
Canopy Cover	9	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<u>87</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR 7.5 - 8.9 = <u>GOOD</u> > 9.0 = EXCELLENT 8.7 <sup>+</sup>

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).		Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.	Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).	3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.			
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.	> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.			
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)	Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.			
	5	4		3	2				1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS/SA Date: 5-1-08  
 Sub-Watershed South trib 2 to RR Stream Section Name \_\_\_\_\_  
 Stream Name Pippling Run Reference Section \_\_\_\_\_  
 Weather Conditions Today 70's Rain/Sun Past 2-5 Days 100's Rain  
 Active Channel Width: 3-4 feet

LAND USE WITHIN DRAINAGE (%):				
Grazing Pasture	<u>10</u>	Grassy Field	<u>10</u>	Row Crops
Forest	<u>65</u>	Residential	<u>15</u>	Industrial
Commercial		Abandoned Mine Lands		Other

SUBSTRATE (%):				
Boulder		Cobble	<u>20</u>	Gravel
			<u>75</u>	Silt
				Mud

DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:  
MOSTLY FORESTED, A FEW HOMES/PASTURES

GPS POINTS / PHOTOS:				
Waypoint	Photo	Description	pH	Cond.
RR 74		Start		
RR 15		Homeowners by stream		
RR 16		End @ Road <span style="float: right;">of RR trib</span>		
	1	End looking upstream headwaters ↑ looking upstream		
	2	Wetlands @ same spot		
		Conservation area @ top		
RR 17		End of other trib		

Invasive plants present:  Yes  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other

Trash / Litter:  Yes  No Skunk cabbages

Floodplain wetlands:  Yes  No If so, approximate size: Length \_\_\_\_\_ / Width \_\_\_\_\_ feet 1/2 acre by road near top

Flooded areas:  Yes  No (Wetland or other) \_\_\_\_\_

Notes: Also 1/2 acre near confluence w/ RR.

Parameter	Score	Explanation of Score Given
Channel condition	8	
Riparian zone	8	
Bank stability	9	
Water appearance	9	
Nutrient enrichment	9	
Fish barriers	8	
In-stream fish cover	8	
Embeddedness	9	
Invertebrate habitat	8	
Canopy Cover	9	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	85  <u>8.5</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR 7.5 - 8.9 = GOOD > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition											
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.			Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levies are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.		
10	9	(8)	7	6	5	4	3	2	1		

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	(8)	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability											
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).		
10	(9)	8	7	6	5	4	3	2	1		

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

Keys: Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

Keys: Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

Keys: You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

Cover types: Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.	Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).	3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.			
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.	> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.			
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)									
(Intentionally blank)	Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.			
	5	4	3	2	1				

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.



Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



Parameter	Score	Explanation of Score Given
Channel condition	9	
Riparian zone	9	
Bank stability	8	
Water appearance	9	
Nutrient enrichment	8	
Fish barriers	8	
In-stream fish cover	8	
Embeddedness	8	
Invertebrate habitat	8	
Canopy Cover	9	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	<sup>84</sup> <u>8.4</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR <u>7.5 - 8.9 = GOOD</u> > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <b>aggradation</b> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone									
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.		Natural vegetation extends half of the active channel width on each side.		Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.		Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bare bank, numerous mature trees falling into stream annually, numerous slope failures apparent).	
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.			Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available			4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness										
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.			Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1	

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. Be sure that you are looking at the entire reach, not just one riffle. To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded.

Insect/invertebrate Habitat										
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).		3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.			1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.			
10	9	8	7	6	5	4	3	2	1	

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover										
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery										
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.			20 to 50% shaded.		<20% of water surface in reach shaded.			
10	9	8	7	6	5	4	3	2	1	

Abandoned Mine Drainage (if applicable)											
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.			Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.				
		5			4		3		2		1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**



# Big Sewickley Creek Watershed Visual Assessment

Evaluators' Names KS/SA Date: 4-24-08  
 Sub-Watershed \_\_\_\_\_ Stream Section Name \_\_\_\_\_  
 Stream Name Ripping Run Reference Section \_\_\_\_\_  
 Weather Conditions Today 75° Sunny Past 2-5 Days Same  
 Active Channel Width: 25 feet

LAND USE WITHIN DRAINAGE (%):				
Grazing Pasture		Grassy Field	10	Row Crops
Forest	60	Residential	30	Industrial
Commercial		Abandoned Mine Lands		Other

SUBSTRATE (%):				
Boulder	10	Cobble	60	Gravel
			5	Silt
				20
				Mud
				5

DESCRIBE THE LAND USE OF THE AREA THAT THE STREAM FLOWS THROUGH:  
STREAM FLOWS ADJACENT TO WEXFORD-BAYNE ROAD. MOSTLY FLOWS THROUGH LIGHTLY WOODED/BRUSHY AREAS, THEN THROUGH SOME HOMEOWNER'S PROPERTIES, THEN HEADS AWAY FROM ROAD TO SECLUDED SECHLERS LAKE/WOODS

GPS POINTS / PHOTOS:				
Waypoint	Photo	Description	pH	Cond.
RP1		Start		
RP2	1	Bank outcrop - SW outlet		
RP3	2	Pipe / waterfall outlet	8.27	500
	3	"		
	4	"		
RP4	5	Trb on left going upstream / Debris Jam	7.93	360
RP5	6	Trb on right side	8.11	480
RP6	7	Jam		
	8	Culvert w driveway by Jam (2477)		
	9	other side of culvert		
	10	lake		
	11	lake		
	12	Culvert out of lake		
	13	Down stream from lake		
RP7		End [From Bayne to the end of channel 3' wide, homeowners, grass, etc] Airchannel		
ForK		All woods / nursery / logging at start (Franklin nursery)		
RP8		Trb on right		
RP9		Sechlers Lake		
RP10		End		

Invasive plants present:  Yes /  No  Japanese Knotweed  Garlic mustard  Purple loosestrife  Other  
 Trash / Litter: Yes /  No SKUNK CABBAGE  
 Floodplain wetlands:  Yes /  No If so, approximate size: Length \_\_\_\_ / Width \_\_\_\_ feet ONLY A FEW  
 Flooded areas: Yes  No (Wetland or other) \_\_\_\_\_

Notes:

Parameter	Score	Explanation of Score Given
Channel condition	7	
Riparian zone	8	
Bank stability	9	
Water appearance	9	
Nutrient enrichment	9	
Fish barriers	8	
In-stream fish cover	8	
Embeddedness	8	
Invertebrate habitat	8	
Canopy Cover	8	
AMD (if applicable)	NA	
Sewage (if applicable)	NA	
Manure presence (if applicable)	NA	
<b>TOTAL SCORE</b> (Add all scores and divide by number of scores given)	82/10  <u>8.2</u>	< 6.0 = POOR 6.1 - 7.4 = FAIR <del>7.5 - 8.9 = GOOD</del> > 9.0 = EXCELLENT

**Scoring Descriptions**

Each assessment element is rated with a value of 1 to 10. Rate only those elements appropriate to the stream reach. Record the score that best fits the observations you make based on the narrative description provided.

Channel Condition									
Natural channel; no structures, dikes. No evidence of down-cutting or excessive lateral cutting.		Evidence of past channel alteration, but with significant recovery of channel and banks. Any dikes or levees are set back to provide access to an adequate flood plain.			Altered channel; <50% of the reach with riprap and/or channelization. Excess <i>aggradation</i> ; braided channel. Dikes or levees restrict flood plain width.			Channel is actively downcutting or widening. >50% of the reach with riprap or channelization. Dikes or levees prevent access to the flood plain.	
10	9	8	7	6	5	4	3	2	1

**aggradation:** The process by which a stream's gradient steepens due to increased deposition of sediment.

**Keys:** look for things like down cutting, lateral cutting, altered or widened sections, dykes, levees or other obstructions.

Riparian Zone										
Natural Vegetation extends at least two active channel widths on each side.		Natural vegetation extends one active channel width on each side. Or If less than one width, covers entire flood plain.			Natural vegetation extends half of the active channel width on each side.			Natural vegetation extends a third of the active channel width on each side. Or Filtering function moderately compromised.		Natural vegetation less than a third of the active channel width on each side. Or Lack of regeneration. Or Filtering function severely compromised.
10	9	8	7	6	5	4	3	2	1	

**Keys:** Related to ACTIVE channel width, an example would be a 5' wide stream. 10' = 2x active channel width.

Bank Stability									
Banks are stable; at elevation of active flood plain; 33% or more of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately stable; at elevation of active flood plain; less than 33% of eroding surface area of banks in outside bends is protected by roots that extend to the base-flow elevation.			Moderately unstable; banks may be low, but typically are high (flooding occurs 1 year out of 5, or less frequently); outside bends are actively eroding (overhanging vegetation at top of bank, some mature trees falling into stream annually, some slope failures apparent).			Unstable; banks may be low, but typically are high; some straight reaches and inside edges of bends are actively eroding as well as outside bends (overhanging vegetation at top of bank, numerous mature trees falling into stream annually, numerous slope failures apparent).
10	9	8	7	6	5	4	3	2	1

**Keys:** All outside bends in streams erode; even the most stable streams may have 50% of its banks bare and eroding. A stable bank would be characterized by healthy vegetative cover, and/or a gentle slope. Unstable banks, on the other hand, would have little or no vegetative cover or a steep or vertical slope.

Water Appearance									
Very clear, or clear but tea-colored; objects visible at depth 3 to 6 ft (less if slightly colored); no oil sheen on surface; no noticeable film on submerged objects or rocks.		Occasionally cloudy; objects visible at depth 1.5 to 3 ft; may have slightly green color; no oil sheen on water surface.			Considerable cloudiness most of time; objects visible to depth 0.5 to 1.5 ft; slow sections may appear pea-green; bottom rocks or submerged objects covered with heavy green or olive-green film.  Or Moderate odor of ammonia or rotten eggs.			Very turbid or muddy appearance most of the time; objects visible to depth <0.5 ft; slow moving water may be bright-green; other obvious water pollutants; floating algal mats, surface scum, sheen or heavy coat of foam on surface.  Or Strong odor of chemicals, oil, sewage, other pollutants.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Remember to look at the water, not the substrate. Dip a clear glass jar in water and observe the clarity.

Nutrient Enrichment									
Clear water along entire reach; diverse aquatic plant community little algal growth present.		Fairly clear or slightly greenish water along entire reach; moderate algal growth on stream substrates.			Greenish water along entire reach; abundant algal growth, especially during warmer months.			Pea green, gray or brown water along entire reach; severe algal blooms create thick algal mats in stream.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Looking for algae and other aquatic vegetation, some is good, but it should not be excessive.

Fish Barriers									
No barriers.		Seasonal water withdrawals inhibit movement within the reach.		Drop structures, culverts, dams or diversions (<1ft drop) within the reach.		Drop structures, culverts, dams or diversions (>1ft drop) within 1 mile of reach.		Drop structures, culverts, dams or diversions (>1ft drop) within the reach.	
10	9	8	7	6	5	4	3	2	1

**Keys:** You are looking for withdrawals, culverts, dams and diversions. Anything that is imposed or constructed by man that would impede fish passage.

Instream Fish Cover									
>7 cover types available		6 to 7 cover types available		4 to 5 cover types available		2 to 3 cover types available		None to 1 cover type available	
10	9	8	7	6	5	4	3	2	1

**Cover types:** Logs/large woody debris, deep pools, overhanging vegetation, boulders/cobble, riffles, undercut banks, thick root mats, dense macrophyte beds, isolated/backwater pools, other: \_\_\_\_\_

Embeddedness									
Gravel or cobble particles are <20% embedded.		Gravel or cobble particles are 20 to 30% embedded.		Gravel or cobble particles are 30 to 40% embedded.		Gravel or cobble particles are >40% embedded.		Completely embedded.	
10	9	8	7	6	5	4	3	2	1

**Keys:** Embeddedness is defined as the degree to which objects in the stream bottom are surrounded by fine sediment. Only evaluate this item in riffles & runs. Measure the depth to which objects are buried by sediment. **Be sure that you are looking at the entire reach, not just one riffle.** To help better define embeddedness, picture a rock. If the average sediment in the stream covers the bottom 20% of the rock than you would check 20%. If the rock is covered 1/3<sup>rd</sup> of the way by sediment then it is 30% embedded:

Insect/invertebrate Habitat									
At least 5 types of habitat available. Habitat is at a stage to allow full insect colonization (woody debris and logs not freshly fallen).		3 to 4 types of habitat. Some potential habitat exists, such as overhanging trees, which will provide habitat, but have not yet entered the stream.		1 to 2 types of habitat. The substrate is often disturbed, covered, or removed by high stream velocities and scour or by sediment deposition.		None to 1 type of habitat.			
10	9	8	7	6	5	4	3	2	1

**Cover types:** Fine woody debris, submerged logs, leaf packs, undercut banks, cobble, boulders, coarse gravel, other: \_\_\_\_\_

Canopy Cover									
Key: This pertains to waterways where channel is 50 feet wide or less. Coldwater fishery									
>75% of water surface shaded and upstream 2 to 3 miles generally well shaded.		> 50% shaded in reach. Or >75% in reach, but upstream 2 to 3 miles poorly shaded.		20 to 50% shaded.		<20% of water surface in reach shaded.			
10	9	8	7	6	5	4	3	2	1

Abandoned Mine Drainage (if applicable)										
(Intentionally blank)		Evidence of iron staining. Or Noticeable iron precipitate.		Iron precipitate visible, muddy orange appearance.		Heavy iron precipitate, noticeable kill zone. Or White/bluish-white precipitate visible, rotten egg smell.				
		5		4		3		2		1

If AMD is found, complete AMD site diagram and mark discharge point on map, and/or with GPS unit.

Sewage (if applicable)			
(Intentionally blank)	Noticeable odor, excess plant growth and siltation.	Noticeable odor, excess plant growth. And Questionable pipe and black stream substrate.	Visible pipe with effluent, heavy odor.
	5                      4	3                      2	1

Mark discharge(s) on map and/or with GPS unit.

Manure Presence (if applicable)			
(Intentionally blank)	Evidence of livestock access to riparian zone.	Occasional manure in stream or waste storage structure located on the flood plain.	Extensive amount of manure on banks or in stream.  Or Untreated human waste discharge pipes present.
	5                      4	3                      2	1

**NOTES**

ATTACHMENT F:  
GIS MAP REFERENCES SUMMARY



Attachment F  
GIS Reference Summary

Map	Shapefiles/Layers	Source	Description
Stream Score Assessment	PAMAP Tile Index - South 2006	PAMAP Program, Bureau of Topographic and Geologic Survey, PA Department of Conservation and Natural Resources	PAMAP 10,000 feet x 10,000 feet tile index covering counties in the southern State Plane zone of Pennsylvania. This version has been updated to include additional tiles within a 5000 feet buffer of the Pennsylvania border....
Areas Of Encroachment & Bank Erosion	Encroachment Locations	Pennsylvania Department of Environmental Protection	An Encroachment Location is a DEP primary facility type related to the Water Resources Management Water Obstructions Program. There are many sub-facility types relating to Encroachment Locations, ranging from Boat Launch Ramps to Dredging to Wetland Impact. These sub-facilities may pertain...
Stormwater Management & Land Use	Erosion & Sediment Control Facilities	Pennsylvania Department of Environmental Protection	An Erosion and Sediment Control Facility is a DEP primary facility type related to the Water Pollution Control program...
	PAMAP Program Land Cover for Pennsylvania, 2005	The Pennsylvania State University	State wide land cover will provide a reference for current land use status in the state;The coding is based on the Anderson Land Use/Land Cover system...
Oil And Gas Wells	Encroachment Locations for Oil & Gas	Pennsylvania Department of Environmental Protection	An Encroachment Location for Oil & Gas is a DEP primary facility type related to the Oil and Gas Program. The sub-facilities that fall under Oil and Gas Encroachment also exist under Encroachment Locations.....
Natural Areas	National Wetlands Inventory - Pennsylvania	U.S. Fish and Wildlife Service	This data set represents the extent, approximate location and type of wetlands and deepwater habitats in the conterminous United States..
	State Game Lands	PA Game Commission	PA State Game Land Boundaries
	Floodplains of Pennsylvania	Office of Remote Sensing for Earth Resources, Penn State University	Floodplain boundaries state wide
	NHI (Natural Heritage Inventory)	Western Pennsylvania Conservancy	Natural Heritage Inventories, prepared by the Western Pennsylvania Conservancy
	Trout Stocked Streams	PA Fish and Boat Commission	This layer contains flowing waters from the Pennsylvania Fish and Boat Commission Fisheries Resource Database that were stocked with trout in 2008
General (multiple maps)	Watershed Boundaries (ERRI - Small Watersheds)	Environmental Resources Research Institute	Boundaries of 9,895 watersheds in Pennsylvania indicated in the Pennsylvania gazeteer of streams.
	State Roads	Pennsylvania Department of Transportation, Bureau of Planning and Research, Geographic Information Division	State-owned and maintained public roads within Pennsylvania as extracted from the PENNDOT Roadway Management System (RMS). Includes fields describing pavement type, traffic volumes and other information as detailed below....
	Municipalities	Pennsylvania Department of Transportation	Boundaries of municipalities within Pennsylvania as delineated for the PennDOT Type 10 general highway maps.
	Counties	Pennsylvania Department of Transportation	Boundaries of counties within Pennsylvania
	Streams	Environmental Resources Research Institute	The connected network of streams and waterways of Pennsylvania are indicated as single lines in this coverage.

Other shapefiles or layers were based on waypoints taken during field surveys conducted in watershed.

ATTACHMENT G:  
MEDIA: NEWS REPORTS & WATERSHED ARTICLES



Bob Donaldson/Post-Gazette

Blue Heron returned to their nests for another season in the trees above Big Sewickley Creek in Bell Acres in April 2004. Collecting old bird nests without the proper permit is illegal.

## Craig Barras

---

**From:** suzybeezy@comcast.net  
**Sent:** Monday, June 04, 2007 12:13 PM  
**To:** Craig Barras  
**Subject:** Sewickley Herald Article

Forwarding this article for inclusion with our study.

Susan Barness

--

### Property still in danger of falling into creek

**Adam Brandolph**  
**Staff Writer**

*Thursday, May 31, 2007*

A broken wire fence and cracked concrete slabs are all that separates Elizabeth Zedak's home in Bell Acres from a 30-foot cliff into the Big Sewickley Creek.

Zedak, who lives in the home with her daughter Jenni and Anthony Caracci, believes the creek is causing the hillside to slowly erode, sliding their home closer to the cliff.

"The creek is causing the house to move," Zedak said. "The creek is the reason my house is falling."



A Network  
of People  
Committed  
to You.

Last Friday, Zedak invited members of the Pennsylvania Department of Environmental Protection to investigate the property.

She hopes they'll be able to offer assistance in finding a solution.

DEP officials have visited her home on many occasions over the last several years.

"They've been out here before and every single time they're here, they don't say anything except that it's my issue," she said.

State officials offered her information on stabilizing the hillside before, but Zedak says she doesn't have money to pay for permits let alone construction costs.

"I don't have money to be fixing this problem," she said.



The graphic is a vertical rectangle divided into two horizontal sections. The top section has an orange background and contains the text "UPMC HEALTH PLAN" in a large, white, serif font, with "Where you belong." in a smaller, white, sans-serif font below it. A dark blue button with the text "LEARN MORE" in white is centered below the text. The bottom section has a dark grey background and contains the text "You're Committed to Better Health" in a white, sans-serif font, followed by "Now All You Need Is a Plan" in a larger, white, sans-serif font.

UPMC HEALTH PLAN  
Where you belong.

LEARN MORE

You're  
Committed  
to Better Health

Now All You  
Need Is a Plan

"It would cost almost \$4,000 just for permits. I don't have that kind of money just sitting around."

In a letter dated February 2004, Joseph Capasso of the DEP told the Zedak's that the "team again confirmed that the problem appears to be erosion of the upper embankment rather than the top or the area immediately adjacent to the stream."

Zedak doesn't believe that conclusion.

"They (the DEP) keep telling me it's my problem," she said. "It's not rain run-off that's causing this problem."

The creek does have its upsides, though.

"The creek offers so much nature here," she said.

"It's like Raccoon [Creek State] Park. With the deer and the fish all around the creek, it's so nice to be near."

But it's the fish in the creek that are partly to blame for her troubles.

Even though government officials have told her before to dump soil along the hillside, Zedak risks being fined by state fish and game officials.

"We've been told to dump dirt down the hill by some officials," she said. "If we do that, we'll get fined."

Her situation worsened after the remnants of Hurricane Ivan swept through the area.

"After Ivan," she said, "waters were very high. It looked like a river running through here."

Ivan relocated the creek nearly 30 feet closer to her home, she said, placing it directly at the bottom of the hill.

"When Ivan moved the creek, our problem got worse," Zedak said.

"Ivan did so much damage in a little amount of time."

State Rep. Sean Ramaley, who also visited the Zedak property last Friday, said he would like to do whatever he can to help.

"Finding a way to stabilize Mrs. Zedak's home is important," he said.

"She's obviously very worried about her property."


Though Zedak knows her life may be in danger should another leftover hurricane or heavy rainfall come through the valley, she doesn't want to move.

"This is my house," she said.

"It may not be much but it's my house. I love it."

## FIGURES





**LEGEND**

- Stream
- Watershed Boundary
- Stream Assessment Score**
- EXCELLENT
- GOOD
- FAIR
- POOR

3,000 1,500 0 3,000  
Feet

Butler

Beaver

Allegheny

North Fork  
Big Sewickley Creek  
Cooney Hollow  
East Branch  
Rippling Run



**BIG SEWICKLEY CREEK WATERSHED**

Allegheny, Beaver, and Butler Counties, Pennsylvania

**STREAM ASSESSMENT SCORING**

BALANCED ENVIRONMENTAL SOLUTIONS

Pittsburgh, PA, Telephone: 724/733-2060; State College, PA, Telephone: 814/238-2060

2010


Map 1 of 7



**LEGEND**

- State Road
- Stream
- County Boundary
- Watershed Boundary
- Stream Encroachment
- Bank Erosion
- ATV Impacts
- Debris Jam

4,000 2,000 0 4,000 Feet



**PaDEP Permitted Encroachments (PASDA)**

- Bridge
- Culvert
- Interceptor Pipe
- Stream Relocation
- Wetland Impact


**Stream Scoring**

- Excellent
- Good
- Fair
- Poor

Municipalities are indicated by the different colored polygons clipped to the Big Sewickley Creek Watershed.


**Municipalities**

- AMBRIDGE
- BELL ACRES
- BRADFORDWOODS
- CRANBERRY
- ECONOMY
- FRANKLIN PARK
- HARMONY
- LEET
- LEETSDALE
- MARSHALL
- NEW SEWICKLEY
- SEWICKLEY HILLS



Key for Waypoint Abbreviations	
BSC	Big Sewickley Creek
BSCT	Tributaries to Big Sewickley Creek
CH	Cooney Hollow
EF	East Branch Big Sewickley Creek
EFT	Tributaries to East Branch Big Sewickley Creek
NF	North Fork Big Sewickley Creek
NFT	Tributaries to North Fork Big Sewickley Creek
RR	Rippling Run

Number following BSC, CH, EF, NF, RR refers to the waypoint. The numbers increase from the mouth of the segment heading upstream. For Tributaries: First No. (1, 2, 3, etc.) refers to the tributary Direction of Tributary (E or W) refers to East or West side of branch Second No. (1, 2, 3, etc.) is waypoint identification



**BIG SEWICKLEY CREEK WATERSHED**

Allegheny, Beaver, and Butler Counties, Pennsylvania

**AREAS OF ENCROACHMENTS AND BANK EROSION**

BALANCED ENVIRONMENTAL SOLUTIONS

Pittsburgh, PA, Telephone: 724/733-2060; State College, PA, Telephone: 814/238-2060

2010

Map 2 of 7



**LEGEND**

- State Road
- Stream
- Watershed Boundary
- Stormwater Erosion Sites
- PaDEP Erosion and Sediment Control Facilities
- Stormwater Management Facilities/Issues

**LANDUSE**


- |  |                      |  |
|--|----------------------|--|
|  | Roads                | Residential, Commercial, or Industrial Land Use<br>% Impervious Area = |
|  | Pasture or Grass     |  |
|  | Forests              |  |
|  | Water                | 5 - 30%  |
|  | Wetlands             | 30 - 74%   |
|  | Bare or Un-vegetated | > 74%  |

4,000 2,000 0 4,000 Feet



Key for Waypoint Abbreviations	
BSC	Big Sewickley Creek
BSCT	Tributaries to Big Sewickley Creek
CH	Cooney Hollow
EF	East Branch Big Sewickley Creek
EFT	Tributaries to East Branch Big Sewickley Creek
NF	North Fork Big Sewickley Creek
NFT	Tributaries to North Fork Big Sewickley Creek
RR	Rippling Run






Number following BSC, CH, EF, NF, RR refers to the waypoint. The numbers increase from the mouth of the segment heading upstream. For Tributaries: First No. (1, 2, 3, etc.) refers to the tributary Direction of Tributary (E or W) refers to East or West side of branch Second No. (1, 2, 3, etc.) is waypoint identification





	<b>BIG SEWICKLEY CREEK WATERSHED</b> Allegheny, Beaver, and Butler Counties, Pennsylvania <b>STORMWATER MANAGEMENT AND LAND COVER</b>	2010
	BALANCED ENVIRONMENTAL SOLUTIONS <small>Pittsburgh, PA, Telephone: 724/733-2060; State College, PA, Telephone: 814/238-2060</small>	Map 3 of 7






**LEGEND**



-  State Road
-  Stream
-  County Boundary
-  Watershed Boundary
-  Sewage Impacts



**Bacteria Sampling (CFU/100mL)**

-  36-1,000
-  1,001-5,000
-  5,001-56,000

**Habitat Sampling Sites**

-  Macroinvertebrate
-  Fish Shocking Site



**Stream Scoring**

-  Excellent
-  Good
-  Fair
-  Poor

Municipalities are indicated by the different colored polygons clipped to the Big Sewickley Creek Watershed.

**Municipalities**





-  AMBRIDGE
-  BELLACRES
-  BRADFORDWOODS
-  CRANBERRY
-  ECONOMY
-  FRANKLIN PARK
-  HARMONY
-  LEET
-  LEETSDALE
-  MARSHALL
-  NEW SEWICKLEY
-  SEWICKLEY HILLS



**BIG SEWICKLEY CREEK WATERSHED**  
 Allegheny, Beaver, and Butler Counties, Pennsylvania  
**BIOLOGICAL SURVEYS AND SAMPLING**  
 BALANCED ENVIRONMENTAL SOLUTIONS  
 Pittsburgh, PA, Telephone: 724/733-2060; State College, PA, Telephone: 814/238-2060

2010  
 Map 4 of 7




**LEGEND**

-  State Road
-  Stream
-  County Boundary
-  Watershed Boundary

**Stream Scoring**

-  Excellent
-  Good
-  Fair
-  Poor

**PaDEP Oil and Gas Locations**




-  Abandoned
-  Plugged (Inactive)
-  Active

Municipalities are indicated by the different colored polygons clipped to the Big Sewickley Creek Watershed.

**Municipalities**

-  AMBRIDGE
-  BELL ACRES
-  BRADFORDWOODS
-  CRANBERRY
-  ECONOMY
-  FRANKLIN PARK
-  HARMONY
-  LEET
-  LEETSDALE
-  MARSHALL
-  NEW SEWICKLEY
-  SEWICKLEY HILLS

4,000 2,000 0 4,000 Feet



**BIG SEWICKLEY CREEK WATERSHED**  
 Allegheny, Beaver, and Butler Counties, Pennsylvania

**OIL AND GAS WELLS**




BALANCED ENVIRONMENTAL SOLUTIONS

Pittsburgh, PA, Telephone: 724/733-2060; State College, PA, Telephone: 814/238-2060


2010

Map 5 of 7

**LEGEND**

-  Road
-  Stream
-  County Boundary
-  Watershed Boundary
-  National Wetlands Inventory
-  State Gamelands 203
-  Natural Heritage Inventory
-  Trout Streams
-  Floodplains (1996)



4,000 2,000 0 4,000 Feet



Municipalities are indicated by the different colored polygons clipped to the Big Sewickley Creek Watershed.

**Municipalities**

-  AMBRIDGE
-  BELL ACRES
-  BRADFORD WOODS
-  CRANBERRY
-  ECONOMY
-  FRANKLIN PARK
-  HARMONY
-  LEET
-  LEETSDALE
-  MARSHALL
-  NEW SEWICKLEY
-  SEWICKLEY HILLS



**BIG SEWICKLEY CREEK WATERSHED**  
 Allegheny, Beaver, and Butler Counties, Pennsylvania

**NATURAL AREAS**





BALANCED ENVIRONMENTAL SOLUTIONS  
 Pittsburgh, PA, Telephone: 724/733-2060; State College, PA, Telephone: 814/238-2060



2010

Map 6 of 7






**LEGEND**

-  State Road
-  Stream
-  County Boundary
-  Watershed Boundary




**Management Recommendations/  
Potential Project Sites**

-  Conservation Area
-  Stormwater Management
-  Stream Improvement Project

**Municipalities**


-  AMBRIDGE
-  BELL ACRES
-  BRADFORDWOODS
-  CRANBERRY
-  ECONOMY
-  FRANKLIN PARK
-  HARMONY
-  LEET
-  LEETSDALE
-  MARSHALL
-  NEW SEWICKLEY
-  SEWICKLEY HILLS

Municipalities are indicated by the different colored polygons clipped to the Big Sewickley Creek Watershed.



Key for Waypoint Abbreviations	
BSC	Big Sewickley Creek
BSCT	Tributaries to Big Sewickley Creek
CH	Cooney Hollow
EF	East Branch Big Sewickley Creek
EFT	Tributaries to East Branch Big Sewickley Creek
NF	North Fork Big Sewickley Creek
NFT	Tributaries to North Fork Big Sewickley Creek
RR	Rippling Run

Number following BSC, CH, EF, NF, RR refers to the waypoint.  
The numbers increase from the mouth of the segment heading upstream.  
For Tributaries:  
First No. (1, 2, 3, etc.) refers to the tributary  
Direction of Tributary (E or W) refers to East or West side of branch  
Second No. (1, 2, 3, etc.) is waypoint identification



**BIG SEWICKLEY CREEK WATERSHED**  
Allegheny, Beaver, and Butler Counties, Pennsylvania  
**WATERSHED MANAGEMENT  
RECOMMENDATIONS**  
BALANCED ENVIRONMENTAL SOLUTIONS  
Pittsburgh, PA, Telephone: 724/733-2060; State College, PA, Telephone: 814/238-2060

2010  
Map 7 of 7